

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	84								
Andover Count	1								
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Ashford Count	2								
	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Boltob Count	1								
	Boltob	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Bolton Count	1								
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain
Coventry Count	6								
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Petrographic Analysis	Denied	1	1	25	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
East Hartford Count		1							
	East Hartford	Visual Inspection	On Hold	0	0	0			Finished Basement
Ellington Count		10							
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	On Hold	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Approved - Pending Payment	0	0	0			Gutters
	Ellington	Petrographic Analysis	Approved - Pending Payment	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
Hartford Count	1								

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Hartford	Visual Inspection	Denied	0	0	0			
Manchester Count	5								
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	manchester	Petrographic Analysis	Approved - Pending Payment	0	1	29			Gutters;Gutters - With Extension
Mansfield Count	3								
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
Mansfield Center Count	1								

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
Portland Count	1								
	Portland	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
Somers Count	1								
	Somers	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
South Windsor Count	9								
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
Stafford Count	4								
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	On Hold	0	0	0			
stafford springs Count	2								
	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
	Stafford Springs	Petrographic Analysis	Approved - Pending Payment	1	1	23	Don't know	Floor and walls both	Gutters - With Extension

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Storrs Mansfield Count	1								
	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
Suffield Count	2								
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
Thompson Count	1								
	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Count	15								
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	On Hold	0	0	0			Gutters
	Tolland	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	On Hold	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Approved - Pending Payment	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	On Hold	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			
Union Count	1								
	Union	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters
Vernon Count	12								
	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Footing Drains

January Only All

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Willington Count		3							
	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	979								
Count	0		Denied	0	0	0	No visible signs	Wall only	
Count	0		Denied	0	0	0	No visible signs	Wall only	
Count	0		Denied	0	0	0	No visible signs	Wall only	
Amston Count	1								
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
Andover Count	8								
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ashford Count	25								
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Boltob Count	1								
	Boltob	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Bolton Count	18								
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Broadbrook Count	1								
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Columbia Count	5								
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Coventry Count	66								
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	On Hold	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Denied	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Denied	1	1	25	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	On Hold	1	1	70	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
East Hartford Count									
	4								
	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	On Hold	0	0	0			Finished Basement
	East Hartford	Visual Inspection	Denied	0	0	0			
	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
East Lyme Count									
	1								
	East Lyme	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
East Windsor Count									
	11								

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Petrographic Analysis	Denied	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Eastford Count	1								

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ellington Count	78								
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	On Hold	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	On Hold	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ellington	Petrographic Analysis	On Hold	0	1	11.5			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Approved - Pending Payment	0	0	0			Gutters
	Ellington	Petrographic Analysis	Approved - Pending Payment	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
Enfield Count	10								
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Glastonbury Count	3								
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Hartford Count	1								
	Hartford	Visual Inspection	Denied	0	0	0			
Hebron Count	6								
	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Killingly Count	1								
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Lebanon Count	1								
	Lebanon	Visual Inspection	Paid	0	0	0			
Manchester Count	90								
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	0	1	2			
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	manchester	Petrographic Analysis	Approved - Pending Payment	0	1	29			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Mansfield Count	28								
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
Mansfield Center Count	2								
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
Marlborough Count	1								
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
Plainfield Count	1								
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Portland Count	2								
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
	Portland	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
Rocky Hill Count	1								
	Rocky Hill	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Somers Count	19								
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
South Windsor Count	120								
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Denied	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Stafford Count	66								
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	On Hold	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
Stafford Springs Count	6								
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
	Stafford Springs	Petrographic Analysis	Approved - Pending Payment	1	1	23	Don't know	Floor and walls both	Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
Storrs Count	1								
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Storrs Mansfield Count	2								
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
Suffield Count	13								
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Thompson Count	1								
	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Count	227								

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Denied	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	On Hold	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Petrographic Analysis	On Hold	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Denied	1	1	74	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	On Hold	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Approved - Pending Payment	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	On Hold	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Union Count	10								
	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Union	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Union	Petrographic Analysis	Paid	0	0	0			
Vernon Count	90								
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Denied	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Wethersfield Count	3								
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
Willington Count	53								
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Denied	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Denied	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior
	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
Woodstock Count	1								
	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	880								
Bolton Count	1								
	Boltob	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Ellington Count	2								
	Ellington	Petrographic Analysis	Approved - Pending Payment	0	0	0			Gutters
	Ellington	Petrographic Analysis	Approved - Pending Payment	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
manchester Count	1								
	manchester	Petrographic Analysis	Approved - Pending Payment	0	1	29			Gutters;Gutters - With Extension
Somers Count	1								
	Somers	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
South Windsor Count	1								
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
Stafford Springs Count	1								

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Petrographic Analysis	Approved - Pending Payment	1	1	23	Don't know	Floor and walls both	Gutters - With Extension
Suffield Count	1								
	Suffield	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
Tolland Count	3								
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Approved - Pending Payment	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			
Union Count	1								
	Union	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters
Vernon Count	1								
	Vernon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Footing Drains
Amston Count	1								
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Andover Count	8								
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ashford Count	24								
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Bolton Count	16								
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Broadbrook Count	1								
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Columbia Count	5								
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Coventry Count	60								
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
East Hartford Count	2								
	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
East Windsor Count	10								
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Eastford Count	1								
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ellington Count	70								

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
Enfield Count	10								
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Glastonbury Count	1								

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
Hebron Count	6								
	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Killingly Count	1								
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Lebanon Count	1								

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Lebanon	Visual Inspection	Paid	0	0	0			
Manchester Count	87								
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	1	2			
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Mansfield Count	26								
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
Mansfield Center Count	2								

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
Marlborough Count	1								
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
Plainfield Count	1								
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
Portland Count	1								
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
Somers Count	18								
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
South Windsor Count	91								
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Stafford Count	63								
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
Stafford Springs Count	5								
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
Storrs Count	1								
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Storrs Mansfield Count	2								
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
Suffield Count	10								
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Thompson Count	1								
	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Count	205								
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	0	0			
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Union Count	8								
	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Union	Petrographic Analysis	Paid	0	0	0			
Vernon Count	76								
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Wethersfield Count	1								
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willington Count	50								
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior
	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Approved and Paid Only

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
Woodstock Count	1								
	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain