

October 2018-All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------------|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|--|----------------------|---|
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| Manchester Count | 4 | | | | | | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 1.58 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| Mansfield Count | 1 | | | | | | | | |
| | Mansfield | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| Somers Count | 1 | | | | | | | | |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| South Windsor Count | 2 | | | | | | | | |
| | South Windsor | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| Stafford Count | 2 | | | | | | | | |
| | Stafford | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.74 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains |
| Tolland Count | 11 | | | | | | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 39 | | | Waterproofing - Exterior;Gutters |

October 2018-All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Willington | Petrographic Analysis | On Hold | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| Grand Count | 685 | | | | | | | | |
| Andover Count | 6 | | | | | | | | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Ashford Count | 18 | | | | | | | | |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ashford | Petrographic Analysis | Paid | 0 | 1 | 25 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Ashford | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| Bolton Count | 11 | | | | | | | | |
| | Bolton | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| Columbia Count | 5 | | | | | | | | |
| | Columbia | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Capillary Break |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Columbia | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| Coventry Count | 44 | | | | | | | | |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Coventry | Petrographic Analysis | Paid | 1 | 1 | 15 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Ellington | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 10 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 6 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 1.15 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 29 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Killingly Count | 1 | | | | | | | | |
| | Killingly | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| Lebanon Count | 1 | | | | | | | | |
| | Lebanon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| Manchester Count | 69 | | | | | | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Concrete floor only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Petrographic Analysis | Paid | 0 | 1 | 0.12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Concrete floor only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 1.58 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters - With Extension |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| Mansfield Count | 21 | | | | | | | | |
| | Mansfield | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Finished Basement |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------------|-------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 4.4 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 14 | | | Gutters;Footing Drains |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Mansfield | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | |
| Marlborough Count | 1 | | | | | | | | |
| | Marlborough | Petrographic Analysis | Paid | 1 | 1 | 26 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains |
| Portland Count | 1 | | | | | | | | |
| | Portland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| Somers Count | 16 | | | | | | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Somers | Petrographic Analysis | Paid | 0 | 1 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | |
| | Somers | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------------|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| South Windsor Count | 67 | | | | | | | | |
| | South Windsor | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 40 | Moderate to severe (significant repairs required) | Wall only | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 38 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | south windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 45 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 0.93 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 25 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 18 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| Stafford Count | 56 | | | | | | | | |
| | Stafford | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.74 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 13 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 20 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0.91 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.69 | | | Gutters;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.58 | | | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------------|------------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| Storrs Mansfield Count | 1 | | | | | | | | |
| | Storrs Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Footing Drains |
| Suffield Count | 8 | | | | | | | | |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| Tolland Count | 174 | | | | | | | | |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.15 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|--|----------------------|--|
| | Tolland | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 71 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 10 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain |
| | TOLLAND | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 1.28 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2.5 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 13 | No visible signs | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 7 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 15 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 7 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 30 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 25 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|--|----------------------|--|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 8 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 39 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 1.02 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 74 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 26 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | No visible signs | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters - With Extension;Footing Drains |
| Union Count | 7 | | | | | | | | |
| | Union | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Union | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters |
| Vernon Count | 54 | | | | | | | | |
| | Vernon | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | Minor degradation | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |
| | Vernon | Petrographic Analysis | Paid | 1 | 1 | 4.65 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1 | | | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1.78 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 21 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |

All Approved and Paid Only

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Finished Basement |
| Woodstock Count | 1 | | | | | | | | |
| | Woodstock | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| Grand Count | 737 | | | | | | | | |
| Andover Count | 6 | | | | | | | | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Ashford Count | 19 | | | | | | | | |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Bolton | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| | Bolton | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| Columbia Count | 5 | | | | | | | | |
| | Columbia | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Capillary Break |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Columbia | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| Coventry Count | 48 | | | | | | | | |
| | Coventry | Petrographic Analysis | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Coventry | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Coventry | Petrographic Analysis | Paid | 1 | 1 | 15 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Petrographic Analysis | On Hold | 1 | 1 | 70 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------------|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Paid | 1 | 1 | 1.83 | Don't know | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| East Hartford Count | 1 | | | | | | | | |
| | East Hartford | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| East Lyme Count | 1 | | | | | | | | |
| | East Lyme | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| East Windsor Count | 9 | | | | | | | | |
| | East Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | East Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | East Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | East Windsor | Petrographic Analysis | Denied | 0 | 0 | 0 | | | |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|--------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | East Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| Eastford Count | 1 | | | | | | | | |
| | Eastford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| Ellington Count | 65 | | | | | | | | |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 10 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 6 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Ellington | Visual Inspection | On Hold | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 1.15 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Denied | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 29 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | On Hold | 0 | 1 | 11.5 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement |
| | Ellington | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | On Hold | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Petrographic Analysis | On Hold | 1 | 1 | 13 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior |
| Enfield Count | 9 | | | | | | | | |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension;Finished Basement;Footing Drains |
| | Enfield | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Curtain or French Drain |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------------|-------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Glastonbury Count | 2 | | | | | | | | |
| | Glastonbury | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Glastonbury | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| Hebron Count | 5 | | | | | | | | |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Killingly Count | 1 | | | | | | | | |
| | Killingly | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| Lebanon Count | 1 | | | | | | | | |
| | Lebanon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| Manchester Count | 69 | | | | | | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Concrete floor only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Petrographic Analysis | Paid | 0 | 1 | 0.12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Concrete floor only | Gutters |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 1.58 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| Mansfield Count | 23 | | | | | | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Finished Basement |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 4.4 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 14 | | | Gutters;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------------|-------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Mansfield | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | |
| | Mansfield | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| Marlborough Count | 1 | | | | | | | | |
| | Marlborough | Petrographic Analysis | Paid | 1 | 1 | 26 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains |
| Portland Count | 1 | | | | | | | | |
| | Portland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| Somers Count | 16 | | | | | | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Somers | Petrographic Analysis | Paid | 0 | 1 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | |
| | Somers | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------------|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Footing Drains |
| South Windsor Count | 70 | | | | | | | | |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 40 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | South Windsor | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 38 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | south windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 45 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 0.93 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 25 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 18 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Stafford Count | 58 | | | | | | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Denied | 1 | 0 | 0 | Don't know | Wall only | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 13 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 20 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Stafford | Visual Inspection | Denied | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Curtain or French Drain |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------------|------------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Stafford | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.74 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0.91 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.69 | | | Gutters;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.58 | | | Gutters |
| Storrs Mansfield Count | 1 | | | | | | | | |
| | Storrs Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Footing Drains |
| Suffield Count | 9 | | | | | | | | |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Suffield | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| Tolland Count | 188 | | | | | | | | |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 71 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 10 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain |
| | TOLLAND | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 1.28 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2.5 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 13 | No visible signs | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 7 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 15 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 7 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 30 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Petrographic Analysis | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 25 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 8 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 39 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 1.02 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Denied | 1 | 1 | 74 | Minor degradation | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 74 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 26 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.15 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | No visible signs | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| Union Count | 8 | | | | | | | | |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Union | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Footing Drains |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Union | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters |
| | Union | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | |
| Vernon Count | 59 | | | | | | | | |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Denied | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |
| | Vernon | Petrographic Analysis | Paid | 1 | 1 | 4.65 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1 | | | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1.78 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Denied | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Petrographic Analysis | Denied | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | Minor degradation | | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Curtain or French Drain |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|--|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Footing Drains |
| | Willington | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---|----------------------|---|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior |
| | Willington | Petrographic Analysis | On Hold | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Finished Basement |

All Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|--|----------------------|---|
| Woodstock Count | 1 | | | | | | | | |
| | Woodstock | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |