

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------------|--------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| Grand Count | 741 | | | | | | | | |
| Bolton Count | 1 | | | | | | | | |
| | Bolton | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| Coventry Count | 4 | | | | | | | | |
| | Coventry | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 2.8 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 2.3 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| East Windsor Count | 2 | | | | | | | | |
| | East Windsor | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.13 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | East Windsor | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| Glastonbury Count | 1 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------|-------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------|
| | Glastonbury | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| Manchester Count | 6 | | | | | | | | |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 1.9 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2 | | | |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 0 | Don't know | | Gutters;Finished Basement |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 0 | Don't know | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 5.78 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Mansfield Count | 1 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Mansfield | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| South Windsor Count | 2 | | | | | | | | |
| | South Windsor | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | South Windsor | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Finished Basement |
| Stafford Count | 1 | | | | | | | | |
| | Stafford | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 52.5 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension |
| Tolland Count | 7 | | | | | | | | |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 4.13 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters - With Extension;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 3.58 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.88 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 3.03 | Don't know | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| Vernon Count | 4 | | | | | | | | |
| | Vernon | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2.03 | | | Waterproofing - Exterior;Gutters |
| | Vernon | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------|------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| Willington Count | 1 | | | | | | | | |
| | Willington | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| Andover Count | 6 | | | | | | | | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Ashford Count | 18 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------|
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ashford | Petrographic Analysis | Paid | 0 | 1 | 25 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Ashford | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| Bolton Count | 12 | | | | | | | | |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------|
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | bolton | Petrographic Analysis | Paid | 0 | 0 | 0 | No visible signs | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| Columbia Count | 5 | | | | | | | | |
| | Columbia | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Capillary Break |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------|
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Columbia | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| Coventry Count | 45 | | | | | | | | |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Coventry | Petrographic Analysis | Paid | 1 | 1 | 15 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Paid | 1 | 1 | 1.83 | Don't know | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| East Hartford Count | 1 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------|
| | East Hartford | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| East Windsor Count | 8 | | | | | | | | |
| | East Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | East Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | East Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | East Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| Eastford Count | 1 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Eastford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| Ellington Count | 60 | | | | | | | | |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 10 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|-----------------|-----------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 6 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 1.15 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 29 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|-----------------|-------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 13 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior |
| Enfield Count | 10 | | | | | | | | |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension;Finished Basement;Footing Drains |
| | Enfield | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Curtain or French Drain |
| | Enfield | Petrographic Analysis | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Hebron Count | 5 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------|
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Killingly Count | 1 | | | | | | | | |
| | Killingly | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| Lebanon Count | 1 | | | | | | | | |
| | Lebanon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| Manchester Count | 75 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Concrete floor only | Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Petrographic Analysis | Paid | 0 | 1 | 0.12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Concrete floor only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|--------------------------------------------------|----------------------|-----------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------|
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|--------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 1.58 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Finished Basement |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Mansfield Count | 21 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------|
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Finished Basement |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 4.4 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 14 | | | Gutters;Footing Drains |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Mansfield | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------------|-------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------|
| Marlborough Count | 1 | | | | | | | | |
| | Marlborough | Petrographic Analysis | Paid | 1 | 1 | 26 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains |
| Plainfield Count | 1 | | | | | | | | |
| | Plainfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| Portland Count | 1 | | | | | | | | |
| | Portland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| Somers Count | 16 | | | | | | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------|
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Somers | Petrographic Analysis | Paid | 0 | 1 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | |
| | Somers | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Footing Drains |
| South Windsor Count | 67 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 40 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 38 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | south windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 45 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 0.93 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 25 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 18 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Stafford Count | 59 | | | | | | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 13 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 20 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 1.74 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0.91 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.69 | | | Gutters;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.58 | | | Gutters |
| Stafford Springs Count | 1 | | | | | | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|------------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Stafford Springs | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| Storrs Count | 1 | | | | | | | | |
| | Storrs | Petrographic Analysis | Paid | 1 | 1 | 3.03 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| Storrs Mansfield Count | 1 | | | | | | | | |
| | Storrs Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Footing Drains |
| Suffield Count | 8 | | | | | | | | |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------|
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| Tolland Count | 180 | | | | | | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 71 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|--------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 10 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain |
| | TOLLAND | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 1.28 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2.5 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 13 | No visible signs | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 7 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 15 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 7 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 30 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 25 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|--------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 8 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 39 | | | Waterproofing - Exterior;Gutters |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 1.02 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 74 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 26 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 1.15 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | No visible signs | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| Union Count | 7 | | | | | | | | |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------------|
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Union | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters |
| | Union | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| Vernon Count | 55 | | | | | | | | |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |
| | Vernon | Petrographic Analysis | Paid | 1 | 1 | 4.65 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1 | | | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1.78 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | Minor degradation | | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 21 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 2.1 | | | Gutters;Gutters - With Extension |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Vernon | Petrographic Analysis | Paid | 1 | 1 | 70 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters;Finished Basement;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------------|--------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1.18 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| Wethersfield Count | 1 | | | | | | | | |
| | Wethersfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Willington Count | 42 | | | | | | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement |

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior |
| | Willington | Petrographic Analysis | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Petrographic Analysis | Paid | 1 | 1 | 2 | | Wall only | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Finished Basement |
| Woodstock Count | 1 | | | | | | | | |
| | Woodstock | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| Grand Total | 0 | | | | | | | | |
| Total | 0 | | | | | | | | |
| | | | Denied | 0 | 0 | 0 | No visible signs | Wall only | |
| Andover Total | 0 | | | | | | | | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | |
| | Andover | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Andover | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Ashford Total | 0 | | | | | | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------|
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ashford | Petrographic Analysis | Paid | 0 | 1 | 25 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|-----------------|--------------------------------------------------------------------------------------------------------------------|
| | Ashford | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Ashford | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Footing Drains |
| | Ashford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Ashford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| Bolton Total | 0 | | | | | | | | |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Bolton | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Bolton | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Bolton | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------|
| | Bolton | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| | Bolton | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | bolton | Petrographic Analysis | Paid | 0 | 0 | 0 | No visible signs | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| Columbia Total | 0 | | | | | | | | |
| | Columbia | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Capillary Break |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Columbia | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Columbia | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| Coventry Total | 0 | | | | | | | | |
| | Coventry | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 2.8 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 2.3 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters - With Extension;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Coventry | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Coventry | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Coventry | Petrographic Analysis | Paid | 1 | 1 | 15 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Petrographic Analysis | On Hold | 1 | 1 | 70 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Paid | 1 | 1 | 1.83 | Don't know | | Gutters |
| | Coventry | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| East Hartford Total | 0 | | | | | | | | |
| | East Hartford | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| | East Hartford | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| East Lyme Total | 0 | | | | | | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------------|--------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------|
| | East Lyme | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| East Windsor Total | 0 | | | | | | | | |
| | East Windsor | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.13 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | East Windsor | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | East Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | East Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | East Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | East Windsor | Petrographic Analysis | Denied | 0 | 0 | 0 | | | |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------|--------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------|
| | East Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | East Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| Eastford Total | 0 | | | | | | | | |
| | Eastford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| Ellington Total | 0 | | | | | | | | |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | Moderate to severe (significant repairs required) | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Finished Basement |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 10 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 6 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | On Hold | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 1.15 | | | Waterproofing - Exterior;Gutters;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Denied | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 29 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Finished Basement;Footing Drains |
| | Ellington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | On Hold | 0 | 1 | 11.5 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|-----------------|-------------------------------------------------------------------------------------------|
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement |
| | Ellington | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Footing Drains |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Ellington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Ellington | Petrographic Analysis | On Hold | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Ellington | Petrographic Analysis | Paid | 1 | 1 | 13 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Ellington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Ellington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior |
| Enfield Total | 0 | | | | | | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------|
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension;Finished Basement;Footing Drains |
| | Enfield | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Enfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------------|-------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | Enfield | Petrographic Analysis | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Enfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Glastonbury Total | 0 | | | | | | | | |
| | Glastonbury | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Glastonbury | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Glastonbury | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| Hebron Total | 0 | | | | | | | | |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------|------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------|
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters |
| | Hebron | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Killingly Total | 0 | | | | | | | | |
| | Killingly | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| Lebanon Total | 0 | | | | | | | | |
| | Lebanon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| Manchester Total | 0 | | | | | | | | |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 1.9 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2 | | | |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 0 | Don't know | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Gutters |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 0 | Don't know | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 5.78 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Pending | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Concrete floor only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Petrographic Analysis | Paid | 0 | 1 | 0.12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Concrete floor only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Capillary Break |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------|
| | Manchester | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 1.58 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | Manchester | Visual Inspection | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------|
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Finished Basement |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Mansfield Total | 0 | | | | | | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Finished Basement |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------------------------------|
| | Mansfield | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 4.4 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 14 | | | Gutters;Footing Drains |
| | Mansfield | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Mansfield | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Mansfield | Visual Inspection | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | |
| | Mansfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------------------|-------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------|
| Marlborough Total | 0 | | | | | | | | |
| | Marlborough | Petrographic Analysis | Paid | 1 | 1 | 26 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains |
| Plainfield Total | 0 | | | | | | | | |
| | Plainfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| Portland Total | 0 | | | | | | | | |
| | Portland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| Somers Total | 0 | | | | | | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------|
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Somers | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Somers | Petrographic Analysis | Paid | 0 | 1 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | |
| | Somers | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Somers | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------------|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------|
| | Somers | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Footing Drains |
| South Windsor Total | 0 | | | | | | | | |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 40 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Finished Basement |
| | South Windsor | Visual Inspection | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 1 | 12.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | South Windsor | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 38 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | south windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 45 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | South Windsor | Petrographic Analysis | Paid | 0 | 1 | 0.93 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 25 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Petrographic Analysis | Paid | 1 | 1 | 18 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Exterior |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | South Windsor | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|----------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------|---------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension |
| | South Windsor | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | South Windsor | Visual Inspection | On Hold | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Stafford Total | 0 | | | | | | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break |
| | Stafford | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 52.5 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Denied | 1 | 0 | 0 | Don't know | Wall only | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 13 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 20 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Stafford | Visual Inspection | Denied | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Curtain or French Drain |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 1.74 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters;Gutters - With Extension |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters;Finished Basement;Footing Drains |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0.91 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| | Stafford | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------------|------------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Finished Basement |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters;Finished Basement |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.69 | | | Gutters;Curtain or French Drain |
| | Stafford | Petrographic Analysis | Paid | 0 | 1 | 0.58 | | | Gutters |
| Stafford Springs Total | 0 | | | | | | | | |
| | Stafford Springs | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| Storrs Total | 0 | | | | | | | | |
| | Storrs | Petrographic Analysis | Paid | 1 | 1 | 3.03 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| Storrs Mansfield Total | 0 | | | | | | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|------------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Storrs Mansfield | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Footing Drains |
| Suffield Total | 0 | | | | | | | | |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Suffield | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|-----------------|-----------------------------------------------------------------------------------|
| | Suffield | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Petrographic Analysis | Paid | 1 | 1 | 58 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Curtain or French Drain |
| | Suffield | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| Tolland Total | 0 | | | | | | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Exterior;Gutters |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 71 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 4.13 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 17 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 10 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------|
| | TOLLAND | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 3.58 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.88 | | | Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 1.28 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 3.03 | Don't know | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0.9 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2.5 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 13 | No visible signs | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 2 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 7 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior;Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Concrete floor only | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 15 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 7 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 30 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Tolland | Petrographic Analysis | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 12 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 25 | | | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|--------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 8 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 39 | | | Waterproofing - Exterior;Gutters |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 1.02 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Petrographic Analysis | Denied | 1 | 1 | 74 | Minor degradation | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Concrete floor only | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 74 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Tolland | Petrographic Analysis | Paid | 1 | 1 | 26 | Minor degradation | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | | Waterproofing - Exterior;Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 1.15 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 16 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 11 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | No visible signs | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains |
| Union Total | 0 | | | | | | | | |
| | Union | Petrographic Analysis | On Hold | 1 | 1 | 40 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Union | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Footing Drains |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------------|
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Finished Basement |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | |
| | Union | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters |
| | Union | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters |
| | Union | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| Vernon Total | 0 | | | | | | | | |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain |
| | Vernon | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2.03 | | | Waterproofing - Exterior;Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Denied | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Denied | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain |
| | Vernon | Petrographic Analysis | Paid | 1 | 1 | 4.65 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1 | | | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1.78 | | | Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Denied | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Interior;Gutters |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Gutters |
| | Vernon | Petrographic Analysis | Denied | 0 | 0 | 0 | | | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | Minor degradation | | Gutters |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Vernon | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 21 | | | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Interior;Gutters;Gutters - With Extension |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 2.1 | | | Gutters;Gutters - With Extension |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------------|--------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |
| | Vernon | Petrographic Analysis | Paid | 0 | 0 | 0 | | | |
| | Vernon | Petrographic Analysis | Paid | 1 | 1 | 70 | Severe (imminent threat of failure) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Wall only | Gutters;Finished Basement;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Footing Drains;Curtain or French Drain |
| | Vernon | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1.18 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| Wethersfield Total | 0 | | | | | | | | |
| | Wethersfield | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------|--------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------------------------|
| | Wethersfield | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Wethersfield | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters |
| Willington Total | 0 | | | | | | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Denied | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Gutters;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Footing Drains |
| | Willington | Visual Inspection | Denied | 0 | 0 | 0 | | | Gutters |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Severe (imminent threat of failure) | Wall only | Waterproofing - Exterior;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Footing Drains |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Gutters;Gutters - With Extension;Finished Basement |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Gutters - With Extension |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Willington | Petrographic Analysis | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Don't know | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | | Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Visual Inspection | Denied | 0 | 0 | 0 | | | |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-------------------------------------------------------------------------------------------|
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain |
| | Willington | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Floor and walls both | Gutters;Finished Basement |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/rec ommended) | Wall only | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain |
| | Willington | Petrographic Analysis | Paid | 0 | 1 | 0 | | | Waterproofing - Exterior |
| | Willington | Petrographic Analysis | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Petrographic Analysis | Paid | 1 | 1 | 2 | | Wall only | Gutters;Gutters - With Extension |

All Applications to Date

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------|------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------|
| | Willington | Petrographic Analysis | On Hold | 1 | 1 | 1.45 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |
| | Willington | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Finished Basement |
| Woodstock Total | 0 | | | | | | | | |
| | Woodstock | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Footing Drains;Curtain or French Drain |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-----------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| Grand Count | 58 | | | | | | | | |
| Count | 0 | | | | | | | | |
| | | | Denied | 0 | 0 | 0 | No visible signs | Wall only | |
| Bolton Count | 2 | | | | | | | | |
| | Bolton | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain |
| | bolton | Petrographic Analysis | Paid | 0 | 0 | 0 | No visible signs | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| Coventry Count | 5 | | | | | | | | |
| | Coventry | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 2.8 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Coventry | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 2.3 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains;Curtain or French Drain |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Coventry | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------------|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------------------------------|
| | Coventry | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain |
| East Hartford Count | 1 | | | | | | | | |
| | East Hartford | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Finished Basement |
| East Windsor Count | 2 | | | | | | | | |
| | East Windsor | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.13 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | East Windsor | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| Enfield Count | 1 | | | | | | | | |
| | Enfield | Petrographic Analysis | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| Glastonbury Count | 1 | | | | | | | | |
| | Glastonbury | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters |
| Manchester Count | 14 | | | | | | | | |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------|
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 1.9 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2 | | | |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 0 | Don't know | | Gutters;Finished Basement |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 0 | Don't know | Floor and walls both | Gutters |
| | Manchester | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 5.78 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| | Manchester | Visual Inspection | Pending | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------|------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|------------------------------------------------------------------------------------------|
| | Manchester | Visual Inspection | On Hold | 0 | 0 | 0 | | | Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters;Gutters - With Extension |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Manchester | Visual Inspection | Paid | 0 | 0 | 0 | | | Waterproofing - Interior;Gutters;Finished Basement |
| | Manchester | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Gutters - With Extension;Finished Basement |
| | Manchester | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters |
| Mansfield Count | 1 | | | | | | | | |
| | Mansfield | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters |
| Plainfield Count | 1 | | | | | | | | |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|----------------------------|---------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| | Plainfield | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Floor and walls both | Gutters;Finished Basement |
| South Windsor Count | 3 | | | | | | | | |
| | South Windsor | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains |
| | South Windsor | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Finished Basement |
| | South Windsor | Visual Inspection | On Hold | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain |
| Stafford Count | 4 | | | | | | | | |
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | |
| | Stafford | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 52.5 | Severe (imminent threat of failure) | Floor and walls both | Gutters;Gutters - With Extension |
| | Stafford | Petrographic Analysis | Paid | 1 | 1 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Gutters - With Extension;Footing Drains |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|-------------------------------|------------------|------------------------|--------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------|
| | Stafford | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Finished Basement |
| Stafford Springs Count | 1 | | | | | | | | |
| | Stafford Springs | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Gutters |
| Storrs Count | 1 | | | | | | | | |
| | Storrs | Petrographic Analysis | Paid | 1 | 1 | 3.03 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains |
| Tolland Count | 13 | | | | | | | | |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Wall only | Waterproofing - Exterior;Gutters |
| | Tolland | Petrographic Analysis | Paid | 0 | 1 | 0.5 | | | Waterproofing - Exterior;Gutters;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Minor degradation | Wall only | Waterproofing - Exterior;Gutters;Finished Basement |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|--|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|--------------------------------------------------------------------------------------------------|
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 4.13 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain |
| | Tolland | Visual Inspection | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters - With Extension;Finished Basement;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 0 | 0 | | | Gutters - With Extension;Footing Drains;Curtain or French Drain |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 3.58 | Moderate to severe (significant repairs required) | Wall only | Gutters;Gutters - With Extension |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2 | | | Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 1.88 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Petrographic Analysis | Approved - Pending Payment | 1 | 1 | 3.03 | Don't know | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains |
| | Tolland | Visual Inspection | Paid | 0 | 0 | 0 | | | Gutters;Finished Basement |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|---------------------|-----------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement |
| | Tolland | Visual Inspection | Paid | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Footing Drains |
| Union Count | 1 | | | | | | | | |
| | Union | Petrographic Analysis | On Hold | 1 | 1 | 40 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| Vernon Count | 5 | | | | | | | | |
| | Vernon | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 2.03 | | | Waterproofing - Exterior;Gutters |
| | Vernon | Petrographic Analysis | Approved - Pending Payment | 0 | 1 | 0 | | | Gutters;Gutters - With Extension;Finished Basement |
| | Vernon | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Floor and walls both | Gutters;Finished Basement |

2018 November Applications

| | Home City | Type of Test Performed | Application Status | Was Damage Present? | Was Pyrrhotite Present | Pyrrhotite Percent | Damage Level | Damage Location | House Features |
|------------------|------------|------------------------|----------------------------|---------------------|------------------------|--------------------|---------------------------------------------------|----------------------|-----------------------------------------------------------------------------|
| | Vernon | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Gutters;Gutters - With Extension |
| | Vernon | Petrographic Analysis | Paid | 0 | 1 | 1.18 | | | Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement |
| Willington Count | | 2 | | | | | | | |
| | Willington | Visual Inspection | Approved - Pending Payment | 1 | 0 | 0 | Moderate to severe (significant repairs required) | Wall only | Waterproofing - Exterior;Gutters;Gutters - With Extension |
| | Willington | Petrographic Analysis | On Hold | 1 | 1 | 1.45 | Minor to moderate (repair suggested/recommended) | Floor and walls both | Waterproofing - Exterior;Gutters;Footing Drains |