

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Total	0								
Ellington Total	0								
	Ellington	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
South Windsor Total	0								
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
Tolland Total	0								
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Union Total	0								
	Union	Petrographic Analysis	Approved - Pending Payment	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
Vernon Total	0								
	Vernon	Petrographic Analysis	Approved - Pending Payment	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
Willington Total	0								
	Willington	Visual Inspection	Approved - Pending Payment	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
Amston Total	0								
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
Andover Total	0								
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
Ashford Total	0								
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Bolton Total	0								
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Broadbrook Total	0								
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing
Columbia Total	0								
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
Coventry Total	0								
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
Eastford Total	0								
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ellington Total	0								
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Glastonbury Total	0								
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
Hebron Total	0								
	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Killingly Total	0								
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Lebanon Total	0								
	Lebanon	Visual Inspection	Paid	0	0	0			
Manchester Total	0								
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	1	2			

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Mansfield Total	0								
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
Mansfield Center Total	0								
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French
Marlborough Total	0								
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
Plainfield Total	0								
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
Portland Total	0								
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Somers Total	0								
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
South Windsor Total	0								
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing -
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
Stafford Total	0								
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing -
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
Stafford Springs Total	0								
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
Storrs Total	0								
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Storrs Mansfield Total	0								
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
Suffield Total	0								
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Total	0								
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing -
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Union Total	0								
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Petrographic Analysis	Paid	0	0	0			
Vernon Total	0								
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or Gutters
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing -
Wethersfield Total	0								
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
Wilmington Total	0								
	Wilmington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Wilmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Wilmington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Wilmington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Wilmington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Approved and Paid

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Total	0								
Total	0								
			Denied	0	0	0	No visible signs	Wall only	
Total	0								
			Denied	0	0	0	No visible signs	Wall only	
Amston Total	0								
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
Andover Total	0								
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ashford Total	0								
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Bolton Total	0								
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Broadbrook Total		0							
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Columbia Total		0							
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Coventry Total		0							
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	On Hold	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Denied	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	On Hold	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	On Hold	1	1	70	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
East Hartford Total	0								
	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	Denied	0	0	0			
	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
East Lyme Total	0								
	East Lyme	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
East Windsor Total	0								
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Petrographic Analysis	Denied	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Eastford Total	0								
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ellington Total	0								
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	On Hold	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	1	2			
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Mansfield Total	0								
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
Mansfield Center Total	0								
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
Marlborough Total	0								
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
Plainfield Total	0								
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
Portland Total	0								
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
Rocky Hill Total	0								
	Rocky Hill	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Somers Total	0								
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
South Windsor Total	0								
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Stafford Total	0								
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
Stafford Springs Total	0								
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
Storrs Total	0								
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Storrs Mansfield Total	0								
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
Suffield Total	0								
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Total	0								
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Denied	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	On Hold	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Denied	1	1	74	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Union Total	0								
	Union	Petrographic Analysis	Approved - Pending Payment	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Union	Petrographic Analysis	Paid	0	0	0			
Vernon Total	0								
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Pending	0	1	2.8			Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Approved - Pending Payment	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Pending	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Wethersfield Total	0								
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
Willington Total	0								
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Approved - Pending Payment	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior
	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
Woodstock Total	0								
	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain

December 2018

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Pending	0	1	2.8			Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Approved - Pending Payment	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Pending	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Willington Total	0								
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Approved - Pending Payment	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains