

All Applications To Date

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	351							
Andover Count	2							
	Andover	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ashford Count	12							
	Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ashford	Petrographic Analysis	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
Bolton Count	6							
	Bolton	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	bolton	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Columbia Count	2							
	Columbia	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Capillary Break
	Columbia	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Coventry Count	24							
	Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	0	0	0			Gutters
	Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement

All Applications To Date

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	0	0	0			Gutters
	Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
East Windsor Count		2						
	East Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
Ellington Count		30						
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Petrographic Analysis	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Footing Drains

All Applications To Date

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Don't know	Floor and walls both	
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	0	0	0			Gutters
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
Enfield Count	5							
	Enfield	Visual Inspection	0	0	0			Gutters
	Enfield	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	0	0	0			
Hebron Count	3							
	Hebron	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
Manchester Count	30							
	Manchester	Visual Inspection	1	0	0		Wall only	Gutters
	Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Applications To Date

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	0	0	0			Gutters
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	0	0	0			
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	0	0	0			
	Manchester	Visual Inspection	0	0	0			
	Manchester	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	0	0	0			Gutters
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
Mansfield Count	5							
	Mansfield	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Marlborough Count	1							
	Marlborough	Petrographic Analysis	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
Somers Count	5							
	Somers	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications To Date

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
* questions are optional and self reported some homeowners may have chosen not to answer								
Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features	
Somers	Visual Inspection	0	0	0			Gutters;Footing Drains	
Somers	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains	
Somers	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement	
Somers	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters	
South Windsor Count	37							
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains	
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain	
South Windsor	Petrographic Analysis	0	0	0			Gutters;Finished Basement	
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters	
South Windsor	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement	
South Windsor	Visual Inspection	0	0	0			Gutters	
South Windsor	Petrographic Analysis	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters	
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension	
South Windsor	Visual Inspection	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain	
South Windsor	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement	
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both		
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension	
South Windsor	Visual Inspection	0	0	0			Gutters;Gutters - With Extension	
South Windsor	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains	
South Windsor	Visual Inspection	0	0	0				
South Windsor	Petrographic Analysis	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains	
South Windsor	Petrographic Analysis	0	0	0			Gutters	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement	
South Windsor	Petrographic Analysis	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain	
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters	
South Windsor	Visual Inspection	0	0	0				
South Windsor	Visual Inspection	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both		
South Windsor	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement	
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension	
South Windsor	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement	

All Applications To Date

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Stafford Count	16							
	Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Visual Inspection	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	1	0	0	Don't know	Wall only	Gutters;Finished Basement
Stafford Springs Count	7							
	Stafford Springs	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford Springs	Petrographic Analysis	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford Springs	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
Suffield Count	1							
	Suffield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland Count	106							
	Tolland	Petrographic Analysis	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains	
Tolland	Petrographic Analysis	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0			Gutters	
Tolland	Visual Inspection	0	0	0				
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains	
Tolland	Petrographic Analysis	0	0	0				
tolland	Visual Inspection	0	0	0				
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain	
Tolland	Petrographic Analysis	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains	
tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
TOLLAND	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement	
Tolland	Visual Inspection	0	0	0			Gutters;Curtain or French Drain	
Tolland	Petrographic Analysis	0	0	0			Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement	
Tolland	Petrographic Analysis	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters	
Tolland	Visual Inspection	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain	

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features	
Tolland	Petrographic Analysis	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains	
Tolland	Visual Inspection	0	0	0			Gutters;Footing Drains	
Tolland	Petrographic Analysis	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain	
Tolland	Petrographic Analysis	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement	
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain	
Tolland	Petrographic Analysis	0	1	0			Waterproofing - Exterior;Gutters	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement	
Tolland	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0				
Tolland	Visual Inspection	0	0	0			Gutters	
Tolland	Visual Inspection	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension	
Tolland	Visual Inspection	1	0	0				
Tolland	Visual Inspection	0	0	0			Gutters;Gutters - With Extension	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains	
Tolland	Petrographic Analysis	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0			Gutters;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains	

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features	
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement;Footing Drains	
Tolland	Visual Inspection	0	0	0				
Tolland	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	0	0	0				
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	0	0	0			Gutters	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension	
Tolland	Petrographic Analysis	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains	
Tolland	Visual Inspection	1	0	0	Severe (imminent threat of failure)		Gutters	
Tolland	Visual Inspection	0	0	0			Finished Basement	
Tolland	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement	
Tolland	Petrographic Analysis	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain	
Tolland	Petrographic Analysis	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement	
Tolland	Petrographic Analysis	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement	
Tolland	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain	
Tolland	Visual Inspection	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain	
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement	
Tolland	Petrographic Analysis	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement	

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement	
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains	
Union Count	6							
Union	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains	
Union	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains	
Union	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain	
Union	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement	
Union	Visual Inspection	1	0	0	Don't know	Floor and walls both		
Union	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters	
Vernon Count	24							
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain	
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters	
Vernon	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement	
Vernon	Petrographic Analysis	0	0	0			Gutters	
Vernon	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains	
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters	
Vernon	Visual Inspection	0	0	0				
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains	
Vernon	Visual Inspection	0	0	0			Gutters	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters	
Vernon	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains	
Vernon	Visual Inspection	0	0	0			Gutters;Finished Basement	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters	
Vernon	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement	
Vernon	Visual Inspection	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain	
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain	

All Applications To Date

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received by:		2/28/2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willington Count	26							
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	0	0	0			Gutters
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	0	0	0			Gutters
	Willington	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Petrographic Analysis	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	0	1	0			Waterproofing - Exterior
Woodstock Count	1							
	Woodstock	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	331						
Andover Count	2						
Andover	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
Andover	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ashford Count	11						
Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
Ashford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ashford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Ashford	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Ashford	Petrographic Analysis	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Ashford	Petrographic Analysis	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Ashford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ashford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
Ashford	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Bolton Count	5						
Bolton	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Bolton	Visual Inspection	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
Bolton	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Bolton	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
bolton	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Columbia Count	2						
Columbia	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Capillary Break
Columbia	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Coventry Count	24						
Coventry	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
Coventry	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Coventry	Visual Inspection	0	0	0			Gutters
Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Coventry	Visual Inspection	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Coventry	Petrographic Analysis	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
Coventry	Visual Inspection	0	0	0			Gutters
Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)		
Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Coventry	Petrographic Analysis	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
Coventry	Visual Inspection	1	0	0	Don't know	Floor and walls both	
Coventry	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
East Windsor Count		2					
East Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
East Windsor	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
Ellington Count		28					
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
Ellington	Visual Inspection	0	0	0	Moderate to severe (significant repairs required)		Gutters
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ellington	Petrographic Analysis	0	1	10			Waterproofing - Exterior;Gutters
Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
Ellington	Petrographic Analysis	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
Ellington	Visual Inspection	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Ellington	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Footing Drains
Ellington	Petrographic Analysis	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Ellington	Petrographic Analysis	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ellington	Petrographic Analysis	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Ellington	Petrographic Analysis	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
Ellington	Visual Inspection	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Ellington	Visual Inspection	1	0	0	Don't know	Floor and walls both	
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
Ellington	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Ellington	Visual Inspection	0	0	0			Gutters
Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
Enfield Count		5					
Enfield	Visual Inspection	0	0	0			
Enfield	Visual Inspection	0	0	0			Gutters
Enfield	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
Enfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
Enfield	Visual Inspection	0	0	0			Gutters;Finished Basement
Hebron Count		1					
Hebron	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
Manchester Count		30					
Manchester	Visual Inspection	0	0	0			
Manchester	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Manchester	Visual Inspection	1	0	0		Wall only	Gutters
Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
Manchester	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Manchester	Visual Inspection	1	0	0	Don't know	Concrete floor only	Gutters
Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
Manchester	Visual Inspection	0	0	0			Gutters
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Manchester	Petrographic Analysis	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Manchester	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
Manchester	Visual Inspection	0	0	0			
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
Manchester	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Manchester	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters
Manchester	Visual Inspection	0	0	0			
Manchester	Visual Inspection	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Manchester	Petrographic Analysis	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
Manchester	Petrographic Analysis	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Manchester	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
Manchester	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
Manchester	Visual Inspection	0	0	0			Gutters
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
Manchester	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
Manchester	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
Mansfield Count		5					
Mansfield	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
Mansfield	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Mansfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
Mansfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Mansfield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Somers Count		5					
Somers	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Somers	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
Somers	Visual Inspection	0	0	0			Gutters;Footing Drains
Somers	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Somers	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters
South Windsor Count		36					
South Windsor	Visual Inspection	0	0	0			Gutters;Gutters - With Extension
South Windsor	Petrographic Analysis	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
South Windsor	Petrographic Analysis	0	0	0			Gutters;Finished Basement
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
South Windsor	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement
South Windsor	Visual Inspection	0	0	0			Gutters
South Windsor	Petrographic Analysis	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
South Windsor	Visual Inspection	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
South Windsor	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
South Windsor	Petrographic Analysis	0	0	0			Gutters
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
South Windsor	Petrographic Analysis	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
South Windsor	Visual Inspection	0	0	0			
South Windsor	Visual Inspection	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
South Windsor	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
South Windsor	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
South Windsor	Visual Inspection	0	0	0			Gutters;Gutters - With Extension
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
South Windsor	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
South Windsor	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
Stafford Count		16					
Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
Stafford	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Gutters
Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
Stafford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
Stafford	Visual Inspection	0	0	0			Gutters;Gutters - With Extension
Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
Stafford	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
Stafford	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
Stafford	Visual Inspection	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Stafford	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
Stafford	Visual Inspection	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
Stafford	Visual Inspection	1	0	0	Don't know	Wall only	Gutters;Finished Basement
Stafford Springs Count		7					
Stafford Springs	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
Stafford Springs	Petrographic Analysis	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Stafford Springs	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Stafford Springs	Visual Inspection	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
Stafford Springs	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
Stafford Springs	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
Stafford Springs	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
Suffield Count		1					
Suffield	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland Count		100					
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
Tolland	Petrographic Analysis	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Tolland	Petrographic Analysis	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			Gutters
Tolland	Visual Inspection	0	0	0			
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
Tolland	Petrographic Analysis	0	0	0			
tolland	Visual Inspection	0	0	0			
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
Tolland	Petrographic Analysis	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
TOLLAND	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
Tolland	Visual Inspection	0	0	0			Gutters;Curtain or French Drain
Tolland	Petrographic Analysis	0	0	0			Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
Tolland	Petrographic Analysis	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Tolland	Visual Inspection	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Tolland	Petrographic Analysis	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
Tolland	Visual Inspection	0	0	0			Gutters;Footing Drains
Tolland	Petrographic Analysis	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
Tolland	Petrographic Analysis	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
Tolland	Petrographic Analysis	0	1	0			Waterproofing - Exterior;Gutters
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			
Tolland	Visual Inspection	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
Tolland	Visual Inspection	1	0	0			
Tolland	Visual Inspection	0	0	0			Gutters;Gutters - With Extension
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
Tolland	Petrographic Analysis	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Tolland	Visual Inspection	0	0	0			Gutters;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement;Footing Drains
Tolland	Visual Inspection	0	0	0			
Tolland	Visual Inspection	0	0	0			Gutters
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
Tolland	Petrographic Analysis	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Tolland	Visual Inspection	1	0	0	Severe (imminent threat of failure)		Gutters
Tolland	Visual Inspection	0	0	0			Finished Basement
Tolland	Visual Inspection	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
Tolland	Petrographic Analysis	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Tolland	Petrographic Analysis	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
Tolland	Petrographic Analysis	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Tolland	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Tolland	Visual Inspection	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement
Tolland	Petrographic Analysis	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
Tolland	Visual Inspection	0	0	0			Gutters;Finished Basement
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
Union Count		5					
Union	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Union	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Union	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
Union	Visual Inspection	1	0	0	Don't know	Floor and walls both	
Union	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
Vernon Count		21					
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
Vernon	Petrographic Analysis	0	0	0			Gutters
Vernon	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
Vernon	Visual Inspection	0	0	0			
Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
Vernon	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Vernon	Visual Inspection	0	0	0			Gutters;Finished Basement
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
Vernon	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
Vernon	Visual Inspection	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
Vernon	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
Vernon	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willington Count		24					
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Willington	Visual Inspection	0	0	0			Gutters;Finished Basement
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
Willington	Petrographic Analysis	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willington	Visual Inspection	0	0	0			Gutters

Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willington	Visual Inspection	1	0	0			Gutters;Curtain or French Drain
Willington	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
Willington	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
Willington	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
Willington	Petrographic Analysis	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Willington	Visual Inspection	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
Willington	Petrographic Analysis	0	1	0			Waterproofing - Exterior
Woodstock Count		1					
Woodstock	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received in the month of:		February, 2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	42							
Coventry Count	4							
	Coventry	Visual Inspection	0	0	0			Gutters
	Coventry	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
Ellington Count	7							
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
Enfield Count	2							
	Enfield	Visual Inspection	0	0	0			Gutters
	Enfield	Visual Inspection	0	0	0			
Hebron Count	1							
	Hebron	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
Manchester Count	6							
	Manchester	Petrographic Analysis	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	0	0	0			
	Manchester	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	0	0	0			
	Manchester	Visual Inspection	0	0	0			
	Manchester	Visual Inspection	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Marlborough Count	1							
	Marlborough	Petrographic Analysis	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
Somers Count	1							
	Somers	Visual Inspection	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
South Windsor Count	4							
	South Windsor	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	0	0	0			
	South Windsor	Petrographic Analysis	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters

TOWN LEVEL DATA for the CROG Foundation Testing Program								
All Applications Received in the month of:		February, 2018						
<i>* questions are optional and self reported some homeowners may have chosen not to answer</i>								
	Home City	Type of Test Performed	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Tolland Count	9							
	Tolland	Petrographic Analysis	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	0	0	0			Gutters
Vernon Count	3							
	Vernon	Visual Inspection	0	0	0			
	Vernon	Visual Inspection	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	0	0	0			Gutters
Willington Count	4							
	Willington	Visual Inspection	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	0	0	0			Gutters
	Willington	Visual Inspection	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement