

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	61								
Andover Count	1								
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
Ashford Count	2								
	Ashford	Visual Inspection	Approved - Pending Payment	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Coventry Count	4								
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	On Hold	0	0	0			
	Coventry	Petrographic Analysis	Approved - Pending Payment	1	1	1.83	Don't know		Gutters
	Coventry	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
East Hartford Count	1								
	East Hartford	Visual Inspection	Denied	0	0	0			
East Lyme Count	1								
	East Lyme	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Ellington Count	7								
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Pending	0	0	0			Waterproofing - Interior
Enfield Count	1								
	Enfield	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Lebanon Count	1								
	Lebanon	Visual Inspection	Paid	0	0	0			
Manchester Count	5								
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Approved - Pending Payment	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
Mansfield Center Count	1								
	Mansfield Center	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	
Somers Count	1								
	Somers	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Interior;Footing Drains
South Windsor Count	4								
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
Stafford Count	12								
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Approved - Pending Payment	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
	Stafford	Petrographic Analysis	Approved - Pending Payment	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Approved - Pending Payment	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Approved - Pending Payment	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	On Hold	0	1	0.58			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Suffield Count	2								
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
Tolland Count	12								
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Approved - Pending Payment	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Vernon Count	2								
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Wethersfield Count	2								
	Wethersfield	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
Willington Count	2								
	Willington	Visual Inspection	Approved - Pending Payment	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement