

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	22								
Coventry Count	2								
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
East Granby Count	1								
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
Manchester Count	3								
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
Mansfield Count	2								
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement
	Mansfield	Visual Inspection	On Hold	0	0	0			
South Windsor Count	5								
	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	On Hold	0	0	0			
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
Tolland Count	7								
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Wall only	
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Willington Count	2								
	Willington	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	3248								
Amston Count	3								
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Andover Count	30								
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Petrographic Analysis	Paid	0	0	0			
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Andover	Visual Inspection	Paid	0	0	0			
	Andover	Visual Inspection	Paid	0	0	0			
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Andover	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Ashford Count	66								
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Petrographic Analysis	Paid	1	1	1	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	43	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	0	0	0	Don't know		

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Ashford	Petrographic Analysis	Paid	1	1	32	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Paid	1	1	1.35	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	1.38	Minor degradation	Floor and walls both	Gutters;Footing Drains
Avon Count	2								
	Avon	Visual Inspection	Paid	0	0	0			
	Avon	Visual Inspection	Paid	0	0	0			
Berlin Count	1								
	Berlin	Visual Inspection	Paid	0	0	0			
Bloomfield Count	8								
	Bloomfield	Visual Inspection	Paid	0	0	0			
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Bolton Count	60								
	Bolton	Petrographic Analysis	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	1	1.2			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	1	0.66			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	1	11			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	1	0	0	No visible signs		Gutters - With Extension;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Bolton	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Petrographic Analysis	Paid	0	1	0.87			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	1	1	1	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Petrographic Analysis	Paid	0	1	2.15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
Bristol Count	1								
	Bristol	Visual Inspection	Paid	0	0	0			Gutters
Broad Brook Count	4								
	Broad Brook	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	BROAD BROOK	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Broad Brook	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	broad brook	Visual Inspection	Paid	0	0	0			Gutters
Broadbrook Count	1								
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Brooklyn Count	1								
	Brooklyn	Visual Inspection	Paid	0	0	0			
Canterbury Count	1								
	Canterbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
Canton Count	2								
	Canton	Visual Inspection	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Canton	Visual Inspection	Paid	0	0	0			Gutters
Chaplin Count	3								
	Chaplin	Visual Inspection	Paid	0	0	0			
	Chaplin	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Chaplin	Visual Inspection	Paid	0	0	0			
Cheshire Count	1								
	Cheshire	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Colchester Count	5								
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Columbia Count	23								
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Columbia	Visual Inspection	Paid	1	0	0	No visible signs		Gutters
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	0	0	0			
Coventry Count	231								
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	1	1	0		Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	1	54			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Coventry	Visual Inspection	Paid	1	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	0.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	0.55			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Cromwell Count	1								
	Cromwell	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
Durham Count	#REF!								
East Granby Count	3								
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
East Hampton Count	5								
	East Hampton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			
East Hartford Count	8								
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Hartford	Visual Inspection	Paid	0	0	0			
	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hartford	Visual Inspection	Paid	0	0	0			Finished Basement
	East Hartford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
East Lyme Count	#REF!								
East Windsor Count	45								
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	1	1	0.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	1	1	1.05	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	East Windsor	Visual Inspection	Paid	0	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	1	29			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Petrographic Analysis	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	1	1.41			Gutters;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
Eastford Count	1								
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ellington Count	241								
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	1.52			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	0.71			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Interior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0.7			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	1.81	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	1	1	2.28	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	1.57	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0.57			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0	No visible signs		
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Gutters;Gutters - With Extension;Capillary Break
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0.69			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	1.86			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	1	1.86	Don't know		Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	2.21	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	36			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.5			Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Enfield Count	80								

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Petrographic Analysis	Paid	1	1	0.89	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	59	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Petrographic Analysis	Paid	1	1	1.14	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	0.24			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	0.62	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.45	No visible signs	Wall only	Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.51			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation		Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Enfield	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	1	0.88	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	0	1	0.13			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.39	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	33		Wall only	Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	0	1	1.46			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	1	1	27	Don't know	Concrete floor only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Farmington Count	1								
	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Glastonbury Count	55								
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	GLASTONBURY	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Capillary Break
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0	No visible signs		
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
Granby Count	2								
	Granby	Visual Inspection	Paid	0	0	0			Gutters
	Granby	Visual Inspection	Paid	0	0	0			
Griswold Count	#REF!								
Haddam Count	#REF!								
Hamden Count	#REF!								
Hampton Count	3								
	Hampton	Visual Inspection	Paid	0	0	0			Gutters
	Hampton	Visual Inspection	Paid	0	0	0			
	Hampton	Visual Inspection	Paid	0	0	0			
Hartford Count	#REF!								
Hebron Count	28								
	Hebron	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Petrographic Analysis	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Petrographic Analysis	Paid	0	1	0.73			Waterproofing - Exterior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
Killingly Count	2								
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Killingworth Count	1								
	Killingworth	Visual Inspection	Paid	0	0	0			
Lebanon Count	5								
	Lebanon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	0	0	0			
Longmeadow Count	#REF!								
Lyme Count	#REF!								
Madison Count	#REF!								
Manchester Count	279								
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	1	2			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Concrete floor only	Gutters
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	30	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	1	1	2.49	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	68	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	0	1	1.69			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	2.67	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	1	1	2.58	Don't know	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	2.41	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	1	1	56	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	1	1	55	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	MANCHESTER	Petrographic Analysis	Paid	0	1	1.5			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	manchester	Petrographic Analysis	Paid	0	1	29			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
Mansfield Count	104								
	Mansfield	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0.54			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0.52			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0.68			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
Mansfield Center Count	5								
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield Center	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Marlborough Count	7								
	Marlborough	Petrographic Analysis	Paid	0	0	0			Gutters
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters
	Marlborough	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains
Middletown Count	2								
	Middletown	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Middletown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
New Haven Count	#REF!								
Newington Count	1								

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Newington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Northford Count	#REF!								
Plainfield Count	1								
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
Plantsville Count	#REF!								
Pomfret Count	2								
	Pomfret	Visual Inspection	Paid	0	0	0			Gutters
	Pomfret	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Portland Count	6								
	Portland	Visual Inspection	Paid	0	0	0			Finished Basement
	Portland	Visual Inspection	Paid	0	0	0			Gutters
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
	Portland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Portland	Visual Inspection	Paid	0	0	0			Gutters
	Portland	Visual Inspection	Paid	0	0	0			
Rocky Hill Count	#REF!								
S Glastonbury Count	1								
	S Glastonbury	Visual Inspection	Paid	0	0	0			
Simsbury Count	1								
	Simsbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Somers Count	125								
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	1	1	16	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Footing Drains
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Petrographic Analysis	Paid	1	1	0.54	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Petrographic Analysis	Paid	1	1	1.32	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	1.32			Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	0.92			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	0.48			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	0.79			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	1.31			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	0	1	1.33			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	1	1	0.64	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	2.37			Gutters;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Petrographic Analysis	Paid	0	1	0.63			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
South Glastonbury Count	6								
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			
South Windsor Count	430								
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	1	2.37			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0.77			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	0.48	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	1.33			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	1	0.76			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	33			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	28			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	3.22	Don't know	Wall only	Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	29	Don't know	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	0	1	43			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	2.96	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	38			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	0		Floor and walls both	Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	1.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	0.99	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	1.81			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	86			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0.45			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.8			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.67	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.63			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	30	No visible signs		Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South windsor	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	0.4			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	26			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	1.35			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	23	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	11			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
South Windssor Count	1								
	South Windssor	Visual Inspection	Paid	0	0	0			Gutters
Southington Count	#REF!								
Stafford Count	178								
	Stafford	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	visual	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	29	No visible signs		Waterproofing - Exterior
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0		Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0		Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	43			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	1.81	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	0.81	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	1			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	No visible signs		Finished Basement
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
	Stafford	Petrographic Analysis	Paid	0	1	2.18			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
STAFFORD SPGS Count	1								
	STAFFORD SPGS	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Stafford Springs Count	45								
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Stafford springs	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	stafford springs	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	1	1	94	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford Springs	Petrographic Analysis	Paid	1	1	1.05	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	STAFFORD SPRINGS	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	0	1	32			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			
	Stafford Springs	Petrographic Analysis	Paid	1	1	0		Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Petrographic Analysis	Paid	1	1	23	Don't know	Floor and walls both	Gutters - With Extension
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	STAFFORD Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	1	1	3.16	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
Stafford Springs, Count	1								
	Stafford Springs,	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Staffordville Count	1								
	Staffordville	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Storrs Count	4								
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Storrs	Visual Inspection	Paid	0	0	0			Gutters
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Storrs Mansfield Count	7								
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.57			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			
	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.43			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Storrs-Mansfield Count	1								
	Storrs-Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
Suffield Count	45								
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Thompson Count	1								
	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Count	648								
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	1.49			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.06	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	51	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	0.81			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0.69			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	28			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	2.07			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	1.21	No visible signs		Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	73	Minor degradation	Floor and walls both	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	50	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	14			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0.81	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.89			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	34		Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.09			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0.45	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.19	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		
	Tolland	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	1.61	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	70	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	2.51	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	1.09	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0.67			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	3.54	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	84	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	1	2.88	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.78			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
Union Count	28								
	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Union	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Paid	0	1	74			Gutters;Finished Basement
	Union	Visual Inspection	Paid	0	0	0			
	Union	Visual Inspection	Paid	0	0	0			Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Union	Petrographic Analysis	Paid	0	1	0.95			Waterproofing - Exterior;Footing Drains
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Petrographic Analysis	Paid	1	1	1.8	Minor degradation	Wall only	Finished Basement
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Paid	0	0	0			
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Union	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
Vernon Count	201								
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	0.83			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	1	1	2.07	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	0.5	Minor degradation	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	3.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	1.1			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Petrographic Analysis	Paid	1	1	58	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Vernon Rockville Count	2								
	Vernon Rockville	Visual Inspection	Paid	0	0	0			
	Vernon Rockville	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Voluntown Count	1								
	Voluntown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Waterford Count	#REF!								
West Granby Count	1								
	West Granby	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
West Hartford Count	1								
	West Hartford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
WEST WILLINGTON Count	1								
	WEST WILLINGTON	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Wethersfield Count	2								
	Wethersfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willimantic Count	1								
	Willimantic	Visual Inspection	Paid	0	0	0			
Willington Count	166								
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.054			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	60	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Interior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	1	1	0.82	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	0.85	Don't know	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	54	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	1.46			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	2.42			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Petrographic Analysis	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	1.34	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	1.74			Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Petrographic Analysis	Paid	1	1	2.34	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid ONLY									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	2			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
Windham Count	5								
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Gutters
	Windham	Petrographic Analysis	Paid	0	0	0			Gutters
Windsor Count	7								
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Windsor	Visual Inspection	Paid	0	0	0			
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Winsted Count	1								
	Winsted	Petrographic Analysis	Paid	0	0	0			Gutters
Wolcott Count	#REF!								
Woodstock Count	4								
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Woodstock	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	3523								
Amston Count	4								
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Amston	Visual Inspection	On Hold	0	0	0			Finished Basement;Curtain or French Drain
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Andover Count	33								
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Denied	0	0	0			Gutters
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Andover	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Petrographic Analysis	Paid	0	0	0			
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Andover	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			
	Andover	Visual Inspection	Paid	0	0	0			
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Andover	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Ashford Count	70								
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Petrographic Analysis	Paid	1	1	1	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	43	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	0	0	0	Don't know		
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Ashford	Petrographic Analysis	Paid	1	1	32	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Ashford	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
	Ashford	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Denied	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Paid	1	1	1.35	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	1.38	Minor degradation	Floor and walls both	Gutters;Footing Drains
Avon Count	2								
	Avon	Visual Inspection	Paid	0	0	0			
	Avon	Visual Inspection	Paid	0	0	0			
Berlin Count	3								
	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Berlin	Visual Inspection	Paid	0	0	0			
	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
Bloomfield Count	12								
	Bloomfield	Visual Inspection	Pending DoH Approval	0	0	0			
	Bloomfield	Visual Inspection	Paid	0	0	0			
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Bloomfield	Visual Inspection	Denied	0	0	0			Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Pending	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bloomfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
Bolton Count	66								
	Bolton	Petrographic Analysis	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	1	1.2			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	1	0.66			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Bolton	Visual Inspection	On Hold	1	0	0	No visible signs		Gutters;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	1	11			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	On Hold	0	0	0			
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	1	0	0	No visible signs		Gutters - With Extension;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Bolton	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	1	0.87			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	1	1	1	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Petrographic Analysis	Paid	0	1	2.15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
Bristol Count	3								
	Bristol	Visual Inspection	Paid	0	0	0			Gutters
	Bristol	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	Bristol	Visual Inspection	Denied	0	0	0			Finished Basement
Broad Brook Count	4								
	Broad Brook	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	BROAD BROOK	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Broad Brook	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	broad brook	Visual Inspection	Paid	0	0	0			Gutters
Broadbrook Count	1								
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Brooklyn Count	1								
	Brooklyn	Visual Inspection	Paid	0	0	0			
Canterbury Count	1								
	Canterbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
Canton Count	2								
	Canton	Visual Inspection	Paid	0	0	0			Gutters
	Canton	Visual Inspection	Paid	0	0	0			Gutters
Chaplin Count	3								
	Chaplin	Visual Inspection	Paid	0	0	0			
	Chaplin	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Chaplin	Visual Inspection	Paid	0	0	0			
Cheshire Count	2								
	Cheshire	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Cheshire	Visual Inspection	Pending DoH Approval	0	0	0			
Colchester Count	6								
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Colchester	Visual Inspection	Pending	0	0	0			Curtain or French Drain
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Columbia Count	24								
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Columbia	Visual Inspection	Paid	1	0	0	No visible signs		Gutters
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	0	0	0			
Coventry Count	245								
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	On Hold	1	1	0		Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	1	1	0		Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Denied	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Denied	0	0	0			Gutters
	Coventry	Visual Inspection	Denied	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	1	54			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Denied	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Coventry	Visual Inspection	Paid	1	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Denied	1	1	25	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Denied	1	1	70	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	0.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	0.55			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
Cromwell Count	2								
	Cromwell	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Cromwell	Petrographic Analysis	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Durham Count	1								
	Durham	Visual Inspection	On Hold	0	0	0			
East Granby Count	4								
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	East Granby	Petrographic Analysis	Pending DoH Approval	0	0	0			Gutters
East Hampton Count	5								

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Hampton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			
East Hartford Count	10								
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Hartford	Visual Inspection	Paid	0	0	0			
	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hartford	Visual Inspection	Paid	0	0	0			Finished Basement
	East Hartford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	East Hartford	Visual Inspection	Denied	0	0	0			
	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
East Lyme Count	2								
	East Lyme	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters
	East Lyme	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
East Windsor Count	49								
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	1	1	0.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	1	1	1.05	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	East Windsor	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	East Windsor	Visual Inspection	Paid	0	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	1	29			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Petrographic Analysis	Denied	0	0	0			
	East Windsor	Petrographic Analysis	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	1	1.41			Gutters;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
Eastford Count	1								
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
Ellington Count	256								
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	1.52			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	On Hold	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	0	1	0.71			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Interior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0.7			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	1.81	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	1	1	2.28	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	1.57	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0.57			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0	No visible signs		
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Gutters;Gutters - With Extension;Capillary Break
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0.69			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	On Hold	0	0	0			

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Denied	0	1	0.34			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Denied	1	0	0	Minor degradation	Floor and walls both	Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	1.86			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	1	1.86	Don't know		Gutters;Footing Drains
	Ellington	Petrographic Analysis	Denied	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	2.21	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Denied	0	1	11.5			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	36			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Denied	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.5			Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Enfield Count	83								
	Enfield	Petrographic Analysis	Paid	1	1	0.89	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	59	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Petrographic Analysis	Paid	1	1	1.14	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	0.24			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	0.62	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.45	No visible signs	Wall only	Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.51			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation		Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	1	0.88	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	0	1	0.13			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.39	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	33		Wall only	Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	0	1	1.46			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	1	1	27	Don't know	Concrete floor only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Petrographic Analysis	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Farmington Count	1								
	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Glastonbury Count	72								
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Glastonbury	Visual Inspection	Denied	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	GLASTONBURY	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Capillary Break
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Pending	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0	No visible signs		
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Granby Count	4								
	Granby	Visual Inspection	Denied	0	0	0			Gutters
	Granby	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	Granby	Visual Inspection	Paid	0	0	0			Gutters
	Granby	Visual Inspection	Paid	0	0	0			
Griswold Count	1								
	Griswold	Petrographic Analysis	Pending DoH Approval	0	1	0.4			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
Haddam Count	1								
	Haddam	Visual Inspection	Pending DoH Approval	0	0	0			Finished Basement
Hamden Count	1								
	Hamden	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
Hampton Count	3								
	Hampton	Visual Inspection	Paid	0	0	0			Gutters
	Hampton	Visual Inspection	Paid	0	0	0			
	Hampton	Visual Inspection	Paid	0	0	0			
Hartford Count	2								
	Hartford	Visual Inspection	Pending DoH Approval	0	0	0	Minor degradation	Concrete floor only	Finished Basement
	Hartford	Visual Inspection	Denied	0	0	0			
Hebron Count	33								
	Hebron	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Hebron	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Petrographic Analysis	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Denied	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	Hebron	Petrographic Analysis	Paid	0	1	0.73			Waterproofing - Exterior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Denied	1	0	0	Don't know	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
Killingly Count	2								
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Killingworth Count	1								
	Killingworth	Visual Inspection	Paid	0	0	0			
Lebanon Count	5								
	Lebanon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	0	0	0			
Longmeadow Count	1								
	Longmeadow	Petrographic Analysis	On Hold	0	0	0			Gutters;Finished Basement
Lyme Count	1								

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Lyme	Petrographic Analysis	Pending DoH Approval	0	0	0			Gutters;Finished Basement
Madison Count	1								
	Madison	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
Manchester Count	289								
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	1	2			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Concrete floor only	Gutters
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	30	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	2.49	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	On Hold	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	68	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	0	1	1.69			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	2.67	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
	Manchester	Visual Inspection	Denied	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Pending DoH Approval	1	1	34	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	1	1	2.58	Don't know	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Pending DoH Approval	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	2.41	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	1	1	56	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	55	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	MANCHESTER	Petrographic Analysis	Paid	0	1	1.5			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	manchester	Petrographic Analysis	Paid	0	1	29			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Denied	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
Mansfield Count	113								
	Mansfield	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Denied	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0.54			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0.52			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Visual Inspection	On Hold	0	0	0			
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0.68			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Pending DoH Approval	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
Mansfield Center Count	7								

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield Center	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield Center	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Mansfield Center	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Marlborough Count	8								
	Marlborough	Visual Inspection	Pending DoH Approval	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Marlborough	Petrographic Analysis	Paid	0	0	0			Gutters
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters
	Marlborough	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains
Middletown Count	2								
	Middletown	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Middletown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
New Haven Count	1								
	New Haven	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
Newington Count	2								
	Newington	Visual Inspection	Pending DoH Approval	0	0	0			Finished Basement
	Newington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
Northford Count	1								
	Northford	Visual Inspection	Pending DoH Approval	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
Plainfield Count	1								

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
Plantsville Count	1								
	Plantsville	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
Pomfret Count	3								
	Pomfret	Visual Inspection	Paid	0	0	0			Gutters
	Pomfret	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Pomfret	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Portland Count	6								
	Portland	Visual Inspection	Paid	0	0	0			Finished Basement
	Portland	Visual Inspection	Paid	0	0	0			Gutters
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
	Portland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Portland	Visual Inspection	Paid	0	0	0			Gutters
	Portland	Visual Inspection	Paid	0	0	0			
Rocky Hill Count	3								
	Rocky Hill	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Rocky Hill	Visual Inspection	On Hold	0	0	0			
	Rocky Hill	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
S Glastonbury Count	1								
	S Glastonbury	Visual Inspection	Paid	0	0	0			
Simsbury Count	1								
	Simsbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Somers Count	128								
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	1	1	16	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Denied	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Petrographic Analysis	Denied	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Footing Drains
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Petrographic Analysis	Paid	1	1	0.54	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Petrographic Analysis	Paid	1	1	1.32	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	1.32			Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	0.92			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	0.48			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Somers	Petrographic Analysis	On Hold	0	1	0.65			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	0.79			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	1.31			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	0	1	1.33			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	1	1	0.64	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	2.37			Gutters;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Petrographic Analysis	Paid	0	1	0.63			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
South Glastonbury Count	7								
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Glastonbury	Petrographic Analysis	Pending DoH Approval	1	1	35	Don't know	Wall only	
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			
South Windsor Count	474								
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	2.37			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0.77			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	0.48	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	1.33			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	1	0.76			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	33			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	28			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	3.22	Don't know	Wall only	Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	29	Don't know	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	0	1	43			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	2.96	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	38			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Denied	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0		Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	1.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	0.99	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	1.81			Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	On Hold	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Denied	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Denied	0	1	2			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	86			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	On Hold	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0.45			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.8			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.67	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.63			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	30	No visible signs		Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Denied	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South windsor	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	0.4			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	26			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	1.35			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	23	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	11			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
South Windssor Count	1								
	South Windssor	Visual Inspection	Paid	0	0	0			Gutters
Southington Count	2								
	Southington	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Curtain or French Drain
	Southington	Visual Inspection	Denied	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
Stafford Count	185								
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	On Hold	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Denied	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	visual	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	29	No visible signs		Waterproofing - Exterior
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0		Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0		Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	43			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	1.81	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	1	1	0.81	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	1			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	No visible signs		Finished Basement
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
	Stafford	Petrographic Analysis	Paid	0	1	2.18			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
STAFFORD SPGS Count	1								
	STAFFORD SPGS	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Stafford Springs Count	46								
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford springs	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
	Stafford Springs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	stafford springs	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	1	1	94	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford Springs	Petrographic Analysis	Paid	1	1	1.05	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	STAFFORD SPRINGS	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	0	1	32			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			
	Stafford Springs	Petrographic Analysis	Paid	1	1	0		Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			

ALL APPLICATIONS									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Petrographic Analysis	Paid	1	1	23	Don't know	Floor and walls both	Gutters - With Extension
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	STAFFORD Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	1	1	3.16	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
Stafford Springs, Count	1								
	Stafford Springs,	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Staffordville Count	1								
	Staffordville	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Storrs Count	4								
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Storrs	Visual Inspection	Paid	0	0	0			Gutters
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
Storrs Mansfield Count	7								
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.57			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			
	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.43			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Storrs-Mansfield Count	1								
	Storrs-Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
Suffield Count	55								
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	On Hold	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			
	Suffield	Visual Inspection	Denied	0	0	0			
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Denied	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Thompson Count	1								
	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Count	686								
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	1.49			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Denied	1	1	0.42	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Denied	1	1	46	Minor degradation	Wall only	Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.06	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	51	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	0.81			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0.69			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Denied	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	28			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	2.07			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	1.21	No visible signs		Gutters
	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	73	Minor degradation	Floor and walls both	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	50	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	14			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0.81	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.89			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Tolland	Petrographic Analysis	Denied	0	1	1.49			Waterproofing - Interior
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	34		Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual	Denied	1	1	84	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Denied	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.09			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0.45	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.19	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		
	Tolland	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Wall only	
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Petrographic Analysis	Denied	0	1	16			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	1.61	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	70	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	2.51	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	1.09	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Denied	1	1	74	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0.67			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	3.54	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	84	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Tolland	Visual Inspection	Denied	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

ALL APPLICATIONS									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	2.88	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.78			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
Union Count	30								
	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Union	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Paid	0	1	74			Gutters;Finished Basement
	Union	Visual Inspection	Paid	0	0	0			
	Union	Visual Inspection	Paid	0	0	0			Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Union	Petrographic Analysis	Paid	0	1	0.95			Waterproofing - Exterior;Footing Drains
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Union	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Petrographic Analysis	Paid	1	1	1.8	Minor degradation	Wall only	Finished Basement
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Paid	0	0	0			
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Union	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Denied	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
Vernon Count	220								
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	0.83			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	1	1	2.07	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	0.5	Minor degradation	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Vernon	Visual Inspection	Denied	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Denied	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	3.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	1.1			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Petrographic Analysis	Paid	1	1	58	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
	vernon	Petrographic Analysis	Denied	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
Vernon Rockville Count	2								
	Vernon Rockville	Visual Inspection	Paid	0	0	0			
	Vernon Rockville	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Voluntown Count	1								
	Voluntown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Waterford Count	1								
	Waterford	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
West Granby Count	1								
	West Granby	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
West Hartford Count	4								
	West Hartford	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	West Hartford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	West Hartford	Visual Inspection	On Hold	0	0	0			Gutters
	West Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Finished Basement
WEST WILLINGTON Count	1								

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	WEST WILLINGTON	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Wethersfield Count	4								
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
	Wethersfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
Willimantic Count	1								
	Willimantic	Visual Inspection	Paid	0	0	0			
Willington Count	173								
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.054			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	60	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Interior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	1	1	0.82	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	0.85	Don't know	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	54	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	1.46			Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Willington	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	2.42			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

ALL APPLICATIONS									
	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Denied	0	0	0			
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Petrographic Analysis	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	1.34	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	1.74			Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Petrographic Analysis	Paid	1	1	2.34	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Footing Drains
	Willington	Visual Inspection	Pending DoH Approval	1	0	0	No visible signs		Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	2			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
Windham Count	7								
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Gutters
	Windham	Petrographic Analysis	Paid	0	0	0			Gutters
	Windham	Visual Inspection	Pending DoH Approval	0	0	0			
Windsor Count	8								
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Windsor	Visual Inspection	Paid	0	0	0			
	Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Footing Drains
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

ALL APPLICATIONS

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Winsted Count	1								
	Winsted	Petrographic Analysis	Paid	0	0	0			Gutters
Wolcott Count	1								
	Wolcott	Visual Inspection	Pending	0	0	0			Gutters;Finished Basement
Woodstock Count	5								
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Woodstock	Visual Inspection	Denied	0	0	0			Gutters
	Woodstock	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters - With Extension