

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	13								
4102			Paid	0	0	0	No visible signs	Wall only	
Bolton Count	1								
4097	Bolton	Visual Inspection	On Hold	0	0	0			Gutters
Coventry Count	3								
4099	Coventry	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Curtain or French Drain
4103	Coventry	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
4104	Coventry	Petrographic Analysis	On Hold	0	0	0			Gutters;Gutters - With Extension
Eastford Count	1								
4106	Eastford	Visual Inspection	On Hold	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
Enfield Count	1								
4101	Enfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
Glastonbury Count	1								
4098	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			
Hebron Count	1								
4105	Hebron	Visual Inspection	Pending	0	0	0			Gutters;Finished Basement
Manchester Count	1								
4096	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
South Windsor Count	1								
4100	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			
Stafford Springs Count	2								
4095	Stafford Springs	Visual Inspection	Approved - Pending Payment	0	0	0			
4107	Stafford Springs	Visual Inspection	On Hold	0	0	0			Finished Basement
Vernon Count	1								
4108	Vernon	Visual Inspection	On Hold	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	3849								
Amston Count	5								
2194	Amston	Visual Inspection	On Hold	0	0	0			Finished Basement;Curtain or French Drain
3886	Amston	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
3286	Amston	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
809	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2062	Amston	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Andover Count	34								
2008	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2101	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2227	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2326	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
938	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1090	Andover	Visual Inspection	Denied	0	0	0			Gutters
1118	Andover	Visual Inspection	Paid	0	0	0			Gutters
1151	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1179	Andover	Petrographic Analysis	Paid	0	0	0			
1192	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
55	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
234	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3324	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3376	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior
3395	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
3397	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
3644	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
1220	Andover	Visual Inspection	Paid	0	0	0			
1482	Andover	Visual Inspection	Paid	0	0	0			
2754	Andover	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2818	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2916	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
695	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
840	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3202	Andover	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
412	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
466	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
515	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
4079	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1575	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
1688	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1727	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1768	Andover	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1798	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Ashford Count	79								
1587	Ashford	Petrographic Analysis	Paid	1	1	43	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1605	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
1609	Ashford	Petrographic Analysis	Paid	1	1	32	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
1654	Ashford	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1683	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1200	Ashford	Visual Inspection	Paid	0	0	0			
1239	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1241	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior
1305	Ashford	Visual Inspection	Paid	0	0	0			Gutters
1435	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
1458	Ashford	Visual Inspection	Paid	0	0	0			
1521	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2199	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2200	Ashford	Petrographic Analysis	Paid	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2201	Ashford	Petrographic Analysis	Denied	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2209	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension
2229	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2289	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2303	Ashford	Petrographic Analysis	Paid	1	1	1.38	Minor degradation	Floor and walls both	Gutters;Footing Drains
2524	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains
2529	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2603	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2613	Ashford	Visual Inspection	Paid	0	0	0			
2650	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3398	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3428	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3445	Ashford	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
3554	Ashford	Visual Inspection	Paid	0	0	0			Gutters
3615	Ashford	Petrographic Analysis	Paid	1	1	1	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3621	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
900	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
916	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
925	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
997	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1008	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1078	Ashford	Visual Inspection	Paid	0	0	0	Don't know		
1084	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
11	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
19	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
47	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
81	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
110	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
111	Ashford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
112	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
123	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
152	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
161	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
257	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
810	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
825	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
876	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2797	Ashford	Visual Inspection	Paid	0	0	0			Gutters
2921	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
2927	Ashford	Visual Inspection	Paid	0	0	0			
2931	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
3022	Ashford	Petrographic Analysis	Paid	1	1	1.35	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
3702	Ashford	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
3704	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3776	Ashford	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3785	Ashford	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
3834	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3859	Ashford	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3897	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3902	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3951	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3961	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension;Footing Drains
3970	Ashford	Visual Inspection	Paid	0	0	0			
389	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
390	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
395	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
473	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
501	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
516	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
592	Ashford	Visual Inspection	Paid	0	0	0			Gutters
3114	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3127	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3228	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
3234	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
Avon Count	4								
3113	Avon	Visual Inspection	Paid	0	0	0			
3328	Avon	Visual Inspection	Paid	0	0	0			
4027	Avon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3935	Avon	Visual Inspection	Paid	0	0	0			
Berlin Count	4								
3870	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1052	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
2139	Berlin	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2423	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
Bloomfield Count	15								
2178	Bloomfield	Visual Inspection	Denied	0	0	0			Gutters - With Extension;Finished Basement
2197	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1103	Bloomfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1303	Bloomfield	Visual Inspection	Pending DoH Approval	0	0	0			
1965	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
2131	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1822	Bloomfield	Visual Inspection	Paid	0	0	0			
3721	Bloomfield	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3835	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
3867	Bloomfield	Visual Inspection	Denied	0	0	0			
2492	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2505	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2506	Bloomfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
2607	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
4018	Bloomfield	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
Bolton Count	73								
3994	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
4021	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4093	Bolton	Visual Inspection	Paid	0	0	0			
4094	Bolton	Visual Inspection	Paid	0	0	0			Gutters
4097	Bolton	Visual Inspection	On Hold	0	0	0			Gutters
3877	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3955	Bolton	Visual Inspection	Paid	0	0	0			
1202	Bolton	Petrographic Analysis	Paid	0	1	0.87			Gutters;Gutters - With Extension
1203	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1245	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1339	Bolton	Visual Inspection	Paid	0	0	0			
2154	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2294	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2422	Bolton	Visual Inspection	Paid	1	0	0	No visible signs		Gutters - With Extension;Curtain or French Drain
928	Bolton	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
987	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
1012	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1053	Bolton	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
1092	Bolton	Visual Inspection	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1132	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1134	Bolton	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1161	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1618	Bolton	Visual Inspection	Paid	0	0	0			
1628	Bolton	Visual Inspection	Paid	0	0	0			Gutters
1707	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1751	Bolton	Petrographic Analysis	Paid	1	1	1	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3125	Bolton	Petrographic Analysis	Paid	0	1	1.2			Gutters;Gutters - With Extension;Finished Basement
3126	Bolton	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
3167	Bolton	Visual Inspection	On Hold	0	0	0			
3218	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3265	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3276	Bolton	Visual Inspection	Paid	0	0	0			Gutters
1941	Bolton	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Footing Drains
1968	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2039	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
2076	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2134	Bolton	Petrographic Analysis	Paid	0	1	11			
2427	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
2460	Bolton	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
2530	Bolton	Petrographic Analysis	Paid	0	1	2.15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2547	Bolton	Visual Inspection	Paid	0	0	0			Gutters
2615	Bolton	Petrographic Analysis	Paid	0	1	0.66			Waterproofing - Exterior;Footing Drains;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2617	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2654	Bolton	Visual Inspection	Paid	0	0	0			
2702	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2732	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
422	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
522	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
538	Bolton	Visual Inspection	Paid	0	0	0			
616	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
638	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
703	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
727	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
748	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
800	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
812	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
815	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
49	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
59	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
68	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
98	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
279	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
290	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
3377	Bolton	Visual Inspection	Paid	0	0	0			
3637	Bolton	Visual Inspection	Paid	0	0	0			
3640	Bolton	Visual Inspection	Paid	0	0	0			
3660	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2821	Bolton	Petrographic Analysis	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2836	Bolton	Visual Inspection	Paid	0	0	0			Gutters
2849	Bolton	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2885	Bolton	Visual Inspection	On Hold	1	0	0	No visible signs		Gutters;Curtain or French Drain
2920	Bolton	Visual Inspection	Paid	0	0	0			Gutters
2937	Bolton	Visual Inspection	Paid	0	0	0			
Bristol Count	3								
2834	Bristol	Visual Inspection	Paid	0	0	0			Gutters
3540	Bristol	Visual Inspection	Denied	0	0	0			Finished Basement
2649	Bristol	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
Broad Brook Count	4								
1210	Broad Brook	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
1592	Broad Brook	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2379	BROAD BROOK	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3317	broad brook	Visual Inspection	Paid	0	0	0			Gutters
Broadbrook Count	1								
817	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Brooklyn Count	2								
3809	Brooklyn	Visual Inspection	Paid	0	0	0			Gutters
2857	Brooklyn	Visual Inspection	Paid	0	0	0			
Canterbury Count	1								
1287	Canterbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
Canton Count	2								
2995	Canton	Visual Inspection	Paid	0	0	0			Gutters
1155	Canton	Visual Inspection	Paid	0	0	0			Gutters
Chaplin Count	3								
2700	Chaplin	Visual Inspection	Paid	0	0	0			
3708	Chaplin	Visual Inspection	Paid	0	0	0			
2175	Chaplin	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
Cheshire Count	2								
2970	Cheshire	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3508	Cheshire	Visual Inspection	Paid	0	0	0			
Colchester Count	8								
3361	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2254	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1645	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
1791	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4010	Colchester	Visual Inspection	Paid	0	0	0			Gutters

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4063	Colchester	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
1219	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3693	Colchester	Visual Inspection	Pending DoH Approval	0	0	0			Curtain or French Drain
Columbia Count	26								
3752	Columbia	Visual Inspection	Paid	0	0	0			Gutters
3784	Columbia	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2143	Columbia	Visual Inspection	Paid	0	0	0			
2203	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2291	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2405	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3342	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3033	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3042	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1776	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
994	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1047	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
603	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1332	Columbia	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
2808	Columbia	Visual Inspection	Paid	0	0	0			
588	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
593	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2498	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2513	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2532	Columbia	Visual Inspection	Paid	0	0	0			Gutters
2602	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2686	Columbia	Visual Inspection	Paid	1	0	0	No visible signs		Gutters
2690	Columbia	Visual Inspection	Paid	0	0	0			
2730	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
57	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
262	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Coventry Count	265								
35	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
42	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
46	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
82	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
108	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
128	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
159	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
165	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
169	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
193	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
198	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
221	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
243	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
282	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
912	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
917	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
923	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
943	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
951	Coventry	Petrographic Analysis	Denied	1	1	25	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
955	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
989	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1002	Coventry	Visual Inspection	Paid	0	0	0			Gutters

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1017	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			
1019	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
1021	Coventry	Visual Inspection	Paid	0	0	0			
1027	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1028	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
1034	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1038	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1042	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
1046	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1068	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters
1082	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1087	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
1125	Coventry	Visual Inspection	Paid	1	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
1137	Coventry	Visual Inspection	Paid	0	0	0			
1167	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1177	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1180	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2147	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension
2148	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
2159	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2160	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2161	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2165	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2168	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2176	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2182	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2198	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2249	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2252	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2302	Coventry	Visual Inspection	Paid	0	0	0			
2325	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2331	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2337	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2339	Coventry	Visual Inspection	Paid	0	0	0			
2342	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2343	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2345	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2352	Coventry	Visual Inspection	Paid	1	0	0			Gutters
2356	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters
2367	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
4008	Coventry	Visual Inspection	Paid	0	0	0			Gutters
4048	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
4051	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
4075	Coventry	Visual Inspection	Paid	0	0	0			
4086	COVENTRY	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
4099	Coventry	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Curtain or French Drain
4103	Coventry	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
4104	Coventry	Petrographic Analysis	On Hold	0	0	0			Gutters;Gutters - With Extension
3678	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3685	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3690	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3698	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3699	Coventry	Visual Inspection	Paid	0	0	0			
3726	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3728	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3758	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3761	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3791	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3823	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3860	Coventry	Petrographic Analysis	Paid	1	1	34	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
3869	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
3874	Coventry	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
3906	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3920	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3936	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3941	Coventry	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
3969	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1533	Coventry	Petrographic Analysis	Paid	0	1	0.55			Gutters
1543	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1569	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			
1576	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1593	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
1616	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1631	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1633	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1671	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1703	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1715	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1725	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
1728	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1753	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1782	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1797	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
1811	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1828	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters - With Extension
3332	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
3341	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3353	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3451	Coventry	Visual Inspection	Paid	0	0	0			
3530	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3549	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3550	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3585	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
3589	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension
3599	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3645	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3028	Coventry	Visual Inspection	Paid	0	0	0			
3034	Coventry	Visual Inspection	Paid	0	0	0			
3056	Coventry	Visual Inspection	Paid	0	0	0			
3071	Coventry	Visual Inspection	Paid	0	0	0			
3073	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
3085	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3091	Coventry	Petrographic Analysis	On Hold	1	1	0		Wall only	
3092	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
3093	Coventry	Petrographic Analysis	Paid	1	1	0		Wall only	
3097	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
3123	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3143	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3161	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3182	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3200	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3220	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3233	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3279	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3300	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3307	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3308	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3310	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3316	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2485	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2486	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2493	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2526	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2542	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
2556	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2558	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2559	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
2631	Coventry	Petrographic Analysis	Paid	0	1	54			Waterproofing - Exterior;Gutters;Finished Basement
2636	Coventry	Visual Inspection	Paid	0	0	0			
2637	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2639	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2651	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2658	Coventry	Visual Inspection	Denied	0	0	0			Gutters
2659	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2670	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2674	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2698	Coventry	Petrographic Analysis	Paid	0	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
2707	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
2713	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2722	Coventry	Petrographic Analysis	Paid	0	0	0			Finished Basement
2743	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2744	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1206	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1231	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1232	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1254	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
1267	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1272	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1276	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1290	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
1308	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1319	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1321	Coventry	Visual Inspection	Denied	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1322	Coventry	Visual Inspection	Denied	0	0	0			
1325	Coventry	Visual Inspection	Paid	0	0	0			
1342	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1351	Coventry	Petrographic Analysis	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
1352	Coventry	Visual Inspection	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
1386	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1387	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
1457	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1494	Coventry	Visual Inspection	Paid	0	0	0			
1509	Coventry	Visual Inspection	Paid	0	0	0			
1522	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
1527	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1862	Coventry	Visual Inspection	Paid	0	0	0			
1871	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1875	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1877	Coventry	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1894	Coventry	Visual Inspection	Paid	0	0	0			
1912	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1924	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1930	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1936	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1974	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1998	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2004	Coventry	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Gutters
2042	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2053	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2096	Coventry	Visual Inspection	Paid	0	0	0			
2118	Coventry	Visual Inspection	Paid	0	0	0			
642	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
644	Coventry	Petrographic Analysis	Paid	0	0	0			
648	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
653	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
667	Coventry	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
677	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
680	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
693	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
721	Coventry	Petrographic Analysis	Denied	1	1	70	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
722	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
738	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
753	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
776	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
779	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
784	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
793	Coventry	Visual Inspection	Paid	0	0	0			Gutters
806	Coventry	Visual Inspection	Paid	0	0	0			
824	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
833	Coventry	Visual Inspection	Paid	0	0	0			
875	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
877	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
878	Coventry	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
879	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
302	Coventry	Visual Inspection	Paid	0	0	0			Gutters
303	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
305	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
309	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
312	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
313	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
327	Coventry	Visual Inspection	Paid	0	0	0			Gutters
331	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
339	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
351	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
363	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
378	Coventry	Visual Inspection	Paid	0	0	0			
418	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
423	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
436	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
457	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
498	Coventry	Visual Inspection	Paid	0	0	0			
509	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
511	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
528	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
553	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
554	Coventry	Visual Inspection	Denied	0	0	0			Gutters
582	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
2765	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2770	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2787	Coventry	Petrographic Analysis	Paid	1	1	0.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2798	Coventry	Visual Inspection	Paid	0	0	0			
2803	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2805	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2820	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
2826	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
2867	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2889	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2891	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2904	Coventry	Visual Inspection	Paid	0	0	0			
2969	Coventry	Visual Inspection	Paid	0	0	0			
2978	Coventry	Visual Inspection	Paid	0	0	0			
2986	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3021	coventry	Visual Inspection	Paid	0	0	0			Gutters
Cromwell Count	2								
1075	Cromwell	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1391	Cromwell	Petrographic Analysis	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Durham Count	1								
3104	Durham	Visual Inspection	On Hold	0	0	0			
East Granby Count	5								
2383	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3730	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3832	East Granby	Visual Inspection	Pending DoH Approval	0	0	0			
1485	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2534	East Granby	Petrographic Analysis	Paid	0	0	0			Gutters
East Hampton Count	6								
2634	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3322	East Hampton	Visual Inspection	Paid	0	0	0			
3285	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
4028	East Hampton	Visual Inspection	Pending	0	0	0			Gutters
1658	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2087	East Hampton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
East Hartford Count	13								
2305	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2373	East Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
3333	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1709	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3756	East Hartford	Visual Inspection	On Hold	1	0	0	No visible signs		
3889	East Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3945	East Hartford	Visual Inspection	Pending DoH Approval	0	0	0			
484	East Hartford	Visual Inspection	Denied	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
983	East Hartford	Visual Inspection	Paid	0	0	0			Finished Basement
1055	East Hartford	Visual Inspection	Paid	0	0	0			
1497	East Hartford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
762	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
816	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
East Lyme Count		2							
1866	East Lyme	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters
465	East Lyme	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
East Windsor Count		57							
375	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
420	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
442	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
573	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
636	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
640	East Windsor	Petrographic Analysis	Denied	0	0	0			
714	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
790	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
791	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
32	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
94	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2764	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
2806	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2830	East Windsor	Visual Inspection	Paid	0	0	0			
2863	East Windsor	Visual Inspection	Paid	0	0	0			
2878	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains
2879	East Windsor	Petrographic Analysis	Paid	1	1	0.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2935	East Windsor	Petrographic Analysis	Paid	0	1	29			Waterproofing - Exterior;Gutters;Finished Basement
2963	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
2141	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
2224	East Windsor	Visual Inspection	Paid	0	0	0			
2290	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
2727	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3082	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3120	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
3121	East Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
3140	East Windsor	Petrographic Analysis	Paid	1	1	1.05	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
3188	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3221	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3226	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1872	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
1943	East Windsor	Petrographic Analysis	Paid	0	1	1.41			Gutters;Finished Basement;Footing Drains
3697	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3762	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3856	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3861	East Windsor	Visual Inspection	Paid	0	0	0			
3871	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3873	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3876	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
3911	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
3952	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3380	East Windsor	Visual Inspection	Paid	0	0	0			
3401	East Windsor	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
3402	East Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
3518	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
3626	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
1577	East Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
1788	East Windsor	Visual Inspection	Paid	0	0	0			
1250	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1295	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1297	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1302	East Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Wall only	Gutters;Gutters - With Extension;Finished Basement
1434	East Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
996	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1054	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1124	East Windsor	Visual Inspection	Paid	0	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1160	East Windsor	Petrographic Analysis	Paid	0	0	0			
Eastford Count	3								
4106	Eastford	Visual Inspection	On Hold	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
386	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3924	Eastford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
Ellington Count	280								
3674	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3684	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3692	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains
3755	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3759	Ellington	Visual Inspection	Paid	0	0	0			
3775	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3789	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3790	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3813	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3817	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3824	Ellington	Visual Inspection	Paid	0	0	0			
3828	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement
3852	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3868	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3882	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
3944	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
3968	Ellington	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3986	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3991	Ellington	Petrographic Analysis	On Hold	1	0	0	Don't know		Gutters;Finished Basement
4003	Ellington	Visual Inspection	Paid	0	0	0			Gutters
4005	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
4012	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4015	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
4036	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4040	Ellington	Petrographic Analysis	Paid	0	0	0			
4044	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
4060	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
907	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
920	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
921	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
935	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
937	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
947	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
959	Ellington	Visual Inspection	Paid	0	0	0			
966	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
984	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
988	Ellington	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1006	Ellington	Petrographic Analysis	Paid	0	1	0.5			Finished Basement
1013	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1014	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1024	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1040	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1051	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1056	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1057	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1065	Ellington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Interior;Gutters;Gutters - With Extension
1066	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1076	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1097	Ellington	Visual Inspection	Paid	0	0	0			
1119	Ellington	Petrographic Analysis	Paid	0	1	0.9			Gutters;Gutters - With Extension;Capillary Break
1141	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
631	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
633	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
637	Ellington	Visual Inspection	Paid	0	0	0			Gutters
651	Ellington	Visual Inspection	Paid	0	0	0			
656	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
660	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
664	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters
673	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
682	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
704	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
705	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
717	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
723	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Footing Drains
725	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
728	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
733	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
739	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
821	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
823	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
897	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2441	Ellington	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2443	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2523	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2555	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
2590	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
2601	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2608	Ellington	Visual Inspection	Paid	0	0	0			Gutters
2623	Ellington	Petrographic Analysis	Paid	1	1	1.81	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2624	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2680	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2682	Ellington	Visual Inspection	Paid	0	0	0			Gutters
2687	Ellington	Visual	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2688	Ellington	Petrographic Analysis	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2740	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2136	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2140	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2190	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2191	Ellington	Petrographic Analysis	Paid	0	1	1.86			Gutters;Footing Drains
2192	Ellington	Visual Inspection	Paid	1	1	1.86	Don't know		Gutters;Footing Drains
2217	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2218	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
2230	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2235	Ellington	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
2238	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2258	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2262	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2271	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2281	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2282	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2311	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
2318	Ellington	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Gutters - With Extension
2324	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2338	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
2386	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
2394	Ellington	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2398	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2402	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2418	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2419	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2420	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
31	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
34	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
37	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
38	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
56	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
84	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
95	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
106	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
107	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
113	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
118	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
126	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
127	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
137	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
157	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
192	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
205	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
223	Ellington	Visual Inspection	Paid	0	0	0			Gutters
235	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
264	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
284	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
291	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
2771	Ellington	Visual Inspection	Paid	0	0	0			
2784	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2785	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2799	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2815	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2827	Ellington	Visual Inspection	Paid	0	0	0			
2831	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2838	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2852	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2868	Ellington	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2884	Ellington	Visual Inspection	Paid	0	0	0			
2906	Ellington	Visual Inspection	Paid	0	0	0	No visible signs		
2907	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2914	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2943	Ellington	Visual Inspection	Denied	1	0	0	Minor degradation	Floor and walls both	Finished Basement;Curtain or French Drain
2947	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2972	Ellington	Petrographic Analysis	Paid	0	0	0			
2973	Ellington	Visual Inspection	Paid	0	0	0			
2985	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
2989	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
3016	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
3019	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3023	Ellington	Visual Inspection	Paid	0	0	0			
319	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
323	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
335	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
338	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
340	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
341	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
353	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
379	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
388	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
407	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
438	Ellington	Visual Inspection	Paid	0	0	0			Gutters
448	Ellington	Petrographic Analysis	Denied	0	1	11.5			Waterproofing - Exterior;Gutters
451	Ellington	Visual Inspection	Paid	0	0	0			Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
454	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
462	Ellington	Visual Inspection	Paid	0	0	0			Gutters
467	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
468	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
480	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
495	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
529	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
534	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
549	Ellington	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
561	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
562	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
566	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1216	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1221	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1227	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
1229	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1230	Ellington	Visual Inspection	Denied	0	0	0			
1312	Ellington	Visual Inspection	Paid	0	0	0			Footing Drains
1314	Ellington	Petrographic Analysis	Paid	0	1	0.71			Gutters;Curtain or French Drain
1341	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1343	Ellington	Petrographic Analysis	Paid	0	1	0.7			Gutters
1380	Ellington	Visual Inspection	Paid	0	0	0			
1383	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1428	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1432	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1436	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
1439	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1443	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1444	Ellington	Petrographic Analysis	Paid	1	1	2.21	Minor to moderate (repair suggested/recommended)	Floor and walls both	
1462	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1484	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1487	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1495	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement;Curtain or French Drain
1518	Ellington	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3030	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3032	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3060	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3061	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3069	Ellington	Visual Inspection	Paid	0	0	0			
3077	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
3079	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3087	Ellington	Visual Inspection	Paid	0	0	0			
3088	Ellington	Petrographic Analysis	Paid	0	0	0			
3136	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3146	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3150	Ellington	Visual Inspection	Paid	0	0	0			
3154	Ellington	Petrographic Analysis	Paid	1	1	1.57	Moderate to severe (significant repairs required)	Floor and walls both	
3177	Ellington	Visual Inspection	On Hold	0	0	0			
3179	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
3190	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3196	Ellington	Visual Inspection	Paid	0	0	0			
3203	Ellington	Visual Inspection	Paid	0	0	0			
3208	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3210	Ellington	Visual Inspection	Paid	0	0	0			
3215	Ellington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3216	Ellington	Petrographic Analysis	Denied	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3217	Ellington	Petrographic Analysis	Paid	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
3229	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain
3264	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension
3278	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Finished Basement
3289	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Curtain or French Drain
3304	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3311	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1863	Ellington	Petrographic Analysis	Paid	1	1	2.28	Moderate to severe (significant repairs required)	Wall only	Gutters
1864	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1865	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1895	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters - With Extension
1905	Ellington	Petrographic Analysis	Denied	0	1	0.34			Gutters;Gutters - With Extension
1926	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1990	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2018	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2033	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
2048	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2055	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2065	Ellington	Petrographic Analysis	Paid	0	1	1.52			Gutters
2074	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
2090	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2091	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2132	Ellington	Petrographic Analysis	Paid	0	1	0.57			Gutters
1531	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1536	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1545	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1562	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1565	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1574	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1622	Ellington	Visual Inspection	Paid	0	0	0			Gutters

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1635	Ellington	Petrographic Analysis	Paid	0	1	0.69			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1650	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
1655	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1667	Ellington	Visual Inspection	Paid	0	0	0			
1710	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1716	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement
1742	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1778	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
1796	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1825	Ellington	Petrographic Analysis	Paid	1	1	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3329	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3350	Ellington	Visual Inspection	Paid	0	0	0			
3357	Ellington	Visual Inspection	Paid	0	0	0			
3383	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
3396	Ellington	Visual Inspection	Paid	0	0	0			
3421	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3432	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3527	Ellington	Petrographic Analysis	Paid	0	1	36			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3576	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3587	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3610	Ellington	Visual Inspection	Paid	0	0	0			
3629	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3647	Ellington	Visual Inspection	Paid	0	0	0			
3650	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Enfield Count	90								
3375	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3551	Enfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3622	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
73	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
88	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
97	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1059	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1094	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1136	Enfield	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1145	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1152	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Curtain or French Drain
1153	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
3714	Enfield	Visual Inspection	Paid	0	0	0			Gutters
3717	Enfield	Petrographic Analysis	Paid	0	1	0.13			
3763	Enfield	Visual Inspection	Paid	0	0	0			
3783	Enfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3937	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
3993	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4006	Enfield	Visual Inspection	Paid	0	0	0			
4092	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
4101	Enfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
2193	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
2244	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2334	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2335	Enfield	Petrographic Analysis	Paid	1	1	1.14	Moderate to severe (significant repairs required)	Wall only	Gutters
2366	Enfield	Visual Inspection	Paid	0	0	0			
2403	Enfield	Petrographic Analysis	Paid	1	1	0.51			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
2404	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation		Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
760	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
2430	Enfield	Petrographic Analysis	Paid	1	1	0.88	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2435	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2436	Enfield	Visual Inspection	Paid	0	0	0			Gutters
2438	Enfield	Visual Inspection	Paid	0	0	0			Gutters
2444	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2474	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2503	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
2525	Enfield	Petrographic Analysis	Paid	1	1	27	Don't know	Concrete floor only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2527	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2543	Enfield	Visual Inspection	Paid	0	0	0			Gutters
2595	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2610	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2641	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2692	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
1530	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1621	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1700	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1701	Enfield	Petrographic Analysis	Paid	1	1	0.39	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1729	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1770	Enfield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Curtain or French Drain
1793	Enfield	Petrographic Analysis	Paid	1	1	0.89	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
1233	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1237	Enfield	Petrographic Analysis	Paid	0	1	1.46			Gutters
1262	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1376	Enfield	Visual Inspection	Paid	0	0	0			Gutters
1394	Enfield	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Finished Basement
1395	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
1426	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1489	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
1492	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1502	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
1503	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
1514	Enfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2762	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2766	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2829	Enfield	Visual Inspection	Paid	0	0	0			
2832	Enfield	Petrographic Analysis	Paid	1	1	59	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
2877	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2997	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2998	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
321	Enfield	Visual Inspection	Paid	0	0	0			Gutters
356	Enfield	Visual Inspection	Paid	0	0	0			
445	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
506	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
560	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
594	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1856	Enfield	Petrographic Analysis	Paid	1	1	0.62	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1858	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
1891	Enfield	Petrographic Analysis	Paid	1	1	0.45	No visible signs	Wall only	Gutters;Finished Basement
1892	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
1976	Enfield	Petrographic Analysis	Paid	0	1	33		Wall only	Waterproofing - Exterior;Gutters
1980	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1988	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
2009	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2034	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2038	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2044	Enfield	Petrographic Analysis	Paid	0	0	0			
2047	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3110	Enfield	Petrographic Analysis	Paid	0	1	0.24			Gutters;Finished Basement
3181	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3241	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Farmington Count	3								
3366	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3907	Farmington	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
3914	Farmington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Glastonbury Count	89								
3686	Glastonbury	Visual Inspection	Paid	0	0	0			
3687	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3700	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			
3766	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Footing Drains
3787	Glastonbury	Visual Inspection	On Hold	0	0	0			
3812	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3844	Glastonbury	Visual Inspection	Paid	0	0	0			
3845	Glastonbury	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
3847	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Curtain or French Drain
3851	Glastonbury	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
3916	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3921	Glastonbury	Visual Inspection	Paid	0	0	0			
3980	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3379	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
3412	Glastonbury	Visual Inspection	Paid	0	0	0			
3512	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
3568	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
3606	Glastonbury	Visual Inspection	Paid	0	0	0			
3618	Glastonbury	Visual Inspection	Pending DoH Approval	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
3666	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3668	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
665	Glastonbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
789	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
995	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters
1020	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters
1048	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1071	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1128	GLASTONBURY	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Capillary Break
1187	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
1197	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3080	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3086	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
3094	Glastonbury	Visual Inspection	Paid	0	0	0			
3144	Glastonbury	Visual Inspection	Paid	0	0	0			
3206	Glastonbury	Visual Inspection	Paid	0	0	0	No visible signs		
3227	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
3257	Glastonbury	Visual Inspection	Denied	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3259	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2158	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Finished Basement
2172	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2187	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
2188	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2215	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2269	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains
2353	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
2364	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
2414	Glastonbury	Visual Inspection	Paid	0	0	0			
3992	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3997	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4034	Glastonbury	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
4039	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			
4062	Glastonbury	Visual Inspection	Pending	0	0	0			Gutters;Finished Basement
4066	Glastonbury	Visual Inspection	Pending	0	0	0	No visible signs		Gutters;Finished Basement
4098	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			
1890	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
1893	Glastonbury	Visual Inspection	Denied	0	0	0			
1972	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2012	Glastonbury	Visual Inspection	Paid	0	0	0			
2014	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1226	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1326	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1399	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1424	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1475	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
1483	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1499	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2429	Glastonbury	Visual Inspection	Paid	0	0	0			
2551	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2668	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
2669	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2677	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2685	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
1581	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
1586	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1598	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
1634	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1641	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1679	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1804	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
519	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
2774	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2777	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2804	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2824	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2835	Glastonbury	Visual Inspection	Paid	0	0	0			
2856	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2869	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2944	Glastonbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2948	Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
Granby Count	4								
2790	Granby	Visual Inspection	Paid	0	0	0			
2265	Granby	Visual Inspection	Denied	0	0	0			Gutters
2272	Granby	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
1253	Granby	Visual Inspection	Paid	0	0	0			Gutters
Griswold Count	1								
2122	Griswold	Petrographic Analysis	Pending DoH Approval	0	1	0.4			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
Haddam Count	1								
1274	Haddam	Visual Inspection	Pending DoH Approval	0	0	0			Finished Basement
Hamden Count	1								
1481	Hamden	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
Hampton Count	5								
2293	Hampton	Visual Inspection	Paid	0	0	0			
4030	Hampton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
4083	Hampton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
2689	Hampton	Visual Inspection	Paid	0	0	0			Gutters
2717	Hampton	Visual Inspection	Paid	0	0	0			
Hartford Count	2								

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
930	Hartford	Visual Inspection	Denied	0	0	0			
1696	Hartford	Visual Inspection	Pending DoH Approval	0	0	0	Minor degradation	Concrete floor only	Finished Basement
Hebron Count	40								
1800	Hebron	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters
1813	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2448	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2490	Hebron	Visual Inspection	Paid	0	0	0			Gutters
2500	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2548	Hebron	Petrographic Analysis	Paid	0	1	0.73			Waterproofing - Exterior;Gutters
2557	Hebron	Visual Inspection	Paid	0	0	0			Gutters
2652	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3336	Hebron	Visual Inspection	Paid	0	0	0			
3354	Hebron	Visual Inspection	Paid	0	0	0			Gutters
3504	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3601	Hebron	Visual Inspection	Paid	0	0	0			Gutters
3843	Hebron	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Footing Drains
3895	Hebron	Visual Inspection	Paid	0	0	0			
3931	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
3959	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
93	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
201	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
247	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2780	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2783	Hebron	Visual Inspection	Denied	0	0	0			
2840	Hebron	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
720	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
822	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
3064	Hebron	Visual Inspection	Denied	1	0	0	Don't know	Concrete floor only	Gutters;Gutters - With Extension
3151	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3283	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1243	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1397	Hebron	Visual Inspection	Paid	0	0	0			Gutters
1447	Hebron	Petrographic Analysis	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
1919	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1953	Hebron	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
2025	Hebron	Visual Inspection	Paid	0	0	0			
345	Hebron	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
4042	Hebron	Visual Inspection	Pending	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
4064	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
4105	Hebron	Visual Inspection	Pending	0	0	0			Gutters;Finished Basement
2169	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
2284	Hebron	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
2285	Hebron	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
Killingly Count	2								
2979	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
450	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Killingworth Count	1								
3593	Killingworth	Visual Inspection	Paid	0	0	0			
Lebanon Count	5								
3384	Lebanon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3429	Lebanon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
452	Lebanon	Visual Inspection	Paid	0	0	0			
2888	Lebanon	Visual Inspection	Paid	0	0	0			
3186	Lebanon	Visual Inspection	Paid	0	0	0			
Longmeadow Count	1								
2645	Longmeadow	Petrographic Analysis	On Hold	0	0	0			Gutters;Finished Basement
Lyme Count	1								
3546	Lyme	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
Madison Count	1								
1102	Madison	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
Manchester Count	310								
904	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
949	Manchester	Visual Inspection	Paid	0	0	0			
954	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
957	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
961	Manchester	Visual Inspection	Paid	0	0	0			
964	manchester	Petrographic Analysis	Paid	0	1	29			Gutters;Gutters - With Extension

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
990	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1004	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
1011	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Finished Basement
1025	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
1029	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1035	Manchester	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1036	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
1058	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1069	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
1073	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters
1088	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
1108	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1139	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1154	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1163	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1166	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1170	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1193	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2426	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2450	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2463	Manchester	Petrographic Analysis	Paid	1	1	56	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension
2466	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2475	Manchester	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
2479	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2528	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2538	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
2550	Manchester	Visual Inspection	Paid	0	0	0			
2553	Manchester	Visual Inspection	Paid	0	0	0			
2594	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2626	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2646	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2672	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2676	Manchester	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
2684	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2718	Manchester	Petrographic Analysis	Paid	1	1	2.41	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
2721	Manchester	Visual Inspection	Paid	0	0	0			
2736	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
2741	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3055	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3063	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3078	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3115	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3117	Manchester	Visual Inspection	Paid	0	0	0			
3156	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3157	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3168	Manchester	Visual Inspection	Paid	0	0	0			Finished Basement
3173	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
3176	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3178	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3187	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3192	Manchester	Visual Inspection	Paid	0	0	0			
3193	Manchester	Visual Inspection	Paid	0	0	0			
3205	Manchester	Petrographic Analysis	Paid	0	0	0			
3212	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
3224	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
3236	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
3255	Manchester	Visual Inspection	Paid	0	0	0			
3258	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3262	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3269	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3272	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
3275	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3280	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3306	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Curtain or French Drain
3309	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1539	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
1547	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1588	Manchester	Visual Inspection	Paid	0	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Gutters
1604	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
1611	Manchester	Visual Inspection	Paid	0	0	0			
1614	Manchester	Visual Inspection	Paid	0	0	0			
1647	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
1662	Manchester	Petrographic Analysis	Paid	1	1	2.58	Don't know	Floor and walls both	Gutters;Finished Basement
1670	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1689	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1692	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1767	Manchester	Visual Inspection	Paid	0	0	0			
1784	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1786	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1790	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1807	Manchester	Visual Inspection	Paid	1	0	0		Concrete floor only	Gutters
1833	Manchester	Visual Inspection	Paid	0	0	0			
2150	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2204	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2222	Manchester	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2223	Manchester	Petrographic Analysis	Paid	1	1	55	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2275	Manchester	Visual Inspection	Denied	0	0	0			
2297	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
2300	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2312	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
2315	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2357	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2377	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
2393	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
604	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
611	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
613	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
615	Manchester	Visual Inspection	Paid	0	0	0			
617	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
622	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
649	Manchester	Visual Inspection	Paid	0	0	0			
666	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
674	Manchester	Visual Inspection	Paid	0	0	0			Gutters
678	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
692	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
696	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
699	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
726	Manchester	Visual Inspection	Paid	0	0	0			
730	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
731	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
745	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
750	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
751	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
752	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
755	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
761	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
763	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
771	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
778	Manchester	Petrographic Analysis	Paid	0	1	2			
785	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
786	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
788	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
794	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
801	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
835	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
3679	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
3680	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3682	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3739	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3741	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3743	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3749	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3751	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3825	Manchester	Visual Inspection	Paid	0	0	0			
3846	Manchester	Visual Inspection	Paid	0	0	0			
3858	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
3898	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
3939	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3967	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3971	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
3978	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3982	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
53	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
54	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
61	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
65	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
71	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
75	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
144	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
176	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
182	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
183	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
195	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
200	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
218	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
222	Manchester	Visual Inspection	Paid	0	0	0			Gutters
230	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
231	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
240	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
241	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
245	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
274	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
278	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
296	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3325	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3340	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
3359	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3363	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
3371	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3373	Manchester	Visual Inspection	Paid	0	0	0			
3374	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
3403	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3410	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3414	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3425	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3448	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3449	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3577	Manchester	Visual Inspection	Paid	0	0	0			
3592	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3603	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3634	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3635	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3636	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
2752	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
2769	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2817	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2819	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2844	Manchester	Petrographic Analysis	Paid	1	1	30	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
2846	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2855	Manchester	Visual Inspection	On Hold	0	0	0			
2880	Manchester	Visual Inspection	Paid	0	0	0			
2881	Manchester	Petrographic Analysis	Paid	0	0	0			
2897	Manchester	Petrographic Analysis	Paid	1	1	2.67	Minor degradation	Wall only	Gutters;Gutters - With Extension
2908	Manchester	Visual Inspection	Denied	0	0	0			
2928	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2930	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
2945	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2949	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2951	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2960	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2976	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3008	MANCHESTER	Petrographic Analysis	Paid	0	1	1.5			Gutters;Gutters - With Extension;Finished Basement
3010	manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3025	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Curtain or French Drain
311	Manchester	Visual Inspection	Paid	0	0	0			Gutters
314	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
316	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
320	Manchester	Visual Inspection	Paid	0	0	0			
325	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
332	Manchester	Visual Inspection	Paid	0	0	0			
343	Manchester	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
352	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
368	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
374	Manchester	Visual Inspection	Paid	0	0	0			
381	Manchester	Visual Inspection	Paid	0	0	0			
394	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
403	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
405	Manchester	Visual Inspection	Paid	0	0	0			
439	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
458	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
464	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
478	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
479	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
496	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
521	Manchester	Visual Inspection	Paid	0	0	0			
543	Manchester	Visual Inspection	Paid	0	0	0			Gutters
548	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
550	Manchester	Visual Inspection	Paid	0	0	0			
551	Manchester	Visual Inspection	Paid	0	0	0			
552	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
558	Manchester	Visual Inspection	Paid	0	0	0			
569	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
572	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
579	Manchester	Visual Inspection	Paid	0	0	0			
583	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1212	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1224	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
1228	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1235	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1236	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1246	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
1258	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1281	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1294	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1301	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1306	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1307	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1309	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1317	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Capillary Break
1324	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1329	Manchester	Visual Inspection	Paid	0	0	0			
1331	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
1338	Manchester	Petrographic Analysis	Paid	1	1	68	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
1345	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
1348	Manchester	Petrographic Analysis	Paid	0	1	1.69			Gutters;Finished Basement
1353	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1371	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1388	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1425	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1429	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1441	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1454	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
1469	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1470	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
1471	Manchester	Visual Inspection	Paid	0	0	0			
1473	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1478	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1490	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1505	Manchester	Visual Inspection	Paid	0	0	0			
1511	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1517	Manchester	Visual Inspection	Paid	0	0	0			
1520	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4011	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
4017	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
4022	Manchester	Visual Inspection	Paid	0	0	0			Gutters
4029	Manchester	Visual Inspection	Paid	0	0	0			
4041	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
4067	Manchester	Visual Inspection	Paid	0	0	0			
4070	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
4074	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
4077	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
4096	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1837	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
1860	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1915	Manchester	Petrographic Analysis	Pending DoH Approval	1	1	34	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1918	Manchester	Visual Inspection	Paid	0	0	0			
1921	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1923	Manchester	Visual Inspection	Pending DoH Approval	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1954	Manchester	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1959	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1962	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1963	Manchester	Visual Inspection	Paid	0	0	0			
1966	Manchester	Petrographic Analysis	Paid	0	0	0			
1994	Manchester	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1997	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2003	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters
2028	Manchester	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
2073	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
2081	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2082	Manchester	Petrographic Analysis	Paid	1	1	2.49	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2088	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2108	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
2121	Manchester	Visual Inspection	Paid	0	0	0			
2128	Manchester	Visual Inspection	Paid	0	0	0			Gutters
Mansfield Count	129								
1869	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
1880	Mansfield	Visual Inspection	Paid	0	0	0			
1931	Mansfield	Petrographic Analysis	Paid	0	1	0.54			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1945	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
1961	Mansfield	Visual Inspection	Paid	0	0	0			
2022	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
2024	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
2031	Mansfield	Visual Inspection	Paid	0	0	0			
2035	Mansfield	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension
2040	Mansfield	Visual Inspection	Paid	0	0	0			
2046	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
2059	Mansfield	Visual Inspection	Paid	0	0	0			
2117	Mansfield	Petrographic Analysis	Paid	0	0	0			
2120	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3670	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
3677	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3701	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3703	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3727	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement
3737	Mansfield	Visual Inspection	On Hold	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3769	Mansfield	Visual Inspection	On Hold	0	0	0			
3770	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3799	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3800	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
3801	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
3818	Mansfield	Visual Inspection	Paid	0	0	0			
3820	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3850	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement;Footing Drains
3872	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3942	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3946	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3957	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
3966	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3046	Mansfield	Petrographic Analysis	Paid	0	0	0			
3074	Mansfield	Visual Inspection	Paid	0	0	0			
3102	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3131	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
3135	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3138	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3159	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3185	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3197	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3235	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3268	Mansfield	Visual Inspection	Paid	0	0	0			
3303	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
911	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
915	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
934	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
1096	Mansfield	Visual Inspection	Paid	0	0	0			
1101	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1114	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1123	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1140	Mansfield	Visual Inspection	Paid	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2468	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
2482	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2502	Mansfield	Visual Inspection	Paid	0	0	0			
2535	Mansfield	Visual Inspection	Pending DoH Approval	0	0	0			
2536	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
									Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2544	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
2620	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
									Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2731	Mansfield	Visual Inspection	Paid	0	0	0			
605	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
606	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
618	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
663	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
743	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
782	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
838	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
									Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1538	Mansfield	Visual Inspection	Paid	0	0	0			
1544	Mansfield	Visual Inspection	Paid	0	0	0			
1603	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1636	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters
1680	Mansfield	Petrographic Analysis	Paid	0	1	0.52			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
1717	Mansfield	Petrographic Analysis	Paid	0	1	0.68			Gutters;Finished Basement
1732	Mansfield	Visual Inspection	Paid	0	0	0			
1735	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1755	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1802	Mansfield	Petrographic Analysis	Paid	0	1	0			Gutters
1831	Mansfield	Visual Inspection	Denied	0	0	0			
2146	Mansfield	Petrographic Analysis	Paid	0	0	0			
2153	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2185	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2206	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2350	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
4019	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4035	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
4058	Mansfield	Visual Inspection	Paid	0	0	0			
2750	Mansfield	Visual Inspection	Paid	0	0	0			
2775	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2779	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2894	Mansfield	Visual Inspection	Paid	0	0	0			
2909	Mansfield	Petrographic Analysis	Paid	0	0	0			
2968	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
13	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
69	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
72	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
90	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
191	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3393	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3424	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3521	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3534	Mansfield	Visual Inspection	Paid	0	0	0			
3545	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3547	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3580	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
3584	Mansfield	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
3624	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3628	Mansfield	Visual Inspection	Paid	0	0	0			
1251	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
1257	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
1289	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1323	Mansfield	Visual Inspection	Paid	0	0	0			
1373	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
1375	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
1456	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1477	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
370	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
408	Mansfield	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
411	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
470	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
517	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
523	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
524	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
525	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
545	Mansfield	Visual Inspection	Paid	0	0	0			
590	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
595	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
596	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
598	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
Mansfield Center Count	7								
1686	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1774	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
1916	Mansfield Center	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Finished Basement
807	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
940	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2767	Mansfield Center	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
3646	Mansfield Center	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Marlborough Count	9								
350	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
3145	Marlborough	Visual Inspection	Pending DoH Approval	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3767	Marlborough	Visual Inspection	Pending DoH Approval	0	0	0			
2933	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2980	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3009	Marlborough	Visual Inspection	Paid	0	0	0			Gutters
2213	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1000	Marlborough	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains
1104	Marlborough	Petrographic Analysis	Paid	0	0	0			Gutters
Middletown Count	2								
2277	Middletown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2341	Middletown	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
New Haven Count	1								
3044	New Haven	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
Newington Count	2								
2210	Newington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2955	Newington	Visual Inspection	Paid	0	0	0			Finished Basement
Northford Count	1								
2755	Northford	Visual Inspection	Pending DoH Approval	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
Norwich Count	1								
3899	Norwich	Visual Inspection	Paid	0	0	0			
Plainfield Count	1								
746	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
Plantsville Count	1								
1043	Plantsville	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
Pomfret Count	3								
2660	Pomfret	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
2661	Pomfret	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
2329	Pomfret	Visual Inspection	Paid	0	0	0			Gutters
Portland Count	6								
2260	Portland	Visual Inspection	Paid	0	0	0			Gutters
2307	Portland	Visual Inspection	Paid	0	0	0			Finished Basement
980	Portland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
578	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
3358	Portland	Visual Inspection	Paid	0	0	0			Gutters
2045	Portland	Visual Inspection	Paid	0	0	0			
Rocky Hill Count	4								
3180	Rocky Hill	Visual Inspection	On Hold	0	0	0			
1785	Rocky Hill	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
3934	Rocky Hill	Visual Inspection	Paid	0	0	0			
836	Rocky Hill	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
S Glastonbury Count	1								
2593	S Glastonbury	Visual Inspection	Paid	0	0	0			
Simsbury Count	1								
1374	Simsbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Somers Count	142								
1207	Somers	Petrographic Analysis	Paid	0	1	1.33			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1255	Somers	Visual Inspection	Paid	0	0	0			Gutters
1266	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
1284	Somers	Visual Inspection	Paid	0	0	0			Gutters
1316	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
1396	Somers	Petrographic Analysis	Paid	0	1	2			Gutters
1455	Somers	Visual Inspection	Paid	0	0	0			Gutters
1512	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1599	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
1606	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
1669	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1678	Somers	Petrographic Analysis	Paid	0	1	1.31			Gutters;Gutters - With Extension;Finished Basement
1693	Somers	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Footing Drains
1698	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
1704	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
1748	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1749	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1756	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1789	Somers	Visual Inspection	Paid	0	0	0			
1799	Somers	Petrographic Analysis	Paid	1	1	16	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
1832	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3321	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3335	Somers	Visual Inspection	Denied	0	0	0			Gutters
3362	Somers	Visual Inspection	Paid	0	0	0			
3365	Somers	Visual Inspection	Paid	0	0	0			
3368	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
3392	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3434	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3532	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3533	Somers	Visual Inspection	Paid	0	0	0			
3555	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3556	Somers	Visual Inspection	Paid	0	0	0			Footing Drains;Curtain or French Drain
3563	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3570	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3574	Somers	Visual Inspection	Paid	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3581	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
977	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
1050	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1064	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1174	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
2162	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
2214	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2219	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
2221	Somers	Visual Inspection	Paid	0	0	0			
2233	Somers	Visual Inspection	Paid	0	0	0			
2266	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2276	Somers	Visual Inspection	Paid	0	0	0			
2321	Somers	Petrographic Analysis	Denied	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2322	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2323	Somers	Petrographic Analysis	Paid	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2327	Somers	Petrographic Analysis	Paid	0	0	0			
2368	Somers	Petrographic Analysis	Paid	0	0	0			Gutters
2371	Somers	Petrographic Analysis	Paid	0	1	0.92			Gutters;Finished Basement
2375	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2384	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
2390	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2396	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2407	Somers	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
3035	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3053	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3065	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3129	Somers	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension
3130	Somers	Visual Inspection	Paid	0	0	0			Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3133	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
3163	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3183	Somers	Visual Inspection	Paid	0	0	0			Gutters
3222	Somers	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
3261	Somers	Visual Inspection	Paid	0	0	0			Gutters
3274	Somers	Petrographic Analysis	Paid	0	1	2.37			Gutters;Finished Basement;Footing Drains
3302	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
346	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
369	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
377	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
447	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
500	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
587	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
597	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1873	Somers	Petrographic Analysis	Paid	0	1	0.48			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1881	Somers	Visual Inspection	Paid	0	0	0			
1888	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
1928	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1955	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
1989	Somers	Petrographic Analysis	Paid	0	1	2			Gutters;Finished Basement
2002	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2007	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2089	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2129	Somers	Visual Inspection	Paid	0	0	0			Gutters
2434	Somers	Petrographic Analysis	Paid	0	1	0.79			Gutters;Gutters - With Extension;Finished Basement
2459	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2461	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
2471	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2489	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2510	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2515	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2516	Somers	Petrographic Analysis	Paid	0	1	0.63			Waterproofing - Exterior;Gutters;Curtain or French Drain
2519	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
2586	Somers	Petrographic Analysis	Paid	1	1	0.54	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2647	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2679	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2703	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2709	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
625	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
627	Somers	Petrographic Analysis	Paid	0	1	0			
652	Somers	Petrographic Analysis	Paid	0	0	0			
661	Somers	Visual Inspection	Paid	0	0	0			
724	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
845	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
894	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
3675	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Finished Basement
3683	Somers	Visual Inspection	Paid	0	0	0			
3691	Somers	Petrographic Analysis	On Hold	0	1	0.65			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3706	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3750	Somers	Visual Inspection	Paid	0	0	0			Gutters
3810	Somers	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Capillary Break
3815	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
3842	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3879	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
3880	Somers	Visual Inspection	Paid	0	0	0			
3883	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3884	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3963	Somers	Visual Inspection	Paid	0	0	0			
3976	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4038	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
4052	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
4068	Somers	Petrographic Analysis	Paid	0	1	1.51			Gutters
4090	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2760	Somers	Petrographic Analysis	Paid	1	1	0.64	Minor degradation	Floor and walls both	Gutters;Finished Basement
2761	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
2793	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2837	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2841	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Footing Drains
2842	Somers	Petrographic Analysis	Paid	1	1	1.32	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
2843	Somers	Petrographic Analysis	Paid	0	1	1.32			Gutters;Finished Basement;Curtain or French Drain
2905	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
2924	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2941	Somers	Visual Inspection	Paid	0	0	0			Gutters
2956	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement
2990	Somers	Visual Inspection	Paid	0	0	0			
162	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
173	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
256	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
273	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
South Glastonbury Count	7								
3526	South Glastonbury	Visual Inspection	Paid	0	0	0			
3656	South Glastonbury	Petrographic Analysis	Paid	1	1	35	Don't know	Wall only	
1579	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3256	South Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
2409	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2988	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2993	South Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
South Windsor Count	520								
2748	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2781	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2786	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2788	South Windsor	Visual Inspection	Paid	0	0	0			
2794	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
2795	South Windsor	Visual Inspection	Paid	0	0	0			
2796	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2801	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2807	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2811	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2814	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
2828	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2839	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2847	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2850	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2854	South Windsor	Visual Inspection	Paid	0	0	0			
2872	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2900	South Windsor	Visual Inspection	Paid	0	0	0			
2901	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2911	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2912	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
2954	South Windsor	Visual Inspection	Paid	0	0	0			
2962	South Windsor	Visual Inspection	Paid	0	0	0			
2965	South Windsor	Visual Inspection	Paid	0	0	0			
2984	South Windsor	Petrographic Analysis	Paid	0	1	0.45			Gutters;Gutters - With Extension;Finished Basement
2992	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
2999	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3006	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3015	South Windsor	Visual Inspection	Denied	0	0	0			Finished Basement
3017	South windsor	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	
3020	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3024	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3026	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3036	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3039	South Windsor	Visual Inspection	Paid	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3040	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3048	South Windsor	Visual Inspection	Paid	0	0	0			
3049	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
3072	South Windsor	Visual Inspection	Paid	0	0	0			
3081	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3083	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3096	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3103	South Windsor	Visual Inspection	Paid	0	0	0			
3122	South Windsor	Visual Inspection	Paid	0	0	0			
3128	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3132	South Windsor	Visual Inspection	Paid	0	0	0			
3134	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
3141	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters
3152	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
3155	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3160	South Windsor	Visual Inspection	Paid	0	0	0			
3162	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3170	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
3172	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
3174	South Windsor	Petrographic Analysis	Paid	0	1	1.81			Gutters;Gutters - With Extension;Finished Basement
3191	South Windsor	Visual Inspection	Paid	0	0	0			
3201	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters - With Extension;Finished Basement
3213	South Windsor	Visual Inspection	Paid	0	0	0			
3214	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3219	South Windsor	Petrographic Analysis	Paid	0	1	86			Waterproofing - Exterior;Gutters
3232	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
3242	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3245	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3246	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3247	South Windsor	Visual Inspection	Paid	0	0	0			
3270	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3271	South Windsor	Visual Inspection	Paid	0	0	0			
3282	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3284	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
3288	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3298	South Windsor	Visual Inspection	Paid	0	0	0			
8	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
22	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
27	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
29	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
67	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
77	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
89	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
96	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
102	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
124	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
130	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
134	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
135	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
146	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
147	South Windsor	Visual Inspection	Paid	0	0	0			
158	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
167	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
168	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
199	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
212	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
215	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
227	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
229	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
232	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
237	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
271	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
272	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
275	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
280	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
281	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
283	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
285	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
288	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1213	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
1218	South Windsor	Petrographic Analysis	Paid	0	1	0.63			Gutters;Gutters - With Extension;Finished Basement
1234	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1238	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1240	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1252	South Windsor	Visual Inspection	Paid	0	0	0			
1259	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1260	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1268	South Windsor	Petrographic Analysis	Paid	1	1	23	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
1280	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1283	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
1291	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1293	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1310	South Windsor	Visual Inspection	Paid	0	0	0			
1311	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1328	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1330	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1346	South Windsor	Visual Inspection	Paid	0	0	0			
1349	South Windsor	Petrographic Analysis	Paid	0	1	38			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1384	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1385	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1392	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1417	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1420	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1427	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
1451	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1464	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1468	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
1488	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1493	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1506	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1508	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
1526	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
326	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
328	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
334	South Windsor	Visual Inspection	Denied	0	0	0			
344	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
364	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
392	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
393	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
426	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
428	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
430	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
437	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
443	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
446	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
449	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
453	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
475	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
482	South Windsor	Visual Inspection	Paid	0	0	0			
485	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
513	South Windsor	Visual Inspection	Paid	0	0	0			
520	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
530	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
531	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
555	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
571	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
575	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
586	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
601	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
1540	South Windsor	Petrographic Analysis	Paid	0	1	2.37			Gutters;Gutters - With Extension;Finished Basement
1548	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1549	South Windsor	Petrographic Analysis	Paid	0	0	0			
1561	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1563	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
1570	South Windsor	Visual Inspection	Paid	0	0	0			
1571	South Windsor	Petrographic Analysis	Paid	0	1	0.76			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1584	South Windsor	Petrographic Analysis	Paid	0	1	33			Gutters;Gutters - With Extension
1595	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1597	South Windsor	Visual Inspection	Paid	0	0	0			
1610	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1612	South Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Curtain or French Drain
1624	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1626	South Windsor	Petrographic Analysis	Paid	0	1	0		Floor and walls both	Gutters
1627	South Windsor	Petrographic Analysis	Paid	1	1	1.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
1640	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1642	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1649	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1653	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1659	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
1661	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1663	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1665	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1668	South Windsor	Visual Inspection	Paid	0	0	0			
1674	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1677	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1681	South Windsor	Petrographic Analysis	Paid	0	0	0			
1685	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1690	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1695	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1702	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1712	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1731	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1739	South Windsor	Visual Inspection	Paid	0	0	0			
1740	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1743	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1744	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1752	South Windsor	Petrographic Analysis	Paid	0	1	26			Waterproofing - Exterior;Gutters;Footing Drains
1754	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
1765	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1766	South Windsor	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1769	South Windsor	Visual Inspection	Paid	0	0	0			
1771	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
1775	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1777	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
1780	South Windsor	Visual Inspection	Denied	0	0	0			Gutters
1783	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1787	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1792	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
1809	South Windsor	Petrographic Analysis	Paid	1	1	0.48	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1819	South Windsor	Visual Inspection	Paid	0	0	0			
1820	South Windsor	Petrographic Analysis	Paid	0	0	0			
1823	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1827	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Finished Basement
902	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
909	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
913	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
927	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
941	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
945	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
965	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
968	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
969	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
978	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
991	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
998	South Windsor	Visual Inspection	Paid	0	0	0			
999	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
1003	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1010	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
1026	South Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
1061	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1063	South Windsor	Visual Inspection	Paid	1	0	0			
1080	South Windsor	Petrographic Analysis	Paid	0	1	28			Gutters

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1086	South Windsor	Petrographic Analysis	Paid	1	1	29	Don't know	Floor and walls both	Gutters;Gutters - With Extension
1093	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1098	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1111	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1117	South Windsor	Petrographic Analysis	Paid	1	1	0.99	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1130	South Windsor	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1138	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1142	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1147	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
1159	South Windsor	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Capillary Break;Footing Drains;Curtain or French Drain
1165	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1168	South Windsor	Petrographic Analysis	Denied	0	1	2			Waterproofing - Exterior;Gutters;Finished Basement
1171	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1182	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1190	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
1195	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3326	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3331	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
3337	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3351	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3352	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3367	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
3372	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3388	South Windsor	Visual Inspection	Paid	0	0	0			
3391	South Windsor	Visual Inspection	Paid	0	0	0			
3399	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3409	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3418	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3426	South Windsor	Visual Inspection	Paid	0	0	0			
3430	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3433	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3446	South Windsor	Visual Inspection	Paid	0	0	0			
3452	South Windsor	Visual Inspection	Paid	0	0	0	Minor degradation	Wall only	Gutters;Footing Drains
3507	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3510	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Finished Basement
3513	South Windsor	Visual Inspection	Paid	0	0	0			
3543	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3558	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3559	South Windsor	Visual Inspection	Paid	0	0	0			
3562	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3564	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3575	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3579	South Windsor	Visual Inspection	Paid	0	0	0			
3591	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3594	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
3595	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
3600	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
3613	South Windsor	Visual Inspection	Paid	0	0	0			
3632	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
3643	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3651	South Windsor	Visual Inspection	Paid	0	0	0			
3663	South Windsor	Visual Inspection	Paid	0	0	0			
3664	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2138	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2142	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2157	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2170	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2171	South Windsor	Visual Inspection	Paid	0	0	0			
2174	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2183	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2205	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2212	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2246	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2247	South Windsor	Petrographic Analysis	Paid	1	1	30	No visible signs		Gutters;Gutters - With Extension;Footing Drains
2250	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2259	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2263	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2264	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2268	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2270	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2283	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
2298	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2301	South Windsor	Petrographic Analysis	Paid	0	1	11			Gutters
2308	South Windsor	Petrographic Analysis	Paid	0	1	0.77			Gutters;Finished Basement
2348	South Windsor	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Interior;Gutters;Finished Basement
2355	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2358	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2365	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
2369	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
2372	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Finished Basement
2374	South Windsor	Visual Inspection	Paid	0	0	0			
2376	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2387	South Windsor	Visual Inspection	Paid	0	0	0			
2388	South Windsor	Visual Inspection	Paid	0	0	0			
2389	South Windsor	Visual Inspection	Denied	0	0	0			
2400	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2406	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2408	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2425	South Windsor	Visual Inspection	Paid	0	0	0			Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
612	South Windsor	Visual Inspection	Paid	0	0	0			
619	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
626	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
635	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
643	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
659	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
662	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
668	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
698	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
712	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
766	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
792	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
803	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement
808	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
814	South Windsor	Petrographic Analysis	Paid	0	0	0			
820	South Windsor	Visual Inspection	Paid	0	0	0			
837	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
842	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
844	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
846	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
847	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
848	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
849	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
850	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
851	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
852	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
853	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
854	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
855	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
856	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
857	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
858	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
859	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
860	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
861	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
862	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
863	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
864	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
865	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
866	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
867	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
868	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
869	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
870	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
871	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
872	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
873	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
888	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
890	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
892	South Windsor	Visual Inspection	Paid	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1859	South Windsor	Petrographic Analysis	Paid	0	1	43			Waterproofing - Exterior;Gutters;Finished Basement
1867	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1868	South Windsor	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1874	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
1876	South Windsor	Visual Inspection	Paid	0	0	0			
1878	South Windsor	Petrographic Analysis	Paid	0	0	0			
1879	South Windsor	Visual Inspection	Paid	0	0	0			
1886	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1889	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Curtain or French Drain
1896	South Windsor	Visual Inspection	Paid	0	0	0			
1900	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1906	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
1909	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1913	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1933	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1934	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
1946	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1947	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1948	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1949	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
1956	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1960	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1971	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1975	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1991	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1996	South Windsor	Petrographic Analysis	Paid	0	1	0.4			Gutters;Finished Basement
2017	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2036	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2049	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2052	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2058	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
2061	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2063	South Windsor	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
2069	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2077	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
2078	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2083	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2097	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2127	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2130	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2431	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
2433	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2437	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
2439	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
2440	South Windsor	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2452	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
2454	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2462	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2473	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2478	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2483	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2484	South Windsor	Petrographic Analysis	Paid	0	1	0.8			
2487	South Windsor	Petrographic Analysis	Paid	1	1	1.67	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
2488	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
2507	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2509	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2511	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters
2517	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2522	South Windsor	Petrographic Analysis	Paid	0	1	1.35			Waterproofing - Exterior;Gutters
2537	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Finished Basement
2552	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2554	South Windsor	Visual Inspection	Paid	0	0	0			
2585	South Windsor	Visual Inspection	Paid	0	0	0			
2592	South Windsor	Petrographic Analysis	Paid	0	1	1.33			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
2596	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2604	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2618	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2619	South Windsor	Petrographic Analysis	Paid	1	1	3.22	Don't know	Wall only	Gutters;Curtain or French Drain
2621	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2622	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2627	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2628	South Windsor	Petrographic Analysis	Paid	1	1	2.96	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2630	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2635	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
2638	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2644	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
2666	South Windsor	Petrographic Analysis	Paid	0	0	0			
2667	South Windsor	Petrographic Analysis	Denied	0	0	0			
2678	South Windsor	Visual Inspection	Paid	0	0	0			
2693	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2694	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
2697	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2712	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2716	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
2719	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2724	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2728	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2729	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2742	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2745	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3990	South Windsor	Visual Inspection	Paid	0	0	0			
4020	South Windsor	Visual Inspection	Paid	0	0	0			
4025	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4026	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4031	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
4046	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
4047	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4050	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
4069	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4071	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
4072	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4073	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4080	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4091	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
4100	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			
3688	South Windsor	Visual Inspection	On Hold	0	0	0			
3711	South Windsor	Visual Inspection	Paid	0	0	0			
3718	South Windsor	Visual Inspection	Paid	0	0	0			
3723	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
3735	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3738	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3740	South Windsor	Visual Inspection	Paid	0	0	0			
3744	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
3748	South Windsor	Petrographic Analysis	Paid	1	1	39	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3764	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
3768	South Windsor	Visual Inspection	Paid	0	0	0			
3777	South Windsor	Visual Inspection	Paid	0	0	0			
3778	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3802	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3803	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
3804	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
3816	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3821	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3822	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3829	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3830	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3836	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3837	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3862	South Windsor	Visual Inspection	Paid	1	0	0		Wall only	
3888	South Windsor	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3891	South Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension
3892	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
3900	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3909	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3918	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3919	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3923	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
3928	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3938	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3943	South Windsor	Visual Inspection	Paid	0	0	0			
3958	South Windsor	Visual Inspection	Paid	0	0	0			
3960	South Windsor	Visual Inspection	Paid	0	0	0			
3972	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
3987	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
South Windssor Count	1								
1421	South Windssor	Visual Inspection	Paid	0	0	0			Gutters
Southington Count	2								
3602	Southington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3623	Southington	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
Stafford Count	199								
3355	Stafford	Visual Inspection	Paid	0	0	0			
3364	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains
3378	Stafford	Visual Inspection	Paid	0	0	0			Gutters
3389	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3419	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
3443	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3447	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3509	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3542	Stafford	Visual Inspection	Paid	0	0	0			Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3586	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3608	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
3616	Stafford	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3617	Stafford	Visual Inspection	Paid	1	0	0		Floor and walls both	
3625	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3639	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
3648	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3707	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3757	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
3849	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
3857	Stafford	Visual Inspection	On Hold	0	0	0			
3885	Stafford	Visual Inspection	Paid	0	0	0			
3940	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3949	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3981	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
33	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
39	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
48	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
117	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
125	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
129	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
136	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
170	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
177	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
186	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
188	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
194	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
203	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
207	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
209	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
211	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
214	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
226	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
238	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
248	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
266	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
293	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
294	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2813	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2861	Stafford	Visual Inspection	Paid	1	0	0		Wall only	Gutters;Finished Basement
2871	Stafford	Visual Inspection	Paid	0	0	0			
2886	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2887	Stafford	Visual Inspection	Paid	1	0	0			
2958	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2964	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
3000	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3043	Stafford	Visual Inspection	Paid	0	0	0			
3070	Stafford	Petrographic Analysis	Paid	0	1	2.18			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3076	Stafford	Visual Inspection	Paid	0	0	0			Gutters
3084	Stafford	Visual Inspection	On Hold	0	0	0			Gutters;Footing Drains

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3105	Stafford	Visual Inspection	Paid	0	0	0			Gutters
3112	Stafford	Visual Inspection	Paid	0	0	0			
922	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
956	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
967	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
981	Stafford	Petrographic Analysis	Paid	0	0	0			
1037	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1049	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1126	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
1146	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1537	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1564	Stafford	visual	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1583	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
1585	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1589	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
1594	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains;Curtain or French Drain
1602	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
1613	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1643	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1672	Stafford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1682	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1684	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
1687	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1691	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
1708	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1737	Stafford	Petrographic Analysis	Paid	1	1	1.81	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1747	Stafford	Petrographic Analysis	Paid	1	1	0.81	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1810	Stafford	Petrographic Analysis	Denied	0	0	0			Gutters
360	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
361	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
382	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
383	Stafford	Visual Inspection	Paid	1	0	0			
385	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
409	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
410	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
413	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
416	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
421	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
431	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
456	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
461	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
471	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
474	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
477	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
486	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
492	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
497	Stafford	Visual Inspection	Paid	0	0	0			Gutters
499	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
502	Stafford	Visual Inspection	Paid	0	0	0			
505	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
510	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
527	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
589	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1244	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
1271	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1313	Stafford	Petrographic Analysis	Paid	1	1	29	No visible signs		Waterproofing - Exterior
1430	Stafford	Petrographic Analysis	Paid	0	1	43			
1440	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
1446	Stafford	Visual Inspection	Paid	0	0	0			Gutters
1450	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
1452	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
1453	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1474	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1479	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1480	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Footing Drains
1496	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
1507	Stafford	Petrographic Analysis	Paid	0	0	0			
1513	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1515	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1516	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3998	Stafford	Visual Inspection	Paid	0	0	0			
4007	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
4049	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
4057	Stafford	Petrographic Analysis	Paid	0	0	0			
4061	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
4081	Stafford	Visual Inspection	Paid	0	0	0			Gutters
4084	Stafford	Visual Inspection	Paid	0	0	0			
614	Stafford	Visual Inspection	Paid	0	0	0			
620	Stafford	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
624	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
630	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
634	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
639	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
647	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
658	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
735	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
737	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
754	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
759	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
772	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
780	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2155	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
2164	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2166	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters
2181	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
2186	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2226	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2232	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2234	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2304	Stafford	Visual Inspection	Paid	0	0	0			
2319	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2328	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2392	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2399	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2401	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2449	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2458	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2465	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2480	Stafford	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2495	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2499	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2501	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2504	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2540	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2546	Stafford	Visual Inspection	Paid	1	0	0	No visible signs		Finished Basement
2549	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
2561	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
2600	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2655	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
2710	Stafford	Visual Inspection	Paid	0	0	0			
1929	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1935	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
1938	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
1952	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Footing Drains
1958	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
1964	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
1973	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2010	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2011	Stafford	Petrographic Analysis	Paid	1	1	1.3	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
2015	Stafford	Petrographic Analysis	Paid	0	1	1			Gutters

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2023	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2032	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2037	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2051	Stafford	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
2067	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2072	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2084	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2103	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
2111	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2126	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Stafford Springs Count	1								
3893	Stafford Springs	Petrographic Analysis	Paid	1	1	2.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
STAFFORD SPGS Count	1								
2467	STAFFORD SPGS	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Stafford Springs Count	49								
2738	Stafford Springs	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1969	Stafford Springs	Visual Inspection	Paid	0	0	0			
1999	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2029	Stafford Springs	Petrographic Analysis	Paid	1	1	3.16	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2030	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
1617	Stafford Springs	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1676	Stafford Springs	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
1821	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3381	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3524	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
914	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
974	Stafford Springs	Petrographic Analysis	Paid	1	1	23	Don't know	Floor and walls both	Gutters - With Extension
1044	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1062	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1081	stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1089	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1115	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
1143	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
1158	Stafford Springs	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement;Curtain or French Drain
3001	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3002	Stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3003	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
3004	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
3013	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3101	Stafford springs	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
3106	Stafford Springs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3254	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
4076	Stafford Springs	Visual Inspection	On Hold	1	0	0	Don't know	Wall only	Gutters;Finished Basement
4095	Stafford Springs	Visual Inspection	Approved - Pending Payment	0	0	0			
4107	Stafford Springs	Visual Inspection	On Hold	0	0	0			Finished Basement
1198	Stafford Springs	Petrographic Analysis	Paid	0	0	0			
1199	Stafford Springs	Petrographic Analysis	Paid	1	1	0		Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
1292	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Curtain or French Drain
1379	Stafford Springs	Petrographic Analysis	Paid	1	1	94	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1419	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1445	Stafford Springs	Petrographic Analysis	Paid	0	1	32			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1472	Stafford Springs	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Footing Drains
1500	STAFFORD Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2163	Stafford Springs	Petrographic Analysis	Paid	1	1	1.05	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2189	STAFFORD SPRINGS	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
2251	Stafford springs	Visual Inspection	Paid	0	0	0			Gutters
2310	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
2330	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2363	stafford springs	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
2421	Stafford Springs	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	
765	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
827	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
828	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
830	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
Stafford Springs, Count		1							
1504	Stafford Springs,	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Staffordville Count		1							
3535	Staffordville	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Stamford Count		1							
3786	Stamford	Visual Inspection	Pending DoH Approval	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
Storrs Count		4							
2070	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3627	Storrs	Visual Inspection	Paid	0	0	0			Gutters
757	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
3184	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
Storrs Mansfield Count		7							
2823	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2974	Storrs Mansfield	Visual Inspection	Paid	0	0	0			
942	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1074	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.57			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
632	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
1982	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.43			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
2279	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Storrs-Mansfield Count	1								
2019	Storrs-Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
Suffield Count	66								
2079	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2746	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2747	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			
2825	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2875	Suffield	Visual Inspection	Paid	0	0	0			Gutters
2882	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
2890	Suffield	Visual Inspection	Paid	0	0	0			
2910	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3007	Suffield	Visual Inspection	Denied	0	0	0			
1248	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1270	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2447	Suffield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2464	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2683	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2701	Suffield	Petrographic Analysis	Paid	0	0	0			
2733	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
15	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3038	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
3041	Suffield	Visual Inspection	Denied	0	0	0			Gutters
3050	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3223	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3237	Suffield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
3281	Suffield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1534	Suffield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1535	Suffield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1541	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1806	Suffield	Visual Inspection	Paid	0	0	0			
3713	Suffield	Visual Inspection	Paid	0	0	0			
3779	Suffield	Petrographic Analysis	Paid	1	1	70	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3792	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3793	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3794	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3795	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3796	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3797	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3798	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3805	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3930	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2173	Suffield	Visual Inspection	Paid	0	0	0			
2184	Suffield	Petrographic Analysis	Paid	0	0	0			
2280	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2347	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
2397	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
2416	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2417	Suffield	Petrographic Analysis	Paid	0	0	0			
910	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
976	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1007	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1149	Suffield	Visual Inspection	Paid	0	0	0			
1169	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters - With Extension

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
380	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
396	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
397	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
398	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
459	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
507	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
556	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
580	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3394	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3450	Suffield	Visual Inspection	Paid	0	0	0			Gutters
3607	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3652	Suffield	Visual Inspection	On Hold	0	0	0			
3662	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
804	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
805	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
4045	Suffield	Visual Inspection	Paid	0	0	0			Gutters
Thompson Count	1								
918	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Count	724								
903	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
905	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
929	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
931	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
932	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
936	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
939	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
944	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
952	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
958	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
960	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
972	Tolland	Petrographic Analysis	Paid	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
973	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
979	Tolland	Petrographic Analysis	Paid	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
985	Tolland	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
986	Tolland	Visual Inspection	Paid	0	0	0			
992	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
1001	Tolland	Petrographic Analysis	Paid	0	0	0			
1009	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1015	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1016	Tolland	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
1018	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1031	Tolland	Visual Inspection	Paid	0	0	0			
1033	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1039	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1041	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains
1045	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1060	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1067	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1070	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
1072	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1077	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
1079	Tolland	Petrographic Analysis	Paid	1	1	1.21	No visible signs		Gutters
1083	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
1091	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1099	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1100	Tolland	Petrographic Analysis	Paid	1	1	0			
1105	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1109	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1110	Tolland	Petrographic Analysis	Paid	0	1	0.89			Waterproofing - Exterior;Gutters;Footing Drains
1116	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
1120	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1122	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1127	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1129	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
1131	Tolland	Visual Inspection	Paid	0	0	0			
1148	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1150	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
1156	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1157	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1162	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1164	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
1172	Tolland	Visual Inspection	Denied	0	0	0			Gutters - With Extension;Curtain or French Drain
1173	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1175	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
1176	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1183	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1184	Tolland	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1186	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1188	Tolland	Petrographic Analysis	Paid	1	1	1.61	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
1189	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
1191	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
1194	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1196	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1532	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1546	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1566	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
1567	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1568	Tolland	Petrographic Analysis	Paid	1	1	51	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1572	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
1573	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
1582	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
1590	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1591	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1596	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1600	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1608	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1615	Tolland	Visual Inspection	Paid	0	0	0			
1619	Tolland	Petrographic Analysis	Paid	1	1	0.81	Don't know	Wall only	Waterproofing - Exterior;Gutters
1623	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
1632	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1637	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1638	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1639	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1644	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1646	Tolland	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
1651	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
1652	Tolland	Visual Inspection	Paid	0	0	0			
1657	Tolland	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1660	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1664	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
1666	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1675	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1694	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1697	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1705	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1706	Tolland	Petrographic Analysis	Paid	1	1	70	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1713	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1714	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1726	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1730	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1733	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
1734	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1736	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1738	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1741	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1746	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
1750	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1757	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
1781	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1795	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1801	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Curtain or French Drain
1803	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1808	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
1812	Tolland	Visual Inspection	Paid	0	0	0			
1816	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1817	Tolland	Petrographic Analysis	Denied	1	1	46	Minor degradation	Wall only	Finished Basement;Footing Drains
1824	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1830	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1204	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
1205	Tolland	Visual Inspection	Paid	0	0	0			
1214	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1215	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1217	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1225	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1242	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1247	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1249	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1263	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1264	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1265	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1273	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1275	Tolland	Petrographic Analysis	Paid	1	1	2.88	Minor degradation	Floor and walls both	Gutters;Finished Basement
1277	Tolland	Petrographic Analysis	Paid	0	1	0.78			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1282	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1285	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1286	Tolland	Petrographic Analysis	Paid	0	1	1.49			Curtain or French Drain
1288	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
1296	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1298	Tolland	Visual Inspection	Paid	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1299	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
1318	Tolland	Petrographic Analysis	Paid	0	1	0.81			Gutters;Gutters - With Extension
1327	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1334	Tolland	Petrographic Analysis	Paid	0	1	28			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1335	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
1337	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1340	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
1350	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1372	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1377	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1389	Tolland	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1390	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1393	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1398	Tolland	Petrographic Analysis	Paid	0	0	0			
1422	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
1423	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1431	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1442	Tolland	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1448	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1449	Tolland	Visual Inspection	Paid	0	0	0			
1461	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1463	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1465	Tolland	Visual Inspection	Paid	1	0	0	Don't know		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1476	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
1519	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1523	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1834	Tolland	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
1853	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1854	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1855	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1857	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1861	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1870	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
1882	Tolland	Petrographic Analysis	Paid	1	1	34		Wall only	Waterproofing - Exterior;Gutters
1883	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters
1885	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1887	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1897	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1903	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
1904	Tolland	Petrographic Analysis	Denied	0	0	0			Gutters
1907	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
1910	Tolland	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1914	Tolland	Petrographic Analysis	Paid	1	1	0.45	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1917	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1920	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1925	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
1927	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		
1937	Tolland	Petrographic Analysis	Paid	0	0	0			
1939	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
1942	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1950	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1951	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1957	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1970	Tolland	Visual Inspection	Paid	0	0	0			
1981	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
1985	Tolland	Visual Inspection	Paid	0	0	0			
1992	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1995	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2000	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2001	Tolland	Visual Inspection	Paid	0	0	0			
2006	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2013	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2016	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2026	Tolland	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2027	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2041	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2043	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2054	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
2056	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2057	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
2064	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2066	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2068	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2071	Tolland	Visual Inspection	Paid	0	0	0			
2075	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2080	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2098	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2099	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2100	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2102	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2104	Tolland	Petrographic Analysis	Paid	1	1	73	Minor degradation	Floor and walls both	Finished Basement
2105	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
2106	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2110	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
2112	Tolland	Petrographic Analysis	Paid	0	1	0			Finished Basement
2113	Tolland	Petrographic Analysis	Paid	1	1	50	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2114	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2119	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
2124	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains
2133	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2135	Tolland	Petrographic Analysis	Denied	0	1	1.49			Waterproofing - Interior
2749	Tolland	Visual Inspection	Paid	0	0	0			
2751	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2756	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2763	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2768	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2773	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2776	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2778	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
2791	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2792	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2800	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
2802	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
2810	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2812	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2833	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2848	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
2859	Tolland	Petrographic Analysis	Paid	0	1	0.69			Gutters;Finished Basement
2860	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2870	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2874	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2876	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2902	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2903	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2923	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2926	Tolland	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
2929	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2934	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2936	Tolland	Visual Inspection	Paid	0	0	0			
2939	Tolland	Visual Inspection	Paid	0	0	0			
2940	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
2950	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
2959	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
2966	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
2967	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2971	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2977	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2981	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2983	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2987	Tolland	Visual Inspection	Paid	0	0	0			
2994	Tolland	Visual Inspection	Paid	0	0	0			
2996	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3005	Tolland	Petrographic Analysis	Paid	1	1	2.51	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
3027	Tolland	Petrographic Analysis	Paid	1	1	3.54	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
3029	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3031	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3037	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3045	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3057	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3058	Tolland	Visual Inspection	Paid	0	0	0			
3059	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3062	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3066	Tolland	Visual Inspection	Paid	0	0	0			
3067	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3068	Tolland	Petrographic Analysis	Paid	0	0	0			
3075	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters
3095	Tolland	Visual Inspection	Paid	0	0	0			
3099	Tolland	Visual Inspection	Paid	0	0	0			
3100	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3108	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3109	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3118	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3124	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3137	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3149	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3153	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3158	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3165	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
3166	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3171	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3189	Tolland	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
3195	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3198	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
3225	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3230	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3239	Tolland	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
3243	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3244	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3248	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3263	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3273	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3301	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3312	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2428	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
2432	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2446	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2455	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2457	Tolland	Petrographic Analysis	Denied	0	1	16			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2469	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2470	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
2476	Tolland	Visual Inspection	Paid	0	0	0			
2477	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2494	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2496	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2497	Tolland	Petrographic Analysis	Paid	1	1	1.09	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2512	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2533	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2545	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2560	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2588	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2589	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
2591	Tolland	Petrographic Analysis	Paid	1	1	2.06	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
2598	Tolland	Visual Inspection	Paid	0	0	0			
2599	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
2605	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
2609	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2611	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2612	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2614	Tolland	Petrographic Analysis	Paid	0	0	0			
2625	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2633	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2640	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2642	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
2643	Tolland	Visual Inspection	Paid	1	0	0			Gutters
2648	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2662	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2663	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2671	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2675	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2681	Tolland	Petrographic Analysis	Paid	0	1	0.09			Waterproofing - Exterior;Gutters;Footing Drains
2691	Tolland	Visual Inspection	Paid	0	0	0			
2695	Tolland	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2704	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
2705	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2706	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2708	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
2711	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2714	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2723	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2735	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
2739	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
3	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
5	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
6	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
7	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
10	Tolland	Visual Inspection	Paid	0	0	0			Gutters
12	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
16	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
17	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
18	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
20	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
23	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
24	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
25	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
26	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
28	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
30	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
36	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
40	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
41	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
44	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
45	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
50	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
52	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
63	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
64	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
66	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
70	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
74	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
76	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
79	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
80	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
85	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
86	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
91	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
92	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
100	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
101	Tolland	Visual Inspection	Paid	0	0	0			
103	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
109	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
114	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
115	Tolland	Visual Inspection	Paid	1	0	0			
116	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
119	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
120	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
122	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
131	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
132	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
133	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
140	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
143	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
145	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
148	Tolland	Visual Inspection	Paid	0	0	0			
149	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
155	Tolland	Visual Inspection	Paid	0	0	0			
160	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
164	Tolland	Visual Inspection	Paid	0	0	0			Gutters
172	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
175	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
178	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
179	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
185	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
187	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
189	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
190	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
196	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
197	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
202	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
204	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
208	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
210	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
216	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
219	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
220	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
224	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
225	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
228	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
239	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
242	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
244	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
246	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
249	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
250	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
251	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
252	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
254	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
255	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
258	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
265	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
267	Tolland	Visual Inspection	Paid	0	0	0			
268	Tolland	Petrographic Analysis	Paid	0	0	0			
269	tolland	Visual Inspection	Paid	0	0	0			
270	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
287	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
295	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
297	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3995	Tolland	Visual Inspection	Paid	0	0	0			Gutters
4004	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
4009	Tolland	Visual Inspection	Paid	0	0	0			

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4023	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
4043	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
4059	Tolland	Visual Inspection	Paid	0	0	0			Gutters
4078	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
4085	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
4088	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
4089	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
602	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
607	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
608	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
609	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
610	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
628	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
641	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
645	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
646	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
650	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
654	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
669	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
672	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
679	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
681	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
685	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
686	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
687	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
688	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
691	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
697	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
700	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
701	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
706	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
709	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
711	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
715	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
716	Tolland	Petrographic Analysis	Denied	1	1	74	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
732	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
740	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
741	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
747	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
758	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
764	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
768	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
769	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
770	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
773	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
781	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
783	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
795	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
796	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
797	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
798	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
818	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
819	Tolland	Petrographic Analysis	Denied	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
826	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
829	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
831	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
832	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
834	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
843	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
889	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
895	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3669	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3672	Tolland	Visual Inspection	Paid	0	0	0			
3676	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3681	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
3689	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
3696	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3716	Tolland	Visual Inspection	Paid	1	0	0			
3724	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3725	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3731	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
3732	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Wall only	
3736	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3742	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3745	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3760	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3765	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3773	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3806	Tolland	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters
3807	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters
3811	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3826	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3827	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3831	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3853	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3855	Tolland	Visual Inspection	Paid	1	0	0			
3887	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3894	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	
3896	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3904	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3905	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3908	Tolland	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3910	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3917	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3922	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3932	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3953	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3956	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3977	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3979	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
3984	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3988	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Gutters - With Extension
3989	Tolland	Petrographic Analysis	Paid	1	1	3.08	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
2137	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2144	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2145	Tolland	Visual	Denied	1	1	84	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2149	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
2152	Tolland	Visual Inspection	Paid	0	0	0			
2167	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2177	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2180	Tolland	Petrographic Analysis	Paid	1	1	1.19	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2196	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2202	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2207	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2208	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2211	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2216	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2225	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2236	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2237	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2243	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Footing Drains
2261	Tolland	Petrographic Analysis	Paid	1	1	84	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2267	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2286	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2288	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2292	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2296	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Curtain or French Drain
2299	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2313	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
2316	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2317	Tolland	Petrographic Analysis	Denied	1	1	0.42	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
2320	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2332	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2340	Tolland	Visual Inspection	Paid	0	0	0			
2344	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2346	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2349	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2354	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2359	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2360	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2361	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2370	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2378	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2381	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2382	Tolland	Petrographic Analysis	Paid	0	1	14			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2385	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2391	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
2395	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2410	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2411	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2413	Tolland	Visual Inspection	Paid	0	0	0			
2415	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
2424	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
3323	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
3327	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
3330	Tolland	Visual Inspection	Paid	0	0	0			
3338	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3369	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
3382	Tolland	Petrographic Analysis	Paid	0	1	2.07			Gutters
3385	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3390	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3404	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3417	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3422	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3423	Tolland	Visual Inspection	Paid	0	0	0			
3427	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3431	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3435	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Footing Drains
3436	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3437	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
3438	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3444	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3502	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3503	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3516	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3522	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3525	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3531	Tolland	Visual Inspection	Paid	0	0	0			
3536	Tolland	Petrographic Analysis	Paid	0	1	0.67			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3539	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3541	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3544	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3560	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
3561	Tolland	Visual Inspection	Paid	0	0	0			
3565	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3569	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3572	Tolland	Visual Inspection	Paid	0	0	0			
3573	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
3578	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3588	Tolland	Visual Inspection	Paid	0	0	0			
3590	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3596	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3609	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
3611	Tolland	Visual Inspection	Paid	0	0	0			
3619	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3633	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3638	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3653	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
3654	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3655	Tolland	Visual Inspection	Paid	0	0	0			
3661	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3665	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3667	Tolland	Visual Inspection	Paid	0	0	0			
299	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
322	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
324	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
329	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
330	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
336	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
342	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
347	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
355	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
358	Tolland	Visual Inspection	Paid	0	0	0			Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
359	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
367	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
372	Tolland	Visual Inspection	Paid	0	0	0			
384	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
391	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain
399	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
400	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
401	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
402	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
404	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
406	Tolland	Visual Inspection	Paid	0	0	0			Gutters
415	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
417	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
419	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
425	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
432	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
433	Tolland	Visual Inspection	Paid	0	0	0			
440	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
441	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
444	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
463	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
469	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
476	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
483	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
487	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
488	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
489	Tolland	Visual Inspection	Denied	0	0	0			
490	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
491	Tolland	Visual Inspection	Paid	0	0	0			Gutters
493	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
494	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
503	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
514	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
532	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
535	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters
536	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
537	Tolland	Visual Inspection	Paid	0	0	0			
539	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
542	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
544	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
546	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
559	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
563	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
564	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
565	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
568	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
570	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
577	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
581	Tolland	Visual Inspection	Paid	0	0	0			Gutters
584	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
591	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Union Count	32								
301	Union	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
2442	Union	Visual Inspection	Paid	0	0	0			Finished Basement
1437	Union	Petrographic Analysis	Paid	0	1	0.95			Waterproofing - Exterior;Footing Drains
1525	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
975	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
993	Union	Petrographic Analysis	Paid	1	1	1.8	Minor degradation	Wall only	Finished Basement
1106	Union	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1107	Union	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1113	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1805	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1829	Union	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3287	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
1984	Union	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2020	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2925	Union	Visual Inspection	Paid	0	0	0			
3318	Union	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
3319	Union	Petrographic Analysis	Denied	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
3320	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
3415	Union	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3571	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Footing Drains
689	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
742	Union	Petrographic Analysis	Paid	0	0	0			
774	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
21	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
87	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
150	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
156	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
213	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
4013	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2156	Union	Petrographic Analysis	Paid	0	1	74			Gutters;Finished Basement
2362	Union	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3771	Union	Petrographic Analysis	Paid	0	1	0.86			Gutters
Vernon Count	233								
3695	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3705	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
3715	Vernon	Visual Inspection	Paid	0	0	0			
3772	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3780	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3838	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3854	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3878	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
3890	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	
3901	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
3912	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3933	Vernon	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters
3950	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3954	Vernon	Visual Inspection	Paid	0	0	0			Gutters
1836	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1908	Vernon	Petrographic Analysis	Paid	0	0	0			
1911	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
1922	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1944	Vernon	Visual Inspection	Paid	0	0	0			Gutters
1977	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
1983	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
1986	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
1993	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2060	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2085	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2086	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2125	Vernon	Visual Inspection	Paid	0	0	0			
1201	Vernon	Petrographic Analysis	Paid	0	1	1.1			Waterproofing - Exterior;Gutters
1211	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1300	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
1315	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1320	Vernon	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
1333	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1336	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1344	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1347	Vernon	Visual Inspection	Paid	0	0	0			
1438	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1459	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1466	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1486	Vernon	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
1498	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
1524	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
298	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
300	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
306	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
315	Vernon	Visual Inspection	Paid	0	0	0			
317	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
357	Vernon	Visual Inspection	Paid	0	0	0			Gutters
376	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
387	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
427	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
429	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
435	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
460	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
472	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
518	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
526	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
533	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
540	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
541	Vernon	Visual Inspection	Paid	0	0	0			Gutters
557	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
574	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
585	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
599	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
600	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2445	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2456	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2514	Vernon	Visual Inspection	Paid	0	0	0			
2518	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2531	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2539	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2606	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
2616	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2656	Vernon	Visual Inspection	Paid	0	0	0			
2657	Vernon	Visual Inspection	Denied	0	0	0			
2664	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
2665	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
2673	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2696	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2715	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2725	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3089	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3116	Vernon	Visual Inspection	Paid	0	0	0			
3142	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3148	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3175	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
3211	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3240	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3249	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3277	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
3299	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3315	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
906	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
908	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
919	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
924	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
933	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
946	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
953	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
962	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
963	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
970	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
971	Vernon	Visual Inspection	Paid	0	0	0			
982	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1005	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
1022	Vernon	Petrographic Analysis	Paid	0	0	0			
1085	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1112	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1121	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1135	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
1178	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1181	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1185	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
1542	Vernon	Visual Inspection	Paid	0	0	0			
1580	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1607	Vernon	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1620	Vernon	Visual Inspection	Paid	0	0	0			Gutters
1630	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1656	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1699	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1773	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
1779	Vernon	Visual Inspection	Paid	0	0	0			
1818	Vernon	Visual Inspection	Denied	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1826	Vernon	Petrographic Analysis	Paid	0	1	0.83			Gutters;Gutters - With Extension;Finished Basement
2151	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2220	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2240	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2242	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2248	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
2255	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
2256	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
2274	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2278	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2295	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
2333	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
621	Vernon	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
623	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
629	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
657	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
671	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
675	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
676	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
683	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
684	Vernon	Petrographic Analysis	Denied	0	0	0			Gutters
690	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
702	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
707	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
708	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
713	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
718	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
719	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
729	Vernon	Petrographic Analysis	Paid	0	0	0			
734	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
767	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
775	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
787	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
799	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
802	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
839	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
874	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
880	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
881	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
882	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
883	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
884	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
885	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
886	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
887	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
891	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
893	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement
896	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
898	Vernon	Petrographic Analysis	Denied	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2758	Vernon	Petrographic Analysis	Paid	1	1	58	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2759	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2782	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2789	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2809	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Footing Drains
2845	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
2851	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2853	Vernon	Petrographic Analysis	Paid	1	1	2.07	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2858	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2862	Vernon	Visual Inspection	Paid	0	0	0			
2893	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2895	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2896	Vernon	Petrographic Analysis	Paid	1	1	0.5	Minor degradation	Wall only	Gutters;Finished Basement
2898	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2899	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
2913	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
2915	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2922	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2953	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2957	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2961	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2982	Vernon	Petrographic Analysis	Paid	1	1	3.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
2991	Vernon	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
3018	vernon	Petrographic Analysis	Denied	0	0	0			Gutters
3334	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3339	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3347	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3356	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3400	Vernon	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Wall only	Gutters
3416	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3453	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
3505	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3511	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3517	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3519	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3528	Vernon	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
3548	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3553	Vernon	Visual Inspection	Paid	0	0	0			
3604	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Gutters - With Extension
3612	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3642	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
4014	Vernon	Petrographic Analysis	Paid	0	0	0			
4108	Vernon	Visual Inspection	On Hold	0	0	0			
51	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
58	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
83	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
121	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
142	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
154	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
171	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
181	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
184	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
233	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
236	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
253	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
261	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
276	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
277	Vernon	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
286	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
289	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
292	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Vernon Rockville Count	2								
2005	Vernon Rockville	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3111	Vernon Rockville	Visual Inspection	Paid	0	0	0			
Voluntown Count	1								
2952	Voluntown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Waterbury Count	1								
3925	Waterbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
Waterford Count	1								
2287	Waterford	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
West Granby Count	1								
2231	West Granby	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
West Hartford Count	6								
1144	West Hartford	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
1510	West Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Finished Basement
3881	West Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3260	West Hartford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
4016	West Hartford	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3523	West Hartford	Visual Inspection	On Hold	0	0	0			Gutters
WEST WILLINGTON Count	1								
2541	WEST WILLINGTON	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Wethersfield Count	5								
2720	Wethersfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
455	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
508	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
512	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
4065	Wethersfield	Visual Inspection	Pending	0	0	0			Gutters
Willimantic Count	1								
2753	Willimantic	Visual Inspection	Paid	0	0	0			
Willington Count	185								
2757	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
2772	Willington	Visual Inspection	Paid	0	0	0			
2816	Willington	Visual Inspection	Paid	0	0	0			Gutters
2822	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2864	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
2865	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
2866	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2873	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2883	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
2892	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2917	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2918	Willington	Petrographic Analysis	Paid	1	1	0.82	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2919	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2932	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
2938	Willington	Visual Inspection	Paid	0	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Footing Drains
2942	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2946	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2975	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3011	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3996	Willington	Visual Inspection	Paid	0	0	0			
4002	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
4032	Willington	Visual Inspection	Denied	1	1	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
4033	Willington	Petrographic Analysis	Paid	0	1	1.36			Gutters;Gutters - With Extension
4037	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3709	Willington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Exterior;Gutters
3722	Willington	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
3729	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3774	Willington	Petrographic Analysis	Paid	1	1	33	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement
3788	Willington	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
3833	Willington	Visual Inspection	Paid	0	0	0			
3913	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
3929	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
3983	Willington	Visual Inspection	Paid	0	0	0			
3985	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2451	Willington	Visual Inspection	Paid	0	0	0			Gutters
2453	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Gutters - With Extension
2472	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2481	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2491	Willington	Visual Inspection	Paid	0	0	0			
2508	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2587	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
2597	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2629	Willington	Visual Inspection	Paid	0	0	0			Gutters
2699	Willington	Visual Inspection	Paid	0	0	0			
2726	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2734	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains
2737	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1835	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1898	Willington	Petrographic Analysis	Paid	1	1	0.85	Don't know	Floor and walls both	Gutters;Finished Basement
1899	Willington	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
1901	Willington	Petrographic Analysis	Paid	1	1	54	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1902	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1932	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
1940	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
1967	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
1978	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1979	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement
1987	Willington	Petrographic Analysis	Paid	0	1	1.74			Gutters;Footing Drains;Curtain or French Drain
2021	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2050	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2092	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
2093	Willington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
2094	Willington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
2095	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
2107	Willington	Petrographic Analysis	Paid	1	1	60	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2109	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2115	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2116	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2123	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
2179	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2195	Willington	Petrographic Analysis	Paid	0	1	2.42			Gutters
2228	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2239	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
2241	Willington	Petrographic Analysis	Paid	1	1	1.34	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2245	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2253	Willington	Visual Inspection	Paid	0	0	0			

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2257	Willington	Visual Inspection	Paid	0	0	0			Gutters
2273	Willington	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2306	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2309	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
2314	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2336	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2380	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2412	Willington	Visual Inspection	Paid	0	0	0			Gutters
3387	Willington	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Interior;Gutters;Finished Basement
3411	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
3506	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3520	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
3552	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3605	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
3630	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3631	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
899	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
926	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
948	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
950	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1023	Willington	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
1030	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
1032	Willington	Visual Inspection	Paid	0	0	0			Gutters
1095	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
655	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
670	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
694	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
710	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
736	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
744	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
756	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
777	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
813	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
841	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1529	Willington	Petrographic Analysis	Paid	0	1	2			Gutters;Curtain or French Drain
1560	Willington	Petrographic Analysis	Paid	0	1	0.054			Gutters;Finished Basement
1601	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Footing Drains
1625	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1629	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1648	Willington	Petrographic Analysis	Paid	0	1	1.46			Gutters;Finished Basement
1711	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
1745	Willington	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1772	Willington	Visual Inspection	Pending DoH Approval	1	0	0	No visible signs		Gutters;Finished Basement
1794	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Finished Basement
1814	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1815	Willington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters;Footing Drains
9	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
14	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
62	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
78	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
99	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
104	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
105	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
138	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
151	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
153	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
163	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
166	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
174	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
206	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
217	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior
259	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
260	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
263	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
304	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
307	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
308	Willington	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
310	Willington	Visual Inspection	Paid	0	0	0			Gutters
318	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
333	Willington	Visual Inspection	Denied	0	0	0			Gutters
337	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
354	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
362	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
365	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
366	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
371	Willington	Visual Inspection	Paid	0	0	0			
373	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
414	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
424	Willington	Visual Inspection	Denied	0	0	0			
434	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
481	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
504	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
547	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
567	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
576	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
1208	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1209	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1223	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
1256	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1269	Willington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1278	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1279	Willington	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1304	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1378	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
1381	Willington	Visual Inspection	Paid	0	0	0			Gutters
1382	Willington	Visual Inspection	Paid	0	0	0			
1418	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1433	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1460	Willington	Petrographic Analysis	Paid	0	0	0			
1491	Willington	Petrographic Analysis	Paid	1	1	2.34	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Finished Basement;Curtain or French Drain
1501	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications									
App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1528	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
3051	Willington	Visual Inspection	Paid	0	0	0			Footing Drains
3098	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
3107	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3164	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3199	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3266	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3267	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Windham Count	7								
1578	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
2632	Windham	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3370	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
3529	Windham	Visual Inspection	Paid	0	0	0			
1222	Windham	Petrographic Analysis	Paid	0	0	0			Gutters
1467	Windham	Visual Inspection	Paid	0	0	0			Gutters
2351	Windham	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
Windsor Count	10								
3671	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3962	Windsor	Visual Inspection	Paid	0	0	0			
3964	Windsor	Visual Inspection	Paid	0	0	0			Gutters
3047	Windsor	Visual Inspection	Paid	0	0	0			Gutters
3305	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3012	Windsor	Visual Inspection	Paid	0	0	0			Gutters
1884	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3413	Windsor	Visual Inspection	Paid	0	0	0			
3515	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3649	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
Winsted Count	1								
3147	Winsted	Petrographic Analysis	Paid	0	0	0			Gutters
Wolcott Count	1								
3712	Wolcott	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Woodstock Count	7								
3915	Woodstock	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
3965	Woodstock	Visual Inspection	Paid	0	0	0			Gutters
60	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain

All Applications

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1673	Woodstock	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3343	Woodstock	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
1354	Woodstock	Visual Inspection	Denied	0	0	0			Gutters
3231	Woodstock	Visual Inspection	Paid	0	0	0			Gutters - With Extension

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Grand Count	3527								
Amston Count	4								
3886	Amston	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
3286	Amston	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
809	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2062	Amston	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Andover Count	31								
2008	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2101	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2227	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2326	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
938	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1118	Andover	Visual Inspection	Paid	0	0	0			Gutters
1151	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1179	Andover	Petrographic Analysis	Paid	0	0	0			
1192	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
55	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
234	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3324	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3376	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior
3395	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
3397	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
3644	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
1220	Andover	Visual Inspection	Paid	0	0	0			
1482	Andover	Visual Inspection	Paid	0	0	0			
2818	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2916	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
695	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
840	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
412	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
466	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
515	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
4079	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1575	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
1688	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1727	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1768	Andover	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1798	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Ashford Count	74								
1587	Ashford	Petrographic Analysis	Paid	1	1	43	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1605	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
1609	Ashford	Petrographic Analysis	Paid	1	1	32	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
1654	Ashford	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1683	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1200	Ashford	Visual Inspection	Paid	0	0	0			
1239	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1241	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior
1305	Ashford	Visual Inspection	Paid	0	0	0			Gutters
1435	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
1458	Ashford	Visual Inspection	Paid	0	0	0			
1521	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Footing Drains;Curtain or French Drain
2199	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2200	Ashford	Petrographic Analysis	Paid	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2209	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2229	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2289	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2303	Ashford	Petrographic Analysis	Paid	1	1	1.38	Minor degradation	Floor and walls both	Gutters;Footing Drains
2524	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains
2529	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2603	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2613	Ashford	Visual Inspection	Paid	0	0	0			
2650	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3398	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3428	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3554	Ashford	Visual Inspection	Paid	0	0	0			Gutters
3615	Ashford	Petrographic Analysis	Paid	1	1	1	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3621	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
900	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
916	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
925	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
997	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1008	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1078	Ashford	Visual Inspection	Paid	0	0	0	Don't know		
1084	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
4	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
11	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
19	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
47	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
81	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
110	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
112	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
123	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
152	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
161	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
257	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
810	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
825	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
876	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2797	Ashford	Visual Inspection	Paid	0	0	0			Gutters
2921	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
2927	Ashford	Visual Inspection	Paid	0	0	0			
2931	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
3022	Ashford	Petrographic Analysis	Paid	1	1	1.35	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
3702	Ashford	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
3704	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3776	Ashford	Visual Inspection	Paid	0	0	0			
3834	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3897	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3902	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3951	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3961	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension;Footing Drains
3970	Ashford	Visual Inspection	Paid	0	0	0			
389	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
390	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
395	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
473	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
501	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
516	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
592	Ashford	Visual Inspection	Paid	0	0	0			Gutters
3114	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3127	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3228	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
3234	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
Avon Count	4								
3113	Avon	Visual Inspection	Paid	0	0	0			
3328	Avon	Visual Inspection	Paid	0	0	0			
4027	Avon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3935	Avon	Visual Inspection	Paid	0	0	0			
Berlin Count	1								
2139	Berlin	Visual Inspection	Paid	0	0	0			
Bloomfield Count	9								
2197	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1103	Bloomfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1965	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
2131	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1822	Bloomfield	Visual Inspection	Paid	0	0	0			
3835	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
2492	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2505	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2607	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
Bolton Count	66								
3994	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
4021	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4093	Bolton	Visual Inspection	Paid	0	0	0			
4094	Bolton	Visual Inspection	Paid	0	0	0			Gutters
3877	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3955	Bolton	Visual Inspection	Paid	0	0	0			
1202	Bolton	Petrographic Analysis	Paid	0	1	0.87			Gutters;Gutters - With Extension
1203	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1245	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1339	Bolton	Visual Inspection	Paid	0	0	0			
2154	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2294	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2422	Bolton	Visual Inspection	Paid	1	0	0	No visible signs		Gutters - With Extension;Curtain or French Drain
928	Bolton	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain
987	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
1012	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1053	Bolton	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
1092	Bolton	Visual Inspection	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1132	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1134	Bolton	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1161	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1618	Bolton	Visual Inspection	Paid	0	0	0			
1628	Bolton	Visual Inspection	Paid	0	0	0			Gutters
1707	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1751	Bolton	Petrographic Analysis	Paid	1	1	1	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3125	Bolton	Petrographic Analysis	Paid	0	1	1.2			Gutters;Gutters - With Extension;Finished Basement
3126	Bolton	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
3218	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3265	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3276	Bolton	Visual Inspection	Paid	0	0	0			Gutters
1968	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2039	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
2076	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2134	Bolton	Petrographic Analysis	Paid	0	1	11			
2427	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
2460	Bolton	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2530	Bolton	Petrographic Analysis	Paid	0	1	2.15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2547	Bolton	Visual Inspection	Paid	0	0	0			Gutters
2615	Bolton	Petrographic Analysis	Paid	0	1	0.66			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
2617	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2654	Bolton	Visual Inspection	Paid	0	0	0			
2702	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2732	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
422	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
522	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
538	Bolton	Visual Inspection	Paid	0	0	0			
616	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
638	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
727	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
748	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
800	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
812	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
815	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
49	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
59	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
98	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
279	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
290	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
3377	Bolton	Visual Inspection	Paid	0	0	0			
3637	Bolton	Visual Inspection	Paid	0	0	0			
3640	Bolton	Visual Inspection	Paid	0	0	0			
3660	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2821	Bolton	Petrographic Analysis	Paid	0	0	0			
2836	Bolton	Visual Inspection	Paid	0	0	0			Gutters
2920	Bolton	Visual Inspection	Paid	0	0	0			Gutters
2937	Bolton	Visual Inspection	Paid	0	0	0			
Bristol Count	1								
2834	Bristol	Visual Inspection	Paid	0	0	0			Gutters
Broad Brook Count	4								
1210	Broad Brook	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
1592	Broad Brook	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2379	BROAD BROOK	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3317	broad brook	Visual Inspection	Paid	0	0	0			Gutters
Broadbrook Count	1								
817	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Brooklyn Count	2								
3809	Brooklyn	Visual Inspection	Paid	0	0	0			Gutters
2857	Brooklyn	Visual Inspection	Paid	0	0	0			
Canterbury Count	1								
1287	Canterbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
Canton Count	2								
2995	Canton	Visual Inspection	Paid	0	0	0			Gutters
1155	Canton	Visual Inspection	Paid	0	0	0			Gutters
Chaplin Count	3								
2700	Chaplin	Visual Inspection	Paid	0	0	0			
3708	Chaplin	Visual Inspection	Paid	0	0	0			
2175	Chaplin	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
Cheshire Count	2								
2970	Cheshire	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3508	Cheshire	Visual Inspection	Paid	0	0	0			
Colchester Count	6								
3361	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2254	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1645	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
1791	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4010	Colchester	Visual Inspection	Paid	0	0	0			Gutters
1219	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
Columbia Count	25								
3752	Columbia	Visual Inspection	Paid	0	0	0			Gutters
3784	Columbia	Visual Inspection	Paid	0	0	0			Gutters - With Extension

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2143	Columbia	Visual Inspection	Paid	0	0	0			
2203	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2291	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2405	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3342	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3033	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3042	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1776	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
994	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1047	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
603	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2808	Columbia	Visual Inspection	Paid	0	0	0			
588	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
593	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2498	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2513	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2532	Columbia	Visual Inspection	Paid	0	0	0			Gutters
2602	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2686	Columbia	Visual Inspection	Paid	1	0	0	No visible signs		Gutters
2690	Columbia	Visual Inspection	Paid	0	0	0			
2730	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
57	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
262	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
Coventry Count	248								
35	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
42	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
46	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
82	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
108	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
128	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
159	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
165	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
169	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
193	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
198	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
221	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
243	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
282	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
912	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
917	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
923	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
943	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
955	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
989	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1002	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1019	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
1021	Coventry	Visual Inspection	Paid	0	0	0			
1027	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1028	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
1034	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1038	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1042	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
1046	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1068	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1082	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1087	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
1125	Coventry	Visual Inspection	Paid	1	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
1137	Coventry	Visual Inspection	Paid	0	0	0			
1167	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1177	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1180	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2147	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension
2148	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
2159	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2160	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2161	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2165	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2168	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2176	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2182	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2198	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2249	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2252	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2302	Coventry	Visual Inspection	Paid	0	0	0			
2325	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2331	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2337	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2339	Coventry	Visual Inspection	Paid	0	0	0			
2342	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2343	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2345	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2352	Coventry	Visual Inspection	Paid	1	0	0			Gutters
2367	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4008	Coventry	Visual Inspection	Paid	0	0	0			Gutters
4048	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
4051	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
4075	Coventry	Visual Inspection	Paid	0	0	0			
4086	COVENTRY	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
4099	Coventry	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Curtain or French Drain
4103	Coventry	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
3678	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3685	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3690	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3698	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3699	Coventry	Visual Inspection	Paid	0	0	0			
3726	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3728	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3758	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3761	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3791	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3823	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3860	Coventry	Petrographic Analysis	Paid	1	1	34	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
3869	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
3906	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3920	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3936	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3969	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1533	Coventry	Petrographic Analysis	Paid	0	1	0.55			Gutters
1543	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1576	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1593	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1631	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1633	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1671	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1703	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1715	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1725	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
1728	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1753	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1782	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1797	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
1811	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1828	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters - With Extension
3332	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
3341	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3353	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3451	Coventry	Visual Inspection	Paid	0	0	0			
3530	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3549	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3550	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3585	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
3589	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension
3599	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3645	Coventry	Visual Inspection	Paid	0	0	0			
3028	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3034	Coventry	Visual Inspection	Paid	0	0	0			
3056	Coventry	Visual Inspection	Paid	0	0	0			
3071	Coventry	Visual Inspection	Paid	0	0	0			
3073	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
3085	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3092	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
3093	Coventry	Petrographic Analysis	Paid	1	1	0		Wall only	
3097	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
3123	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3143	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3161	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3182	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3200	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3220	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3233	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3279	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3300	Coventry	Visual Inspection	Paid	0	0	0			Gutters
3307	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3308	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3310	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3316	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2485	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2486	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2493	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2526	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2542	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
2556	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2558	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2559	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
2631	Coventry	Petrographic Analysis	Paid	0	1	54			Waterproofing - Exterior;Gutters;Finished Basement
2636	Coventry	Visual Inspection	Paid	0	0	0			
2637	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2639	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2651	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2659	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2670	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2674	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2698	Coventry	Petrographic Analysis	Paid	0	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
2707	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
2713	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2722	Coventry	Petrographic Analysis	Paid	0	0	0			Finished Basement
2743	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2744	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1206	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1231	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1232	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1254	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
1267	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1272	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1276	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1290	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
1308	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1319	Coventry	Visual Inspection	Paid	0	0	0			Gutters
1325	Coventry	Visual Inspection	Paid	0	0	0			
1342	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1351	Coventry	Petrographic Analysis	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
1352	Coventry	Visual Inspection	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
1386	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1387	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
1457	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1494	Coventry	Visual Inspection	Paid	0	0	0			
1509	Coventry	Visual Inspection	Paid	0	0	0			
1522	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
1527	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1862	Coventry	Visual Inspection	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1871	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1875	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1877	Coventry	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1894	Coventry	Visual Inspection	Paid	0	0	0			
1912	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1924	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1930	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1936	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1974	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1998	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2042	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2053	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2096	Coventry	Visual Inspection	Paid	0	0	0			
2118	Coventry	Visual Inspection	Paid	0	0	0			
642	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
644	Coventry	Petrographic Analysis	Paid	0	0	0			
648	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
653	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
677	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
680	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
693	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
722	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
738	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
753	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
776	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
779	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
784	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
793	Coventry	Visual Inspection	Paid	0	0	0			Gutters
806	Coventry	Visual Inspection	Paid	0	0	0			
824	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
833	Coventry	Visual Inspection	Paid	0	0	0			
875	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
877	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
879	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
302	Coventry	Visual Inspection	Paid	0	0	0			Gutters
303	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
305	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
309	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
312	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
313	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
327	Coventry	Visual Inspection	Paid	0	0	0			Gutters
331	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
339	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
351	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
363	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
378	Coventry	Visual Inspection	Paid	0	0	0			
418	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
423	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
436	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
457	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
498	Coventry	Visual Inspection	Paid	0	0	0			
509	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
511	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
528	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
553	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
582	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
2765	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2770	Coventry	Visual Inspection	Paid	0	0	0			Gutters
2787	Coventry	Petrographic Analysis	Paid	1	1	0.76		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2798	Coventry	Visual Inspection	Paid	0	0	0			
2803	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2805	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2820	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
2826	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
2867	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2889	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2891	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2904	Coventry	Visual Inspection	Paid	0	0	0			
2969	Coventry	Visual Inspection	Paid	0	0	0			
2978	Coventry	Visual Inspection	Paid	0	0	0			
2986	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3021	coventry	Visual Inspection	Paid	0	0	0			Gutters
Cromwell Count	1								
1075	Cromwell	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
Durham Count	#REF!								
East Granby Count	4								
2383	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3730	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1485	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2534	East Granby	Petrographic Analysis	Paid	0	0	0			Gutters
East Hampton Count	5								
2634	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3322	East Hampton	Visual Inspection	Paid	0	0	0			
3285	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1658	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2087	East Hampton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
East Hartford Count	8								

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2305	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3333	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1709	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
983	East Hartford	Visual Inspection	Paid	0	0	0			Finished Basement
1055	East Hartford	Visual Inspection	Paid	0	0	0			
1497	East Hartford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
762	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
816	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
East Lyme Count	#REF!								
East Windsor Count	53								
375	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
420	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
442	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
573	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
636	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
714	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
790	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
791	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
32	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
94	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2764	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
2806	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2830	East Windsor	Visual Inspection	Paid	0	0	0			
2863	East Windsor	Visual Inspection	Paid	0	0	0			
2878	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains
2879	East Windsor	Petrographic Analysis	Paid	1	1	0.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
2935	East Windsor	Petrographic Analysis	Paid	0	1	29			Waterproofing - Exterior;Gutters;Finished Basement
2963	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
2141	East Windsor	Visual Inspection	Paid	0	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2224	East Windsor	Visual Inspection	Paid	0	0	0			
2290	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
2727	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3082	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3120	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
3121	East Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
3140	East Windsor	Petrographic Analysis	Paid	1	1	1.05	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
3188	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3221	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3226	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1872	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
1943	East Windsor	Petrographic Analysis	Paid	0	1	1.41			Gutters;Finished Basement;Footing Drains
3697	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3762	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3856	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3861	East Windsor	Visual Inspection	Paid	0	0	0			
3871	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3873	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
3876	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
3911	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
3952	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3380	East Windsor	Visual Inspection	Paid	0	0	0			
3402	East Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
3518	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
3626	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
1788	East Windsor	Visual Inspection	Paid	0	0	0			
1250	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1295	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1297	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1302	East Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Wall only	Gutters;Gutters - With Extension;Finished Basement
996	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1054	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1124	East Windsor	Visual Inspection	Paid	0	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1160	East Windsor	Petrographic Analysis	Paid	0	0	0			
Eastford Count	2								
386	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3924	Eastford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
Ellington Count	265								
3674	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3684	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3692	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains
3755	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3759	Ellington	Visual Inspection	Paid	0	0	0			
3775	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3789	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3790	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3813	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3817	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3824	Ellington	Visual Inspection	Paid	0	0	0			
3828	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement
3852	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3868	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3882	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
3944	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
3968	Ellington	Visual Inspection	Paid	0	0	0			
3986	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4003	Ellington	Visual Inspection	Paid	0	0	0			Gutters
4005	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
4012	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4015	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
4036	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4040	Ellington	Petrographic Analysis	Paid	0	0	0			
4044	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
4060	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
907	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
920	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
921	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
935	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
937	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
947	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
959	Ellington	Visual Inspection	Paid	0	0	0			
966	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
984	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
988	Ellington	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1006	Ellington	Petrographic Analysis	Paid	0	1	0.5			Finished Basement
1013	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1014	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1024	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1040	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1051	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1056	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1057	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1065	Ellington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Interior;Gutters;Gutters - With Extension
1066	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1076	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1097	Ellington	Visual Inspection	Paid	0	0	0			
1119	Ellington	Petrographic Analysis	Paid	0	1	0.9			Gutters;Gutters - With Extension;Capillary Break
1141	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
631	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
633	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
637	Ellington	Visual Inspection	Paid	0	0	0			Gutters
651	Ellington	Visual Inspection	Paid	0	0	0			
656	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
660	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
664	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters
673	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
682	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
704	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
705	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
717	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
725	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
728	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
733	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
739	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
821	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
823	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
897	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2441	Ellington	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2443	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2523	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2555	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
2590	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
2608	Ellington	Visual Inspection	Paid	0	0	0			Gutters
2623	Ellington	Petrographic Analysis	Paid	1	1	1.81	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2624	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2680	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2682	Ellington	Visual Inspection	Paid	0	0	0			Gutters
2687	Ellington	Visual	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2688	Ellington	Petrographic Analysis	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2740	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2136	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2140	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2190	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2191	Ellington	Petrographic Analysis	Paid	0	1	1.86			Gutters;Footing Drains
2192	Ellington	Visual Inspection	Paid	1	1	1.86	Don't know		Gutters;Footing Drains
2217	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2218	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
2230	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2235	Ellington	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
2238	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2258	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2262	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2271	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2281	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2282	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2311	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
2318	Ellington	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Gutters - With Extension
2324	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2338	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
2386	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
2398	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2402	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2418	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2419	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2420	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
31	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
34	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
37	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
38	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
56	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
84	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
95	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
106	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
107	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
113	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
118	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
126	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
127	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
137	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
157	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
192	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
205	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
223	Ellington	Visual Inspection	Paid	0	0	0			Gutters
235	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
264	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
284	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
291	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
2771	Ellington	Visual Inspection	Paid	0	0	0			
2784	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2785	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2799	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2815	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2827	Ellington	Visual Inspection	Paid	0	0	0			
2831	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2838	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2852	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
2884	Ellington	Visual Inspection	Paid	0	0	0			
2906	Ellington	Visual Inspection	Paid	0	0	0	No visible signs		
2907	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2914	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2947	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2972	Ellington	Petrographic Analysis	Paid	0	0	0			
2973	Ellington	Visual Inspection	Paid	0	0	0			
2985	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
2989	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
3016	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
3019	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3023	Ellington	Visual Inspection	Paid	0	0	0			
319	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
323	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
335	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
338	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
341	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
353	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
379	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
388	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
407	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
438	Ellington	Visual Inspection	Paid	0	0	0			Gutters
451	Ellington	Visual Inspection	Paid	0	0	0			Gutters
454	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
462	Ellington	Visual Inspection	Paid	0	0	0			Gutters
467	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
468	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
480	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
495	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
529	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
534	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
561	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
562	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
566	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1216	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1221	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1227	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
1229	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1312	Ellington	Visual Inspection	Paid	0	0	0			Footing Drains
1314	Ellington	Petrographic Analysis	Paid	0	1	0.71			Gutters;Curtain or French Drain
1341	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1343	Ellington	Petrographic Analysis	Paid	0	1	0.7			Gutters
1380	Ellington	Visual Inspection	Paid	0	0	0			
1383	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1428	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1432	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1439	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1443	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1444	Ellington	Petrographic Analysis	Paid	1	1	2.21	Minor to moderate (repair suggested/recommended)	Floor and walls both	
1462	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1484	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1487	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1495	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement;Curtain or French Drain
1518	Ellington	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3030	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3032	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3060	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3061	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3069	Ellington	Visual Inspection	Paid	0	0	0			
3077	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
3079	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3087	Ellington	Visual Inspection	Paid	0	0	0			
3088	Ellington	Petrographic Analysis	Paid	0	0	0			
3136	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3146	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3150	Ellington	Visual Inspection	Paid	0	0	0			
3154	Ellington	Petrographic Analysis	Paid	1	1	1.57	Moderate to severe (significant repairs required)	Floor and walls both	
3179	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
3190	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3196	Ellington	Visual Inspection	Paid	0	0	0			
3203	Ellington	Visual Inspection	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3208	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3210	Ellington	Visual Inspection	Paid	0	0	0			
3215	Ellington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3217	Ellington	Petrographic Analysis	Paid	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
3264	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension
3278	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Finished Basement
3289	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Curtain or French Drain
3304	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3311	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1863	Ellington	Petrographic Analysis	Paid	1	1	2.28	Moderate to severe (significant repairs required)	Wall only	Gutters
1864	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1865	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1895	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters - With Extension
1926	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1990	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2018	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2033	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
2048	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2055	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2065	Ellington	Petrographic Analysis	Paid	0	1	1.52			Gutters
2074	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
2090	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2091	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2132	Ellington	Petrographic Analysis	Paid	0	1	0.57			Gutters
1531	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1536	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1545	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1562	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1565	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1574	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1622	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1635	Ellington	Petrographic Analysis	Paid	0	1	0.69			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1650	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
1655	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1667	Ellington	Visual Inspection	Paid	0	0	0			
1710	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1716	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement
1742	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1778	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
1796	Ellington	Visual Inspection	Paid	0	0	0			Gutters
1825	Ellington	Petrographic Analysis	Paid	1	1	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3329	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3350	Ellington	Visual Inspection	Paid	0	0	0			
3357	Ellington	Visual Inspection	Paid	0	0	0			
3383	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
3396	Ellington	Visual Inspection	Paid	0	0	0			
3421	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3432	Ellington	Visual Inspection	Paid	0	0	0			Gutters
3527	Ellington	Petrographic Analysis	Paid	0	1	36			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3576	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3587	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3610	Ellington	Visual Inspection	Paid	0	0	0			
3629	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3647	Ellington	Visual Inspection	Paid	0	0	0			
3650	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
Enfield Count	87								
3375	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3622	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
73	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
88	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
97	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1059	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1094	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1136	Enfield	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1145	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1152	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Curtain or French Drain
1153	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
3714	Enfield	Visual Inspection	Paid	0	0	0			Gutters
3717	Enfield	Petrographic Analysis	Paid	0	1	0.13			
3763	Enfield	Visual Inspection	Paid	0	0	0			
3783	Enfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3937	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
3993	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4006	Enfield	Visual Inspection	Paid	0	0	0			
4092	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
4101	Enfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
2193	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
2244	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2334	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2335	Enfield	Petrographic Analysis	Paid	1	1	1.14	Moderate to severe (significant repairs required)	Wall only	Gutters
2366	Enfield	Visual Inspection	Paid	0	0	0			
2403	Enfield	Petrographic Analysis	Paid	1	1	0.51			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
2404	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation		Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
760	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
2430	Enfield	Petrographic Analysis	Paid	1	1	0.88	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2435	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2436	Enfield	Visual Inspection	Paid	0	0	0			Gutters
2438	Enfield	Visual Inspection	Paid	0	0	0			Gutters
2444	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
2474	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2503	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
2525	Enfield	Petrographic Analysis	Paid	1	1	27	Don't know	Concrete floor only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2527	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2543	Enfield	Visual Inspection	Paid	0	0	0			Gutters
2595	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2610	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2641	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2692	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
1530	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1621	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1700	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1701	Enfield	Petrographic Analysis	Paid	1	1	0.39	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1729	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1793	Enfield	Petrographic Analysis	Paid	1	1	0.89	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
1233	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1237	Enfield	Petrographic Analysis	Paid	0	1	1.46			Gutters
1262	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1376	Enfield	Visual Inspection	Paid	0	0	0			Gutters
1394	Enfield	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Finished Basement
1395	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
1426	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1489	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
1492	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1502	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1503	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
2762	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2766	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2829	Enfield	Visual Inspection	Paid	0	0	0			
2832	Enfield	Petrographic Analysis	Paid	1	1	59	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
2877	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2997	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2998	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
321	Enfield	Visual Inspection	Paid	0	0	0			Gutters
356	Enfield	Visual Inspection	Paid	0	0	0			
445	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
506	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
560	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
594	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1856	Enfield	Petrographic Analysis	Paid	1	1	0.62	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1858	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
1891	Enfield	Petrographic Analysis	Paid	1	1	0.45	No visible signs	Wall only	Gutters;Finished Basement
1892	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
1976	Enfield	Petrographic Analysis	Paid	0	1	33		Wall only	Waterproofing - Exterior;Gutters
1980	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1988	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
2009	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2034	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2038	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2044	Enfield	Petrographic Analysis	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2047	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3110	Enfield	Petrographic Analysis	Paid	0	1	0.24			Gutters;Finished Basement
3181	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3241	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Farmington Count	2								
3366	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3914	Farmington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
Glastonbury Count	63								
3686	Glastonbury	Visual Inspection	Paid	0	0	0			
3687	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3812	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3844	Glastonbury	Visual Inspection	Paid	0	0	0			
3916	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3921	Glastonbury	Visual Inspection	Paid	0	0	0			
3980	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3379	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
3412	Glastonbury	Visual Inspection	Paid	0	0	0			
3512	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
3568	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
3606	Glastonbury	Visual Inspection	Paid	0	0	0			
3666	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3668	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
789	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
995	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters
1048	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1071	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1128	GLASTONBURY	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Capillary Break
1187	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
1197	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3080	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3086	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
3094	Glastonbury	Visual Inspection	Paid	0	0	0			
3144	Glastonbury	Visual Inspection	Paid	0	0	0			
3206	Glastonbury	Visual Inspection	Paid	0	0	0	No visible signs		
3227	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
3259	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2158	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Finished Basement
2172	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2215	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2414	Glastonbury	Visual Inspection	Paid	0	0	0			
3992	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3997	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1890	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
1972	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2012	Glastonbury	Visual Inspection	Paid	0	0	0			
2014	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1326	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1399	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1424	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1475	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
1483	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1499	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2429	Glastonbury	Visual Inspection	Paid	0	0	0			
2551	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2669	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2677	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2685	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
1586	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1598	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
1634	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1641	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1679	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1804	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2774	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2777	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2804	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2824	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2835	Glastonbury	Visual Inspection	Paid	0	0	0			
2856	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2869	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
2948	Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
Granby Count	2								
2790	Granby	Visual Inspection	Paid	0	0	0			
1253	Granby	Visual Inspection	Paid	0	0	0			Gutters
Griswold Count	#REF!								
Haddam Count	#REF!								
Hamden Count	#REF!								
Hampton Count	5								
2293	Hampton	Visual Inspection	Paid	0	0	0			
4030	Hampton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4083	Hampton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
2689	Hampton	Visual Inspection	Paid	0	0	0			Gutters
2717	Hampton	Visual Inspection	Paid	0	0	0			
Hartford Count	#REF!								
Hebron Count	33								
1800	Hebron	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters
1813	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2448	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2490	Hebron	Visual Inspection	Paid	0	0	0			Gutters
2500	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2548	Hebron	Petrographic Analysis	Paid	0	1	0.73			Waterproofing - Exterior;Gutters
2557	Hebron	Visual Inspection	Paid	0	0	0			Gutters
2652	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3336	Hebron	Visual Inspection	Paid	0	0	0			
3354	Hebron	Visual Inspection	Paid	0	0	0			Gutters
3504	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3601	Hebron	Visual Inspection	Paid	0	0	0			Gutters
3843	Hebron	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Footing Drains
3895	Hebron	Visual Inspection	Paid	0	0	0			
3931	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
3959	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
93	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
201	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
247	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2780	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2840	Hebron	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
720	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
822	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
3151	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3283	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1243	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1397	Hebron	Visual Inspection	Paid	0	0	0			Gutters
1447	Hebron	Petrographic Analysis	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
1919	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1953	Hebron	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
2025	Hebron	Visual Inspection	Paid	0	0	0			
4064	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
2169	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
Killingly Count	2								
2979	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
450	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
Killingworth Count	1								
3593	Killingworth	Visual Inspection	Paid	0	0	0			
Lebanon Count	5								
3384	Lebanon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3429	Lebanon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
452	Lebanon	Visual Inspection	Paid	0	0	0			
2888	Lebanon	Visual Inspection	Paid	0	0	0			
3186	Lebanon	Visual Inspection	Paid	0	0	0			
Longmeadow Count	#REF!								
Lyme Count	1								
3546	Lyme	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
Madison Count	#REF!								
Manchester Count	300								
904	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
949	Manchester	Visual Inspection	Paid	0	0	0			
954	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
957	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
961	Manchester	Visual Inspection	Paid	0	0	0			
964	manchester	Petrographic Analysis	Paid	0	1	29			Gutters;Gutters - With Extension
990	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1004	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
1011	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Finished Basement
1025	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1029	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1035	Manchester	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1036	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
1058	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1069	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
1073	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters
1088	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
1108	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1139	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1154	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1163	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1166	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1170	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1193	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2426	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2450	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2463	Manchester	Petrographic Analysis	Paid	1	1	56	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension
2466	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2479	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2528	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2538	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
2550	Manchester	Visual Inspection	Paid	0	0	0			
2553	Manchester	Visual Inspection	Paid	0	0	0			
2594	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2626	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2646	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2672	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2684	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2718	Manchester	Petrographic Analysis	Paid	1	1	2.41	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2721	Manchester	Visual Inspection	Paid	0	0	0			
2736	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
2741	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3055	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3063	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3078	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3115	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3117	Manchester	Visual Inspection	Paid	0	0	0			
3156	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3168	Manchester	Visual Inspection	Paid	0	0	0			Finished Basement
3173	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
3176	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3178	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3187	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3192	Manchester	Visual Inspection	Paid	0	0	0			
3193	Manchester	Visual Inspection	Paid	0	0	0			
3205	Manchester	Petrographic Analysis	Paid	0	0	0			
3212	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
3224	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
3236	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
3255	Manchester	Visual Inspection	Paid	0	0	0			
3258	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3262	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3269	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3272	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
3275	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3280	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
3306	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Curtain or French Drain
3309	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1539	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
1547	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1588	Manchester	Visual Inspection	Paid	0	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Gutters

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1604	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
1611	Manchester	Visual Inspection	Paid	0	0	0			
1614	Manchester	Visual Inspection	Paid	0	0	0			
1647	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
1662	Manchester	Petrographic Analysis	Paid	1	1	2.58	Don't know	Floor and walls both	Gutters;Finished Basement
1670	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1689	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1692	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1767	Manchester	Visual Inspection	Paid	0	0	0			
1784	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1786	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1790	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1807	Manchester	Visual Inspection	Paid	1	0	0		Concrete floor only	Gutters
1833	Manchester	Visual Inspection	Paid	0	0	0			
2150	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2204	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2223	Manchester	Petrographic Analysis	Paid	1	1	55	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2297	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
2300	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2312	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
2315	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
2357	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2377	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
2393	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
604	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
611	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
613	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
615	Manchester	Visual Inspection	Paid	0	0	0			
617	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
622	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
649	Manchester	Visual Inspection	Paid	0	0	0			
666	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
674	Manchester	Visual Inspection	Paid	0	0	0			Gutters
678	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
692	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
696	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
699	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
726	Manchester	Visual Inspection	Paid	0	0	0			
730	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
731	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
745	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
750	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
751	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
752	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
755	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
761	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
763	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
771	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
778	Manchester	Petrographic Analysis	Paid	0	1	2			
785	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
786	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
788	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
794	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
801	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
835	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
3679	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
3680	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3682	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3739	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3741	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3743	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3749	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3751	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3825	Manchester	Visual Inspection	Paid	0	0	0			
3846	Manchester	Visual Inspection	Paid	0	0	0			
3858	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
3898	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
3939	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3967	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3971	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
3978	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3982	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
53	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
54	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
61	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
65	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
71	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
75	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
144	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
176	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
182	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
183	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
195	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
200	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
218	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
222	Manchester	Visual Inspection	Paid	0	0	0			Gutters
230	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
231	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
240	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
241	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
245	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
274	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
278	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
296	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3325	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3340	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
3359	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3363	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
3371	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3373	Manchester	Visual Inspection	Paid	0	0	0			
3374	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
3403	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3410	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3414	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3425	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3448	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3449	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3577	Manchester	Visual Inspection	Paid	0	0	0			
3592	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3603	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3634	Manchester	Visual Inspection	Paid	0	0	0			Gutters
3635	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3636	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
2752	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
2769	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2817	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2819	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2844	Manchester	Petrographic Analysis	Paid	1	1	30	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
2846	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2880	Manchester	Visual Inspection	Paid	0	0	0			
2881	Manchester	Petrographic Analysis	Paid	0	0	0			
2897	Manchester	Petrographic Analysis	Paid	1	1	2.67	Minor degradation	Wall only	Gutters;Gutters - With Extension
2928	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2930	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
2945	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2949	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2951	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2960	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2976	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3008	MANCHESTER	Petrographic Analysis	Paid	0	1	1.5			Gutters;Gutters - With Extension;Finished Basement
3010	manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3025	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Curtain or French Drain
311	Manchester	Visual Inspection	Paid	0	0	0			Gutters
314	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
316	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
320	Manchester	Visual Inspection	Paid	0	0	0			
325	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
332	Manchester	Visual Inspection	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
343	Manchester	Visual Inspection	Paid	0	0	0			
352	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
368	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
374	Manchester	Visual Inspection	Paid	0	0	0			
381	Manchester	Visual Inspection	Paid	0	0	0			
394	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
403	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
405	Manchester	Visual Inspection	Paid	0	0	0			
439	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
458	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
464	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
478	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
479	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
496	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
521	Manchester	Visual Inspection	Paid	0	0	0			
543	Manchester	Visual Inspection	Paid	0	0	0			Gutters
548	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
550	Manchester	Visual Inspection	Paid	0	0	0			
551	Manchester	Visual Inspection	Paid	0	0	0			
552	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
558	Manchester	Visual Inspection	Paid	0	0	0			
569	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
572	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
579	Manchester	Visual Inspection	Paid	0	0	0			
583	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1212	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1224	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
1228	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1235	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1236	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1246	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
1258	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1281	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1294	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1301	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1306	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1307	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1309	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1317	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Capillary Break
1324	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1329	Manchester	Visual Inspection	Paid	0	0	0			
1331	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
1338	Manchester	Petrographic Analysis	Paid	1	1	68	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
1345	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
1348	Manchester	Petrographic Analysis	Paid	0	1	1.69			Gutters;Finished Basement
1353	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1371	Manchester	Visual Inspection	Paid	0	0	0			Gutters
1388	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1425	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1429	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1441	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1454	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
1469	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1470	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
1471	Manchester	Visual Inspection	Paid	0	0	0			
1473	Manchester	Visual Inspection	Paid	0	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1478	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1490	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1505	Manchester	Visual Inspection	Paid	0	0	0			
1511	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1517	Manchester	Visual Inspection	Paid	0	0	0			
1520	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4011	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
4017	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
4022	Manchester	Visual Inspection	Paid	0	0	0			Gutters
4029	Manchester	Visual Inspection	Paid	0	0	0			
4041	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
4067	Manchester	Visual Inspection	Paid	0	0	0			
4070	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
4074	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
4077	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
1837	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
1860	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1918	Manchester	Visual Inspection	Paid	0	0	0			
1921	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1954	Manchester	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1959	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1962	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1963	Manchester	Visual Inspection	Paid	0	0	0			
1966	Manchester	Petrographic Analysis	Paid	0	0	0			
1994	Manchester	Visual Inspection	Paid	0	0	0			
1997	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2003	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters
2028	Manchester	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2073	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
2081	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2082	Manchester	Petrographic Analysis	Paid	1	1	2.49	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2088	Manchester	Visual Inspection	Paid	0	0	0			Gutters
2108	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
2121	Manchester	Visual Inspection	Paid	0	0	0			
2128	Manchester	Visual Inspection	Paid	0	0	0			Gutters
Mansfield Count	117								
1869	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
1880	Mansfield	Visual Inspection	Paid	0	0	0			
1931	Mansfield	Petrographic Analysis	Paid	0	1	0.54			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1945	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
1961	Mansfield	Visual Inspection	Paid	0	0	0			
2022	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
2024	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
2031	Mansfield	Visual Inspection	Paid	0	0	0			
2035	Mansfield	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension
2040	Mansfield	Visual Inspection	Paid	0	0	0			
2046	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
2059	Mansfield	Visual Inspection	Paid	0	0	0			
2117	Mansfield	Petrographic Analysis	Paid	0	0	0			
2120	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3677	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3701	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3703	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3727	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement
3770	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3799	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3818	Mansfield	Visual Inspection	Paid	0	0	0			
3820	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3872	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3942	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3946	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3957	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
3966	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3046	Mansfield	Petrographic Analysis	Paid	0	0	0			
3074	Mansfield	Visual Inspection	Paid	0	0	0			
3102	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3131	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
3135	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3138	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3159	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3185	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3197	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3235	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3268	Mansfield	Visual Inspection	Paid	0	0	0			
3303	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
911	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
915	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
934	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
1096	Mansfield	Visual Inspection	Paid	0	0	0			
1101	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1114	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1123	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1140	Mansfield	Visual Inspection	Paid	0	0	0			
2468	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
2482	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2502	Mansfield	Visual Inspection	Paid	0	0	0			
2536	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2544	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2620	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2731	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
605	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
606	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
618	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
663	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
743	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
782	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
838	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
1538	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1544	Mansfield	Visual Inspection	Paid	0	0	0			
1603	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1636	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters
1680	Mansfield	Petrographic Analysis	Paid	0	1	0.52			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
1717	Mansfield	Petrographic Analysis	Paid	0	1	0.68			Gutters;Finished Basement
1732	Mansfield	Visual Inspection	Paid	0	0	0			
1735	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1755	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1802	Mansfield	Petrographic Analysis	Paid	0	1	0			Gutters
2146	Mansfield	Petrographic Analysis	Paid	0	0	0			
2153	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2185	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2206	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2350	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
4019	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
4035	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
4058	Mansfield	Visual Inspection	Paid	0	0	0			
2750	Mansfield	Visual Inspection	Paid	0	0	0			
2775	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2779	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2894	Mansfield	Visual Inspection	Paid	0	0	0			
2909	Mansfield	Petrographic Analysis	Paid	0	0	0			
2968	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
13	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
69	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
72	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
90	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
191	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3393	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3424	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3521	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3534	Mansfield	Visual Inspection	Paid	0	0	0			
3545	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3547	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3584	Mansfield	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
3624	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
3628	Mansfield	Visual Inspection	Paid	0	0	0			
1251	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
1257	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
1289	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1323	Mansfield	Visual Inspection	Paid	0	0	0			
1375	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
1456	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1477	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
370	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
408	Mansfield	Visual Inspection	Paid	0	0	0			
470	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
517	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
523	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
524	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
525	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
545	Mansfield	Visual Inspection	Paid	0	0	0			
590	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
595	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
596	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
Mansfield Center Count	5								
1686	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1774	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
807	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
940	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3646	Mansfield Center	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Marlborough Count	7								
350	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
2933	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2980	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3009	Marlborough	Visual Inspection	Paid	0	0	0			Gutters
2213	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1000	Marlborough	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains
1104	Marlborough	Petrographic Analysis	Paid	0	0	0			Gutters
Middletown Count	2								
2277	Middletown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2341	Middletown	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
New Haven Count	#REF!								
Newington Count	2								
2210	Newington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2955	Newington	Visual Inspection	Paid	0	0	0			Finished Basement
Northford Count	#REF!								
Norwich Count	1								
3899	Norwich	Visual Inspection	Paid	0	0	0			
Plainfield Count	1								
746	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
Plantsville Count	#REF!								
Pomfret Count	2								

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2660	Pomfret	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
2329	Pomfret	Visual Inspection	Paid	0	0	0			Gutters
Portland Count	6								
2260	Portland	Visual Inspection	Paid	0	0	0			Gutters
2307	Portland	Visual Inspection	Paid	0	0	0			Finished Basement
980	Portland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
578	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
3358	Portland	Visual Inspection	Paid	0	0	0			Gutters
2045	Portland	Visual Inspection	Paid	0	0	0			
Rocky Hill Count	1								
3934	Rocky Hill	Visual Inspection	Paid	0	0	0			
S Glastonbury Count	1								
2593	S Glastonbury	Visual Inspection	Paid	0	0	0			
Simsbury Count	1								
1374	Simsbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Somers Count	138								
1207	Somers	Petrographic Analysis	Paid	0	1	1.33			Gutters;Finished Basement
1255	Somers	Visual Inspection	Paid	0	0	0			Gutters
1266	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
1284	Somers	Visual Inspection	Paid	0	0	0			Gutters
1316	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
1396	Somers	Petrographic Analysis	Paid	0	1	2			Gutters
1455	Somers	Visual Inspection	Paid	0	0	0			Gutters
1512	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1599	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
1606	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
1669	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1678	Somers	Petrographic Analysis	Paid	0	1	1.31			Gutters;Gutters - With Extension;Finished Basement
1693	Somers	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Footing Drains
1698	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
1704	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
1748	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1749	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1756	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1789	Somers	Visual Inspection	Paid	0	0	0			
1799	Somers	Petrographic Analysis	Paid	1	1	16	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
1832	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3321	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3362	Somers	Visual Inspection	Paid	0	0	0			
3365	Somers	Visual Inspection	Paid	0	0	0			
3368	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
3392	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3434	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3532	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3533	Somers	Visual Inspection	Paid	0	0	0			
3555	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3556	Somers	Visual Inspection	Paid	0	0	0			Footing Drains;Curtain or French Drain
3563	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3570	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3574	Somers	Visual Inspection	Paid	0	0	0			
3581	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
977	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
1050	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1064	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1174	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
2162	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
2214	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2219	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
2221	Somers	Visual Inspection	Paid	0	0	0			
2233	Somers	Visual Inspection	Paid	0	0	0			
2266	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2276	Somers	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2322	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2323	Somers	Petrographic Analysis	Paid	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2327	Somers	Petrographic Analysis	Paid	0	0	0			
2368	Somers	Petrographic Analysis	Paid	0	0	0			Gutters
2371	Somers	Petrographic Analysis	Paid	0	1	0.92			Gutters;Finished Basement
2375	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2384	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
2390	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2396	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2407	Somers	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
3035	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3053	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3065	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3129	Somers	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension
3130	Somers	Visual Inspection	Paid	0	0	0			Gutters
3133	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
3163	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3183	Somers	Visual Inspection	Paid	0	0	0			Gutters
3222	Somers	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
3261	Somers	Visual Inspection	Paid	0	0	0			Gutters
3274	Somers	Petrographic Analysis	Paid	0	1	2.37			Gutters;Finished Basement;Footing Drains
3302	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
346	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
369	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
377	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
447	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
500	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
587	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
597	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1873	Somers	Petrographic Analysis	Paid	0	1	0.48			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1881	Somers	Visual Inspection	Paid	0	0	0			
1888	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
1928	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1955	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
1989	Somers	Petrographic Analysis	Paid	0	1	2			Gutters;Finished Basement
2002	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2007	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2089	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2129	Somers	Visual Inspection	Paid	0	0	0			Gutters
2434	Somers	Petrographic Analysis	Paid	0	1	0.79			Gutters;Gutters - With Extension;Finished Basement
2459	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2461	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
2471	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2489	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2510	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2515	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2516	Somers	Petrographic Analysis	Paid	0	1	0.63			Waterproofing - Exterior;Gutters;Curtain or French Drain
2519	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
2586	Somers	Petrographic Analysis	Paid	1	1	0.54	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2647	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2679	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2703	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2709	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
625	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
627	Somers	Petrographic Analysis	Paid	0	1	0			

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
652	Somers	Petrographic Analysis	Paid	0	0	0			
661	Somers	Visual Inspection	Paid	0	0	0			
724	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
845	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
894	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
3675	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Finished Basement
3683	Somers	Visual Inspection	Paid	0	0	0			
3706	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
3750	Somers	Visual Inspection	Paid	0	0	0			Gutters
3815	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
3842	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3879	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
3880	Somers	Visual Inspection	Paid	0	0	0			
3883	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3884	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3963	Somers	Visual Inspection	Paid	0	0	0			
3976	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4038	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
4052	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
4068	Somers	Petrographic Analysis	Paid	0	1	1.51			Gutters
4090	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2760	Somers	Petrographic Analysis	Paid	1	1	0.64	Minor degradation	Floor and walls both	Gutters;Finished Basement
2761	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
2793	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2837	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2841	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Footing Drains
2842	Somers	Petrographic Analysis	Paid	1	1	1.32	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2843	Somers	Petrographic Analysis	Paid	0	1	1.32			Gutters;Finished Basement;Curtain or French Drain
2905	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
2924	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2941	Somers	Visual Inspection	Paid	0	0	0			Gutters
2956	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement
2990	Somers	Visual Inspection	Paid	0	0	0			
162	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
173	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
256	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
273	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
South Glastonbury Count		7							
3526	South Glastonbury	Visual Inspection	Paid	0	0	0			
3656	South Glastonbury	Petrographic Analysis	Paid	1	1	35	Don't know	Wall only	
1579	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3256	South Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
2409	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2988	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2993	South Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
South Windsor Count		474							
2748	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2781	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2786	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2788	South Windsor	Visual Inspection	Paid	0	0	0			
2794	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
2795	South Windsor	Visual Inspection	Paid	0	0	0			
2796	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2801	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2807	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2811	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
2814	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
2828	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2839	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2847	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2850	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2854	South Windsor	Visual Inspection	Paid	0	0	0			
2872	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2900	South Windsor	Visual Inspection	Paid	0	0	0			
2901	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2911	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2912	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
2954	South Windsor	Visual Inspection	Paid	0	0	0			
2962	South Windsor	Visual Inspection	Paid	0	0	0			
2965	South Windsor	Visual Inspection	Paid	0	0	0			
2984	South Windsor	Petrographic Analysis	Paid	0	1	0.45			Gutters;Gutters - With Extension;Finished Basement
2992	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
2999	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3006	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3017	South windsor	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	
3020	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3024	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3026	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3036	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3039	South Windsor	Visual Inspection	Paid	0	0	0			
3040	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3048	South Windsor	Visual Inspection	Paid	0	0	0			
3049	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
3072	South Windsor	Visual Inspection	Paid	0	0	0			
3081	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3083	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3096	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3103	South Windsor	Visual Inspection	Paid	0	0	0			
3122	South Windsor	Visual Inspection	Paid	0	0	0			
3128	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3132	South Windsor	Visual Inspection	Paid	0	0	0			
3134	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
3141	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters
3152	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
3155	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3160	South Windsor	Visual Inspection	Paid	0	0	0			
3162	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3170	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
3172	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
3174	South Windsor	Petrographic Analysis	Paid	0	1	1.81			Gutters;Gutters - With Extension;Finished Basement
3191	South Windsor	Visual Inspection	Paid	0	0	0			
3201	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters - With Extension;Finished Basement
3213	South Windsor	Visual Inspection	Paid	0	0	0			
3214	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3219	South Windsor	Petrographic Analysis	Paid	0	1	86			Waterproofing - Exterior;Gutters
3232	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
3242	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3245	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3246	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3247	South Windsor	Visual Inspection	Paid	0	0	0			
3270	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3271	South Windsor	Visual Inspection	Paid	0	0	0			
3282	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3284	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
3288	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3298	South Windsor	Visual Inspection	Paid	0	0	0			
8	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
22	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
27	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
29	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
67	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
77	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
89	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
96	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
102	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
124	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
130	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
134	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
135	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
146	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
147	South Windsor	Visual Inspection	Paid	0	0	0			
158	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
167	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
168	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
199	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
212	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
215	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
227	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
229	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
232	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
237	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
271	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
272	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
275	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
280	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
281	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
283	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
285	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
288	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1213	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
1218	South Windsor	Petrographic Analysis	Paid	0	1	0.63			Gutters;Gutters - With Extension;Finished Basement
1234	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1238	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1240	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1252	South Windsor	Visual Inspection	Paid	0	0	0			
1259	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1260	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1268	South Windsor	Petrographic Analysis	Paid	1	1	23	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
1280	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1283	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
1291	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1293	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1310	South Windsor	Visual Inspection	Paid	0	0	0			
1311	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1328	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1330	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1346	South Windsor	Visual Inspection	Paid	0	0	0			
1349	South Windsor	Petrographic Analysis	Paid	0	1	38			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1384	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1385	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
1392	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1417	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1420	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1427	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
1451	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1464	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1468	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
1488	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1493	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1506	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1508	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
1526	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
326	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
328	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
344	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
364	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
392	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
393	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
426	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
428	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
430	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
437	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
443	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
446	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
449	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
453	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
475	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
482	South Windsor	Visual Inspection	Paid	0	0	0			
485	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
513	South Windsor	Visual Inspection	Paid	0	0	0			
520	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
530	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
531	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
555	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
571	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
575	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
586	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
601	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
1540	South Windsor	Petrographic Analysis	Paid	0	1	2.37			Gutters;Gutters - With Extension;Finished Basement
1548	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1549	South Windsor	Petrographic Analysis	Paid	0	0	0			
1561	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1563	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
1570	South Windsor	Visual Inspection	Paid	0	0	0			
1571	South Windsor	Petrographic Analysis	Paid	0	1	0.76			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1584	South Windsor	Petrographic Analysis	Paid	0	1	33			Gutters;Gutters - With Extension
1595	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1597	South Windsor	Visual Inspection	Paid	0	0	0			
1610	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1624	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1626	South Windsor	Petrographic Analysis	Paid	0	1	0		Floor and walls both	Gutters
1627	South Windsor	Petrographic Analysis	Paid	1	1	1.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
1640	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1642	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1649	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1653	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1659	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
1661	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1663	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1665	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1668	South Windsor	Visual Inspection	Paid	0	0	0			
1674	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1677	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1681	South Windsor	Petrographic Analysis	Paid	0	0	0			
1685	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1690	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1695	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1702	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1712	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1731	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1739	South Windsor	Visual Inspection	Paid	0	0	0			
1740	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1743	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1744	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1752	South Windsor	Petrographic Analysis	Paid	0	1	26			Waterproofing - Exterior;Gutters;Footing Drains
1754	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
1765	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1769	South Windsor	Visual Inspection	Paid	0	0	0			
1771	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
1775	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1777	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
1783	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1787	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1792	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
1809	South Windsor	Petrographic Analysis	Paid	1	1	0.48	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1819	South Windsor	Visual Inspection	Paid	0	0	0			
1820	South Windsor	Petrographic Analysis	Paid	0	0	0			
1823	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1827	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Finished Basement
902	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
909	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
913	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
927	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
941	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
945	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
965	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
968	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
969	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
978	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
991	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
998	South Windsor	Visual Inspection	Paid	0	0	0			
999	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
1003	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1010	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
1061	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1063	South Windsor	Visual Inspection	Paid	1	0	0			
1080	South Windsor	Petrographic Analysis	Paid	0	1	28			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1086	South Windsor	Petrographic Analysis	Paid	1	1	29	Don't know	Floor and walls both	Gutters;Gutters - With Extension
1093	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1098	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1111	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1117	South Windsor	Petrographic Analysis	Paid	1	1	0.99	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1130	South Windsor	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1138	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1142	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1147	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
1165	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1171	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1182	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
1190	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
1195	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3326	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3331	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
3337	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3351	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3352	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3367	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
3372	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3388	South Windsor	Visual Inspection	Paid	0	0	0			
3391	South Windsor	Visual Inspection	Paid	0	0	0			
3399	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3409	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
3418	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3426	South Windsor	Visual Inspection	Paid	0	0	0			
3430	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3433	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3446	South Windsor	Visual Inspection	Paid	0	0	0			
3452	South Windsor	Visual Inspection	Paid	0	0	0	Minor degradation	Wall only	Gutters;Footing Drains
3507	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3510	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Finished Basement
3513	South Windsor	Visual Inspection	Paid	0	0	0			
3543	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3558	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3559	South Windsor	Visual Inspection	Paid	0	0	0			
3562	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3564	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3575	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3579	South Windsor	Visual Inspection	Paid	0	0	0			
3591	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3594	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
3595	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
3600	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
3613	South Windsor	Visual Inspection	Paid	0	0	0			
3632	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
3643	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3651	South Windsor	Visual Inspection	Paid	0	0	0			
3663	South Windsor	Visual Inspection	Paid	0	0	0			
3664	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2138	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2142	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2157	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2170	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2171	South Windsor	Visual Inspection	Paid	0	0	0			
2174	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2183	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2205	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2212	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2246	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2247	South Windsor	Petrographic Analysis	Paid	1	1	30	No visible signs		Gutters;Gutters - With Extension;Footing Drains
2250	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2259	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2263	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2264	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2268	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2283	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
2298	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2301	South Windsor	Petrographic Analysis	Paid	0	1	11			Gutters
2308	South Windsor	Petrographic Analysis	Paid	0	1	0.77			Gutters;Finished Basement
2348	South Windsor	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Interior;Gutters;Finished Basement
2355	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2358	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
2365	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
2369	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
2372	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Finished Basement
2374	South Windsor	Visual Inspection	Paid	0	0	0			
2376	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2387	South Windsor	Visual Inspection	Paid	0	0	0			
2388	South Windsor	Visual Inspection	Paid	0	0	0			
2400	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2406	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2408	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2425	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
612	South Windsor	Visual Inspection	Paid	0	0	0			
619	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
626	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
643	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
659	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
662	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
668	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
698	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
712	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
766	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
792	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
803	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement
808	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
814	South Windsor	Petrographic Analysis	Paid	0	0	0			
820	South Windsor	Visual Inspection	Paid	0	0	0			
837	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
842	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
844	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
846	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
847	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
888	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
890	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
892	South Windsor	Visual Inspection	Paid	0	0	0			
1859	South Windsor	Petrographic Analysis	Paid	0	1	43			Waterproofing - Exterior;Gutters;Finished Basement
1867	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1868	South Windsor	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1874	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
1876	South Windsor	Visual Inspection	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1878	South Windsor	Petrographic Analysis	Paid	0	0	0			
1879	South Windsor	Visual Inspection	Paid	0	0	0			
1886	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1889	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Curtain or French Drain
1896	South Windsor	Visual Inspection	Paid	0	0	0			
1900	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1906	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
1909	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1913	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1933	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1934	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
1946	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1947	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1948	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1949	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
1956	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
1960	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1971	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
1975	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1991	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1996	South Windsor	Petrographic Analysis	Paid	0	1	0.4			Gutters;Finished Basement
2017	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2036	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2049	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2052	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2058	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
2061	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2063	South Windsor	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2069	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2077	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
2078	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2083	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2097	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2127	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2130	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2431	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
2433	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2437	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
2439	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
2440	South Windsor	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2452	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
2454	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2462	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2473	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2478	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2483	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2484	South Windsor	Petrographic Analysis	Paid	0	1	0.8			
2487	South Windsor	Petrographic Analysis	Paid	1	1	1.67	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
2488	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
2507	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2509	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2517	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2522	South Windsor	Petrographic Analysis	Paid	0	1	1.35			Waterproofing - Exterior;Gutters
2537	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Finished Basement
2552	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2554	South Windsor	Visual Inspection	Paid	0	0	0			
2585	South Windsor	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2592	South Windsor	Petrographic Analysis	Paid	0	1	1.33			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
2596	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2604	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2618	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2619	South Windsor	Petrographic Analysis	Paid	1	1	3.22	Don't know	Wall only	Gutters;Curtain or French Drain
2621	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2622	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2627	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2628	South Windsor	Petrographic Analysis	Paid	1	1	2.96	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2630	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2635	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
2638	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2666	South Windsor	Petrographic Analysis	Paid	0	0	0			
2678	South Windsor	Visual Inspection	Paid	0	0	0			
2693	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2694	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
2697	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2712	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2716	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
2719	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2724	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2728	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
2729	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2742	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2745	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3990	South Windsor	Visual Inspection	Paid	0	0	0			
4020	South Windsor	Visual Inspection	Paid	0	0	0			
4026	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4031	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
4046	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
4047	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4050	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
4069	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4071	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
4072	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
4073	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4080	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
4091	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
4100	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			
3711	South Windsor	Visual Inspection	Paid	0	0	0			
3718	South Windsor	Visual Inspection	Paid	0	0	0			
3735	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3738	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3740	South Windsor	Visual Inspection	Paid	0	0	0			
3744	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
3748	South Windsor	Petrographic Analysis	Paid	1	1	39	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3764	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
3768	South Windsor	Visual Inspection	Paid	0	0	0			
3777	South Windsor	Visual Inspection	Paid	0	0	0			
3778	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3802	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3816	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3821	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3822	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3829	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3830	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3836	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3837	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3862	South Windsor	Visual Inspection	Paid	1	0	0		Wall only	
3891	South Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension
3892	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
3900	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3909	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
3918	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3919	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3923	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
3928	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3938	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3943	South Windsor	Visual Inspection	Paid	0	0	0			
3958	South Windsor	Visual Inspection	Paid	0	0	0			
3960	South Windsor	Visual Inspection	Paid	0	0	0			
3972	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
3987	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
South Windssor Count	1								
1421	South Windssor	Visual Inspection	Paid	0	0	0			Gutters
Southington Count	1								
3602	Southington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
Stafford Count	191								
3355	Stafford	Visual Inspection	Paid	0	0	0			
3378	Stafford	Visual Inspection	Paid	0	0	0			Gutters
3389	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3419	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
3443	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3447	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3509	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3542	Stafford	Visual Inspection	Paid	0	0	0			Gutters
3586	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3608	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
3616	Stafford	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3617	Stafford	Visual Inspection	Paid	1	0	0		Floor and walls both	
3625	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3639	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
3648	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3707	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3757	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
3849	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
3885	Stafford	Visual Inspection	Paid	0	0	0			
3940	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3949	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3981	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
33	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
39	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
48	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
117	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
125	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
129	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
136	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
170	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
177	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
186	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
188	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
194	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
203	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
207	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
209	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
211	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
214	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
226	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
238	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
248	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
266	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
293	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
294	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2813	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2861	Stafford	Visual Inspection	Paid	1	0	0		Wall only	Gutters;Finished Basement
2871	Stafford	Visual Inspection	Paid	0	0	0			
2886	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2887	Stafford	Visual Inspection	Paid	1	0	0			
2958	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2964	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
3000	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3043	Stafford	Visual Inspection	Paid	0	0	0			
3070	Stafford	Petrographic Analysis	Paid	0	1	2.18			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3076	Stafford	Visual Inspection	Paid	0	0	0			Gutters
3105	Stafford	Visual Inspection	Paid	0	0	0			Gutters
3112	Stafford	Visual Inspection	Paid	0	0	0			
922	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
956	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
967	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
981	Stafford	Petrographic Analysis	Paid	0	0	0			
1037	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1049	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1126	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
1146	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1537	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1564	Stafford	visual	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1583	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
1585	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1589	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
1594	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains;Curtain or French Drain
1602	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
1613	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1643	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1682	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
1684	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
1687	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1691	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
1708	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
1737	Stafford	Petrographic Analysis	Paid	1	1	1.81	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1747	Stafford	Petrographic Analysis	Paid	1	1	0.81	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
360	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
361	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
382	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
383	Stafford	Visual Inspection	Paid	1	0	0			
385	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
409	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
410	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
413	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
421	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
431	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
456	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
461	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
471	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
474	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
477	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
486	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
492	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
497	Stafford	Visual Inspection	Paid	0	0	0			Gutters
499	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
502	Stafford	Visual Inspection	Paid	0	0	0			
505	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
510	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
527	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
589	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1244	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
1271	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1313	Stafford	Petrographic Analysis	Paid	1	1	29	No visible signs		Waterproofing - Exterior
1430	Stafford	Petrographic Analysis	Paid	0	1	43			
1440	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
1446	Stafford	Visual Inspection	Paid	0	0	0			Gutters
1450	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
1452	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
1453	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1474	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1479	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1480	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Footing Drains
1496	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
1507	Stafford	Petrographic Analysis	Paid	0	0	0			
1513	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1515	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1516	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3998	Stafford	Visual Inspection	Paid	0	0	0			
4007	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
4049	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
4057	Stafford	Petrographic Analysis	Paid	0	0	0			
4061	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
4081	Stafford	Visual Inspection	Paid	0	0	0			Gutters
4084	Stafford	Visual Inspection	Paid	0	0	0			
614	Stafford	Visual Inspection	Paid	0	0	0			
624	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
630	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
634	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
639	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
647	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
658	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
735	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
737	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
754	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
759	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
772	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
780	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
2155	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
2164	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2166	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters
2181	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
2186	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2226	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2232	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2234	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2304	Stafford	Visual Inspection	Paid	0	0	0			
2319	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2328	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2392	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2399	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2401	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2449	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2458	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2465	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2495	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2499	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2501	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2504	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2540	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2546	Stafford	Visual Inspection	Paid	1	0	0	No visible signs		Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2549	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
2561	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
2600	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2655	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
2710	Stafford	Visual Inspection	Paid	0	0	0			
1929	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1935	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
1938	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
1952	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Footing Drains
1958	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
1964	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
1973	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2010	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2011	Stafford	Petrographic Analysis	Paid	1	1	1.3	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
2015	Stafford	Petrographic Analysis	Paid	0	1	1			Gutters
2023	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2032	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2037	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2051	Stafford	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
2067	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2072	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2084	Stafford	Visual Inspection	Paid	0	0	0			Gutters
2103	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
2111	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2126	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Stafford Springs Count	1								

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3893	Stafford Springs	Petrographic Analysis	Paid	1	1	2.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
STAFFORD SPGS Count	1								
2467	STAFFORD SPGS	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
Stafford Springs Count	46								
2738	Stafford Springs	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1969	Stafford Springs	Visual Inspection	Paid	0	0	0			
1999	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2029	Stafford Springs	Petrographic Analysis	Paid	1	1	3.16	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2030	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
1617	Stafford Springs	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1676	Stafford Springs	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
1821	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3381	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3524	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
914	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
974	Stafford Springs	Petrographic Analysis	Paid	1	1	23	Don't know	Floor and walls both	Gutters - With Extension
1044	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
1062	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1081	stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1089	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1115	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
1143	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
3001	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3002	Stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3003	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
3004	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3013	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3101	Stafford springs	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
3106	Stafford Springs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3254	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
4095	Stafford Springs	Visual Inspection	Approved - Pending Payment	0	0	0			
1198	Stafford Springs	Petrographic Analysis	Paid	0	0	0			
1199	Stafford Springs	Petrographic Analysis	Paid	1	1	0		Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
1292	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Curtain or French Drain
1379	Stafford Springs	Petrographic Analysis	Paid	1	1	94	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1419	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1445	Stafford Springs	Petrographic Analysis	Paid	0	1	32			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1472	Stafford Springs	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Footing Drains
1500	STAFFORD Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2163	Stafford Springs	Petrographic Analysis	Paid	1	1	1.05	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
2189	STAFFORD SPRINGS	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
2251	Stafford springs	Visual Inspection	Paid	0	0	0			Gutters
2310	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
2330	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2363	stafford springs	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
2421	Stafford Springs	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	
765	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
827	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
828	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
830	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
Stafford Springs, Count		1							

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1504	Stafford Springs,	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Staffordville Count	1								
3535	Staffordville	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
Stamford Count	#REF!								
Storrs Count	4								
2070	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3627	Storrs	Visual Inspection	Paid	0	0	0			Gutters
757	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
3184	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
Storrs Mansfield Count	7								
2823	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2974	Storrs Mansfield	Visual Inspection	Paid	0	0	0			
942	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1074	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.57			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
632	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
1982	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.43			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
2279	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
Storrs-Mansfield Count	1								
2019	Storrs-Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
Suffield Count	49								
2079	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2746	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2825	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2875	Suffield	Visual Inspection	Paid	0	0	0			Gutters
2890	Suffield	Visual Inspection	Paid	0	0	0			
2910	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1248	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1270	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2447	Suffield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2683	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2701	Suffield	Petrographic Analysis	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2733	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
15	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3038	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
3050	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3223	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3237	Suffield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
3281	Suffield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
1534	Suffield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1535	Suffield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1541	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1806	Suffield	Visual Inspection	Paid	0	0	0			
3713	Suffield	Visual Inspection	Paid	0	0	0			
3779	Suffield	Petrographic Analysis	Paid	1	1	70	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3794	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3930	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2173	Suffield	Visual Inspection	Paid	0	0	0			
2184	Suffield	Petrographic Analysis	Paid	0	0	0			
2280	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2397	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
2416	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2417	Suffield	Petrographic Analysis	Paid	0	0	0			
910	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
976	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1007	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1149	Suffield	Visual Inspection	Paid	0	0	0			
380	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
396	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
397	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
398	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
459	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
507	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
580	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3394	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3450	Suffield	Visual Inspection	Paid	0	0	0			Gutters
3607	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3662	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
804	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
4045	Suffield	Visual Inspection	Paid	0	0	0			Gutters
Thompson Count	1								
918	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Tolland Count	681								
903	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
905	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
929	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
931	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
932	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
936	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
939	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
952	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
958	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
960	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
972	Tolland	Petrographic Analysis	Paid	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
973	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
979	Tolland	Petrographic Analysis	Paid	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
985	Tolland	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
986	Tolland	Visual Inspection	Paid	0	0	0			
992	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1001	Tolland	Petrographic Analysis	Paid	0	0	0			
1009	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1015	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1018	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1031	Tolland	Visual Inspection	Paid	0	0	0			
1033	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1039	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1041	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains
1045	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1060	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1067	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1072	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1077	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
1079	Tolland	Petrographic Analysis	Paid	1	1	1.21	No visible signs		Gutters
1083	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
1091	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1099	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1100	Tolland	Petrographic Analysis	Paid	1	1	0			
1105	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1109	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1110	Tolland	Petrographic Analysis	Paid	0	1	0.89			Waterproofing - Exterior;Gutters;Footing Drains
1116	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
1120	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1122	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1127	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1129	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
1131	Tolland	Visual Inspection	Paid	0	0	0			
1148	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1150	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
1156	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1157	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1162	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1164	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
1173	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1175	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
1176	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1183	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1184	Tolland	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1186	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1188	Tolland	Petrographic Analysis	Paid	1	1	1.61	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
1189	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
1191	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
1194	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
1196	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1532	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1546	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1566	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
1567	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1568	Tolland	Petrographic Analysis	Paid	1	1	51	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1572	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
1573	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
1582	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1590	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
1591	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1596	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1600	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1608	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1615	Tolland	Visual Inspection	Paid	0	0	0			
1619	Tolland	Petrographic Analysis	Paid	1	1	0.81	Don't know	Wall only	Waterproofing - Exterior;Gutters
1623	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
1632	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1637	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1638	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1639	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1644	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
1651	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
1652	Tolland	Visual Inspection	Paid	0	0	0			
1657	Tolland	Visual Inspection	Paid	0	0	0			
1660	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
1664	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
1666	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1675	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
1694	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1697	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1705	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1706	Tolland	Petrographic Analysis	Paid	1	1	70	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1713	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1714	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1726	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1730	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1733	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
1734	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1736	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1738	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1741	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
1746	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
1750	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1757	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
1781	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1795	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1801	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Curtain or French Drain
1803	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1808	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
1812	Tolland	Visual Inspection	Paid	0	0	0			
1816	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
1824	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1830	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1204	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
1205	Tolland	Visual Inspection	Paid	0	0	0			
1214	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
1215	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1217	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
1225	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1242	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1247	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1249	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1263	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1264	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1265	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1273	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1275	Tolland	Petrographic Analysis	Paid	1	1	2.88	Minor degradation	Floor and walls both	Gutters;Finished Basement
1277	Tolland	Petrographic Analysis	Paid	0	1	0.78			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1282	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1285	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1286	Tolland	Petrographic Analysis	Paid	0	1	1.49			Curtain or French Drain
1288	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
1296	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1298	Tolland	Visual Inspection	Paid	0	0	0			
1299	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
1318	Tolland	Petrographic Analysis	Paid	0	1	0.81			Gutters;Gutters - With Extension
1327	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
1334	Tolland	Petrographic Analysis	Paid	0	1	28			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
1337	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1340	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
1350	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1372	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
1377	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1389	Tolland	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1390	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1393	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1398	Tolland	Petrographic Analysis	Paid	0	0	0			
1422	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
1423	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1431	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1442	Tolland	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1448	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1449	Tolland	Visual Inspection	Paid	0	0	0			
1461	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1463	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1465	Tolland	Visual Inspection	Paid	1	0	0	Don't know		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1476	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
1519	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1523	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1834	Tolland	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
1853	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1854	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1855	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1857	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1861	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1870	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
1882	Tolland	Petrographic Analysis	Paid	1	1	34		Wall only	Waterproofing - Exterior;Gutters
1883	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters
1885	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1887	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1897	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1903	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
1907	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
1910	Tolland	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
1914	Tolland	Petrographic Analysis	Paid	1	1	0.45	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
1917	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1920	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1925	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
1927	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		
1937	Tolland	Petrographic Analysis	Paid	0	0	0			
1939	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
1942	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1950	Tolland	Visual Inspection	Paid	0	0	0			Gutters
1951	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
1957	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1970	Tolland	Visual Inspection	Paid	0	0	0			
1981	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
1985	Tolland	Visual Inspection	Paid	0	0	0			
1992	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
1995	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
2000	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
2001	Tolland	Visual Inspection	Paid	0	0	0			
2006	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2013	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2026	Tolland	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2027	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2041	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2043	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2054	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
2056	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
2057	Tolland	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
2064	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2066	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2068	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2071	Tolland	Visual Inspection	Paid	0	0	0			
2075	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2080	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2098	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2099	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2100	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2102	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2104	Tolland	Petrographic Analysis	Paid	1	1	73	Minor degradation	Floor and walls both	Finished Basement
2105	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
2106	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2110	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
2112	Tolland	Petrographic Analysis	Paid	0	1	0			Finished Basement
2113	Tolland	Petrographic Analysis	Paid	1	1	50	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2114	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2119	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
2124	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains
2133	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2749	Tolland	Visual Inspection	Paid	0	0	0			
2751	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2756	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2768	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2773	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2776	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2778	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
2791	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2792	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2800	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
2802	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
2810	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2812	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2833	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2848	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
2859	Tolland	Petrographic Analysis	Paid	0	1	0.69			Gutters;Finished Basement
2860	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2870	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2874	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2876	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2902	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2903	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2923	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2929	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2934	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2936	Tolland	Visual Inspection	Paid	0	0	0			
2939	Tolland	Visual Inspection	Paid	0	0	0			
2940	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
2950	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
2959	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
2966	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
2967	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2971	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2977	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2981	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2983	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2987	Tolland	Visual Inspection	Paid	0	0	0			
2994	Tolland	Visual Inspection	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2996	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3005	Tolland	Petrographic Analysis	Paid	1	1	2.51	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
3027	Tolland	Petrographic Analysis	Paid	1	1	3.54	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
3029	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3031	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3037	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3045	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3057	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3058	Tolland	Visual Inspection	Paid	0	0	0			
3059	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains
3062	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3066	Tolland	Visual Inspection	Paid	0	0	0			
3067	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3068	Tolland	Petrographic Analysis	Paid	0	0	0			
3075	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters
3095	Tolland	Visual Inspection	Paid	0	0	0			
3099	Tolland	Visual Inspection	Paid	0	0	0			
3100	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3108	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3109	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3118	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3124	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
3137	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3149	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3153	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3158	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
3165	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
3166	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3171	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3195	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3225	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3243	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3244	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3248	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3263	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3273	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3301	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3312	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2428	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
2432	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2446	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2455	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2469	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2470	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
2476	Tolland	Visual Inspection	Paid	0	0	0			
2477	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2494	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2496	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2497	Tolland	Petrographic Analysis	Paid	1	1	1.09	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2533	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2545	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2560	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2588	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2589	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
2591	Tolland	Petrographic Analysis	Paid	1	1	2.06	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
2598	Tolland	Visual Inspection	Paid	0	0	0			
2599	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
2605	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
2609	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2611	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2612	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
2614	Tolland	Petrographic Analysis	Paid	0	0	0			
2625	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2633	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2640	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2642	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
2643	Tolland	Visual Inspection	Paid	1	0	0			Gutters
2648	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2662	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2671	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2675	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2681	Tolland	Petrographic Analysis	Paid	0	1	0.09			Waterproofing - Exterior;Gutters;Footing Drains
2691	Tolland	Visual Inspection	Paid	0	0	0			
2695	Tolland	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2704	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
2705	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2706	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2708	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
2711	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
2714	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
2723	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
2739	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
1	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
3	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
5	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
6	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
7	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
10	Tolland	Visual Inspection	Paid	0	0	0			Gutters
12	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
16	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
17	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
18	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
20	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
23	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
24	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
25	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
26	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
28	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
30	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
36	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
40	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
41	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
44	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
45	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
50	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
52	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
63	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
64	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
66	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
70	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
74	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
76	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
79	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
80	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
85	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
86	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
91	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
92	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
100	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
101	Tolland	Visual Inspection	Paid	0	0	0			
103	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
109	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
114	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
115	Tolland	Visual Inspection	Paid	1	0	0			
116	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
120	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
122	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
131	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
132	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
133	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
140	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
143	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
145	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
148	Tolland	Visual Inspection	Paid	0	0	0			
155	Tolland	Visual Inspection	Paid	0	0	0			
164	Tolland	Visual Inspection	Paid	0	0	0			Gutters
172	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
175	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
178	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
179	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
185	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
187	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
189	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
190	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
196	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
197	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
202	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
204	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
208	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
210	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
216	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
219	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
220	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
224	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
225	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
228	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
239	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
242	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
244	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
246	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
249	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
252	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
254	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
255	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
258	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
265	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
267	Tolland	Visual Inspection	Paid	0	0	0			
268	Tolland	Petrographic Analysis	Paid	0	0	0			
269	tolland	Visual Inspection	Paid	0	0	0			
270	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
287	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
295	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
297	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3995	Tolland	Visual Inspection	Paid	0	0	0			Gutters
4004	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
4009	Tolland	Visual Inspection	Paid	0	0	0			
4023	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
4043	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
4059	Tolland	Visual Inspection	Paid	0	0	0			Gutters
4078	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
4088	Tolland	Visual Inspection	Paid	1	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
4089	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
607	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
628	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
641	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
645	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
646	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
650	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
654	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
669	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
672	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
679	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
681	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
685	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
686	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
687	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
688	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
691	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
697	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
700	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
701	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
706	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
709	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
711	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
715	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
732	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
740	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
741	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
747	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
758	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
764	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
768	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
769	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
770	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
773	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
781	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
783	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
795	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
796	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
797	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
798	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
818	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
826	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
829	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
831	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
832	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
834	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
843	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
889	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
895	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3669	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3672	Tolland	Visual Inspection	Paid	0	0	0			
3676	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3681	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
3689	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
3696	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3716	Tolland	Visual Inspection	Paid	1	0	0			
3724	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3725	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3731	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
3732	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Wall only	
3736	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3742	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
3745	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3760	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3765	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3811	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3826	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
3827	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3831	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3853	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3855	Tolland	Visual Inspection	Paid	1	0	0			
3887	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3894	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	
3896	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
3904	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3905	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3910	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
3917	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3922	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3932	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3953	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3956	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
3977	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3979	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
3984	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3988	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Gutters - With Extension
3989	Tolland	Petrographic Analysis	Paid	1	1	3.08	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
2137	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
2144	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2149	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
2152	Tolland	Visual Inspection	Paid	0	0	0			
2167	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2177	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2180	Tolland	Petrographic Analysis	Paid	1	1	1.19	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2196	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2202	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2207	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2208	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2211	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2216	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2225	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2236	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2237	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2243	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2261	Tolland	Petrographic Analysis	Paid	1	1	84	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
2267	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2286	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2288	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2292	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2299	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2313	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
2316	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2320	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2332	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
2340	Tolland	Visual Inspection	Paid	0	0	0			
2344	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2346	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2349	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
2354	Tolland	Visual Inspection	Paid	0	0	0			Gutters
2359	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2360	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2361	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2370	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2378	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2381	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2382	Tolland	Petrographic Analysis	Paid	0	1	14			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2385	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2391	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
2395	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2410	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2411	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2413	Tolland	Visual Inspection	Paid	0	0	0			
2415	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2424	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
3323	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
3327	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
3330	Tolland	Visual Inspection	Paid	0	0	0			
3338	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3369	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
3382	Tolland	Petrographic Analysis	Paid	0	1	2.07			Gutters
3385	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3390	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3404	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3417	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3422	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3423	Tolland	Visual Inspection	Paid	0	0	0			
3427	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3431	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3435	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Footing Drains
3436	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3437	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
3438	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
3444	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3502	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3503	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3516	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3522	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
3525	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3531	Tolland	Visual Inspection	Paid	0	0	0			
3536	Tolland	Petrographic Analysis	Paid	0	1	0.67			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
3541	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
3544	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
3560	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
3561	Tolland	Visual Inspection	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3565	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Curtain or French Drain
3569	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3572	Tolland	Visual Inspection	Paid	0	0	0			
3573	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
3578	Tolland	Visual Inspection	Paid	0	0	0			Gutters
3588	Tolland	Visual Inspection	Paid	0	0	0			
3590	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3596	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3609	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
3611	Tolland	Visual Inspection	Paid	0	0	0			
3619	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3633	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3638	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
3653	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
3654	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3655	Tolland	Visual Inspection	Paid	0	0	0			
3661	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3665	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3667	Tolland	Visual Inspection	Paid	0	0	0			
299	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
322	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
324	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
329	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
330	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
336	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
342	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
347	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
355	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
358	Tolland	Visual Inspection	Paid	0	0	0			Gutters
359	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
367	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
372	Tolland	Visual Inspection	Paid	0	0	0			
384	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
399	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
400	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
401	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
402	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
404	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
406	Tolland	Visual Inspection	Paid	0	0	0			Gutters
415	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
417	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
419	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
425	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
432	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
433	Tolland	Visual Inspection	Paid	0	0	0			
440	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
441	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
444	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
463	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
469	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
476	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
483	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
487	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
488	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
490	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
491	Tolland	Visual Inspection	Paid	0	0	0			Gutters
493	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
494	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
503	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
514	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
532	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
536	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
537	Tolland	Visual Inspection	Paid	0	0	0			
539	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
542	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
544	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
546	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
559	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
563	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
564	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
565	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
568	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
570	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
577	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
581	Tolland	Visual Inspection	Paid	0	0	0			Gutters
584	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
591	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Union Count	30								
2442	Union	Visual Inspection	Paid	0	0	0			Finished Basement
1437	Union	Petrographic Analysis	Paid	0	1	0.95			Waterproofing - Exterior;Footing Drains
1525	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
975	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
993	Union	Petrographic Analysis	Paid	1	1	1.8	Minor degradation	Wall only	Finished Basement
1106	Union	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1107	Union	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
1113	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1805	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
1829	Union	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3287	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
1984	Union	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2020	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2925	Union	Visual Inspection	Paid	0	0	0			
3318	Union	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
3320	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
3415	Union	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
3571	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Footing Drains
689	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
742	Union	Petrographic Analysis	Paid	0	0	0			
774	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
21	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
87	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
150	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
156	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
213	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
4013	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2156	Union	Petrographic Analysis	Paid	0	1	74			Gutters;Finished Basement
2362	Union	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3771	Union	Petrographic Analysis	Paid	0	1	0.86			Gutters
Vernon Count	213								
3695	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3705	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
3715	Vernon	Visual Inspection	Paid	0	0	0			
3772	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
3780	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3838	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3854	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3878	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
3890	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	
3901	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
3912	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
3933	Vernon	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters
3950	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3954	Vernon	Visual Inspection	Paid	0	0	0			Gutters
1836	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1908	Vernon	Petrographic Analysis	Paid	0	0	0			
1911	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
1922	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1944	Vernon	Visual Inspection	Paid	0	0	0			Gutters
1977	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
1983	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
1986	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
1993	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2060	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
2085	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
2086	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2125	Vernon	Visual Inspection	Paid	0	0	0			

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1201	Vernon	Petrographic Analysis	Paid	0	1	1.1			Waterproofing - Exterior;Gutters
1211	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
1300	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
1315	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1333	Vernon	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
1336	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1344	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
1347	Vernon	Visual Inspection	Paid	0	0	0			
1438	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1459	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1466	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
1486	Vernon	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
1498	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
1524	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
298	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
300	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
306	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
315	Vernon	Visual Inspection	Paid	0	0	0			
317	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
357	Vernon	Visual Inspection	Paid	0	0	0			Gutters
376	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
387	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
427	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
429	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
435	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
460	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
472	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
518	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
526	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
533	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
541	Vernon	Visual Inspection	Paid	0	0	0			Gutters
557	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
574	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
585	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
599	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
600	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
2445	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
2456	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
2514	Vernon	Visual Inspection	Paid	0	0	0			
2518	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2531	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
2539	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2606	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
2616	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2656	Vernon	Visual Inspection	Paid	0	0	0			
2665	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
2673	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2696	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2715	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2725	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3089	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3116	Vernon	Visual Inspection	Paid	0	0	0			
3142	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3148	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3175	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
3211	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3240	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3249	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
3277	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
3299	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3315	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
906	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
908	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
919	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
924	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
933	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
946	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
953	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
962	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
963	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
970	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
971	Vernon	Visual Inspection	Paid	0	0	0			
982	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1005	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
1022	Vernon	Petrographic Analysis	Paid	0	0	0			
1085	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
1112	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1121	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1135	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
1178	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1181	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1185	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
1542	Vernon	Visual Inspection	Paid	0	0	0			
1580	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
1607	Vernon	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1620	Vernon	Visual Inspection	Paid	0	0	0			Gutters
1630	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
1656	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1699	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1773	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
1779	Vernon	Visual Inspection	Paid	0	0	0			
1826	Vernon	Petrographic Analysis	Paid	0	1	0.83			Gutters;Gutters - With Extension;Finished Basement
2151	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
2220	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
2240	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2242	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2248	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
2255	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
2256	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
2274	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2278	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
2295	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
2333	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
623	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
629	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
657	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
671	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
675	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
683	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
690	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
702	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
707	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
708	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
713	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
718	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
719	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
729	Vernon	Petrographic Analysis	Paid	0	0	0			
734	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
767	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
775	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
787	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
799	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
802	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
839	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
874	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
880	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
891	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
893	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement
896	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
2758	Vernon	Petrographic Analysis	Paid	1	1	58	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2759	Vernon	Visual Inspection	Paid	0	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2782	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2789	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2809	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Footing Drains
2845	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
2851	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2853	Vernon	Petrographic Analysis	Paid	1	1	2.07	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2858	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2862	Vernon	Visual Inspection	Paid	0	0	0			
2893	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2895	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2896	Vernon	Petrographic Analysis	Paid	1	1	0.5	Minor degradation	Wall only	Gutters;Finished Basement
2898	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
2899	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
2913	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
2915	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2922	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
2953	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
2957	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
2961	Vernon	Visual Inspection	Paid	0	0	0			Gutters
2982	Vernon	Petrographic Analysis	Paid	1	1	3.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
2991	Vernon	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
3334	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
3339	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
3347	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
3356	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3400	Vernon	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Wall only	Gutters
3416	Vernon	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
3453	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
3505	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
3511	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3517	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
3519	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3548	Vernon	Visual Inspection	Paid	0	0	0			Gutters
3553	Vernon	Visual Inspection	Paid	0	0	0			
3604	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Gutters - With Extension
3612	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
3642	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
4014	Vernon	Petrographic Analysis	Paid	0	0	0			
51	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
58	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
83	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
121	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
142	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
154	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
171	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
181	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
184	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
233	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
236	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
253	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
261	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
276	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
286	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
289	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
292	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
Vernon Rockville Count	2								
2005	Vernon Rockville	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3111	Vernon Rockville	Visual Inspection	Paid	0	0	0			
Voluntown Count	1								
2952	Voluntown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Waterbury Count	#REF!								
Waterford Count	#REF!								
West Granby Count	1								
2231	West Granby	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
West Hartford Count	2								
3881	West Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3260	West Hartford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
WEST WILLINGTON Count	1								
2541	WEST WILLINGTON	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
Wethersfield Count	2								
2720	Wethersfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
455	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
Willimantic Count	1								
2753	Willimantic	Visual Inspection	Paid	0	0	0			
Willington Count	176								
2757	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
2772	Willington	Visual Inspection	Paid	0	0	0			
2816	Willington	Visual Inspection	Paid	0	0	0			Gutters
2822	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2864	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
2865	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
2866	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2873	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2883	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2892	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2917	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2918	Willington	Petrographic Analysis	Paid	1	1	0.82	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
2919	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2932	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
2938	Willington	Visual Inspection	Paid	0	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Footing Drains
2942	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2946	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
2975	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3011	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
3996	Willington	Visual Inspection	Paid	0	0	0			
4002	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
4033	Willington	Petrographic Analysis	Paid	0	1	1.36			Gutters;Gutters - With Extension
4037	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
3709	Willington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Exterior;Gutters
3729	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
3774	Willington	Petrographic Analysis	Paid	1	1	33	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement
3833	Willington	Visual Inspection	Paid	0	0	0			
3913	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
3929	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
3983	Willington	Visual Inspection	Paid	0	0	0			
3985	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
2451	Willington	Visual Inspection	Paid	0	0	0			Gutters
2453	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Gutters - With Extension
2472	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
2481	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2491	Willington	Visual Inspection	Paid	0	0	0			
2508	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2587	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
2597	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
2629	Willington	Visual Inspection	Paid	0	0	0			Gutters
2699	Willington	Visual Inspection	Paid	0	0	0			
2726	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
2734	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains
2737	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1835	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
1898	Willington	Petrographic Analysis	Paid	1	1	0.85	Don't know	Floor and walls both	Gutters;Finished Basement
1899	Willington	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
1901	Willington	Petrographic Analysis	Paid	1	1	54	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
1902	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1932	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
1940	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
1967	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
1978	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
1979	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement
1987	Willington	Petrographic Analysis	Paid	0	1	1.74			Gutters;Footing Drains;Curtain or French Drain
2021	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2050	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
2092	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
2093	Willington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
2095	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
2107	Willington	Petrographic Analysis	Paid	1	1	60	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
2109	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2115	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2116	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
2123	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
2179	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
2195	Willington	Petrographic Analysis	Paid	0	1	2.42			Gutters
2228	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2239	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
2241	Willington	Petrographic Analysis	Paid	1	1	1.34	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
2245	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
2253	Willington	Visual Inspection	Paid	0	0	0			
2257	Willington	Visual Inspection	Paid	0	0	0			Gutters
2273	Willington	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
2306	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
2309	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
2314	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
2336	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
2380	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
2412	Willington	Visual Inspection	Paid	0	0	0			Gutters
3387	Willington	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Interior;Gutters;Finished Basement
3411	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
3506	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
3520	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
3552	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3605	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
3630	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3631	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
899	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
926	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
948	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
950	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
1023	Willington	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
1030	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
1032	Willington	Visual Inspection	Paid	0	0	0			Gutters
1095	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
655	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
670	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
694	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
710	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
736	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
744	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
756	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
777	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
813	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
841	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1529	Willington	Petrographic Analysis	Paid	0	1	2			Gutters;Curtain or French Drain
1560	Willington	Petrographic Analysis	Paid	0	1	0.054			Gutters;Finished Basement
1601	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Footing Drains
1625	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1629	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1648	Willington	Petrographic Analysis	Paid	0	1	1.46			Gutters;Finished Basement
1711	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
1745	Willington	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
1794	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Finished Basement
1814	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
1815	Willington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters;Footing Drains
9	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
14	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
62	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
78	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
99	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
104	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
105	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
138	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
151	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
153	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
163	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
166	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
174	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
206	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
217	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
259	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
260	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
263	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
304	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
307	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
310	Willington	Visual Inspection	Paid	0	0	0			Gutters
318	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
337	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
354	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
362	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
365	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
366	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
371	Willington	Visual Inspection	Paid	0	0	0			
373	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
414	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
434	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
481	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
504	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
547	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
567	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
576	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
1208	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
1209	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1223	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
1256	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
1278	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement

All Approved and Paid ONLY

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1279	Willington	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
1304	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
1378	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
1381	Willington	Visual Inspection	Paid	0	0	0			Gutters
1382	Willington	Visual Inspection	Paid	0	0	0			
1418	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
1433	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
1460	Willington	Petrographic Analysis	Paid	0	0	0			
1491	Willington	Petrographic Analysis	Paid	1	1	2.34	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Finished Basement;Curtain or French Drain
1501	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
1528	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
3051	Willington	Visual Inspection	Paid	0	0	0			Footing Drains
3098	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
3107	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
3164	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
3199	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
3266	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
3267	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Windham Count	6								
1578	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
2632	Windham	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
3370	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
3529	Windham	Visual Inspection	Paid	0	0	0			
1222	Windham	Petrographic Analysis	Paid	0	0	0			Gutters
1467	Windham	Visual Inspection	Paid	0	0	0			Gutters
Windsor Count	10								
3671	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
3962	Windsor	Visual Inspection	Paid	0	0	0			
3964	Windsor	Visual Inspection	Paid	0	0	0			Gutters
3047	Windsor	Visual Inspection	Paid	0	0	0			Gutters
3305	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
3012	Windsor	Visual Inspection	Paid	0	0	0			Gutters

App ID	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
1884	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
3413	Windsor	Visual Inspection	Paid	0	0	0			
3515	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
3649	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
Winsted Count	1								
3147	Winsted	Petrographic Analysis	Paid	0	0	0			Gutters
Wolcott Count	1								
3712	Wolcott	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
Woodstock Count	6								
3915	Woodstock	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
3965	Woodstock	Visual Inspection	Paid	0	0	0			Gutters
60	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
1673	Woodstock	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
3343	Woodstock	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
3231	Woodstock	Visual Inspection	Paid	0	0	0			Gutters - With Extension