

July ONLY

Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
26								
1								
Avon	Visual Inspection	Pending	0	0	0			
1								
Bolton	Visual Inspection	Pending	0	0	0			Gutters
1								
Broad Brook	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Footing Drains;Curtain or French Drain
1								
Columbia	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
3								
Ellington	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
Ellington	Visual Inspection	Pending	0	0	0			Gutters;Finished Basement
Ellington	Visual Inspection	Approved - Pending Payment	0	0	0			
1								
Glastonbury	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
2								
Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
2								
Mansfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
Mansfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1								
Plainfield	Visual Inspection	Pending	0	0	0			
2								
Somers	Visual Inspection	Approved - Pending Payment	1	0	0	Don't know	Wall only	
Somers	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
4								
South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0		Floor and walls both	Finished Basement
South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
1								

July ONLY

Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
Stafford	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
3								
Tolland	Visual Inspection	Paid	0	0	0			
Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters
Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
2								
Vernon	Visual Inspection	Pending	0	0	0			Gutters
Vernon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
1								
Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Grand Count</b>	3638								
<b>Amston Count</b>	5								
	Amston	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Amston	Visual Inspection	Paid	0	0	0			Gutters
<b>Andover Count</b>	31								
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Andover	Petrographic Analysis	Paid	0	0	0			
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Andover	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
<b>Ashford Count</b>	76								
	Ashford	Petrographic Analysis	Paid	1	1	43	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Petrographic Analysis	Paid	1	1	32	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior
	Ashford	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Paid	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	1.38	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Petrographic Analysis	Paid	1	1	1	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0	Don't know		
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Paid	1	1	1.35	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
<b>Avon Count</b>	4								

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Avon	Visual Inspection	Paid	0	0	0			
	Avon	Visual Inspection	Paid	0	0	0			
	Avon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Avon	Visual Inspection	Paid	0	0	0			
<b>Berlin Count</b>	1								
	Berlin	Visual Inspection	Paid	0	0	0			
<b>Bloomfield Count</b>	9								
	Bloomfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Bloomfield	Visual Inspection	Paid	0	0	0			
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
<b>Bolton Count</b>	66								
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	1	11			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	No visible signs		Gutters - With Extension;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Bolton	Visual Inspection	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	1	0.87			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	1	1.2			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Petrographic Analysis	Paid	1	1	1	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	1	2.15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Petrographic Analysis	Paid	0	1	0.66			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
<b>Bristol Count</b>	1								
	Bristol	Visual Inspection	Paid	0	0	0			Gutters
<b>BROAD BROOK Count</b>	5								
	BROAD BROOK	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Broad Brook	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	broad brook	Visual Inspection	Paid	0	0	0			Gutters
	Broad Brook	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Broad Brook	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Footing Drains;Curtain or French Drain
<b>Broadbrook Count</b>	1								
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
<b>Brooklyn Count</b>	2								
	Brooklyn	Visual Inspection	Paid	0	0	0			
	Brooklyn	Visual Inspection	Paid	0	0	0			Gutters
<b>Canterbury Count</b>	1								
	Canterbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
<b>Canton Count</b>	2								
	Canton	Visual Inspection	Paid	0	0	0			Gutters
	Canton	Visual Inspection	Paid	0	0	0			Gutters
<b>Chaplin Count</b>	3								
	Chaplin	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Chaplin	Visual Inspection	Paid	0	0	0			
	Chaplin	Visual Inspection	Paid	0	0	0			
<b>Cheshire Count</b>	2								
	Cheshire	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Cheshire	Visual Inspection	Paid	0	0	0			
<b>Colchester Count</b>	7								
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Colchester	Visual Inspection	Paid	0	0	0			Gutters
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
<b>Columbia Count</b>	26								
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	0	0	0			Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Columbia	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	0	0	0			Gutters
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	1	0	0	No visible signs		Gutters
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
<b>Coventry Count</b>	255								
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	0		Wall only	
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	0.55			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	34	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	1	1	0.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	COVENTRY	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	1	54			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
<b>Cromwell Count</b>		1							
	Cromwell	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
<b>Durham Count</b>	#REF!								
<b>East Granby Count</b>		4							
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	East Granby	Petrographic Analysis	Paid	0	0	0			Gutters
<b>East Hampton Count</b>		6							
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hampton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters
<b>East Hartford Count</b>		10							
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters
	East Hartford	Visual Inspection	Paid	0	0	0			
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Hartford	Visual Inspection	Paid	0	0	0			Finished Basement
	East Hartford	Visual Inspection	Paid	0	0	0			
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
<b>East Lyme Count</b>	#REF!								
<b>East Windsor Count</b>	55								
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	1	1.41			Gutters;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	1	1	1.05	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	1	1	0.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Petrographic Analysis	Paid	0	1	29			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Eastford Count</b>	3								
	Eastford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Eastford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
<b>Ellington Count</b>	269								
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Ellington	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
	Ellington	Visual Inspection	Approved - Pending Payment	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	1.81	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	2.28	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	1.52			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.57			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0.5			Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Interior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Gutters;Gutters - With Extension;Capillary Break
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	1.86			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	1	1.86	Don't know		Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.69			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	1	1	1.57	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0.71			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.7			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	2.21	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0	No visible signs		
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	36			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
<b>Enfield Count</b>	92								
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.88	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Petrographic Analysis	Paid	1	1	27	Don't know	Concrete floor only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Petrographic Analysis	Paid	0	1	0.13			
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	1	1	0.62	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	1	0.45	No visible signs	Wall only	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	33		Wall only	Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	59	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.39	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Petrographic Analysis	Paid	1	1	0.89	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Petrographic Analysis	Paid	1	1	1.14	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	0.51			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation		Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	1.46			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Petrographic Analysis	Paid	0	1	0.24			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Farmington Count</b>	3								
	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Farmington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
<b>Glastonbury Count</b>	69								
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0	No visible signs		
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	GLASTONBURY	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Capillary Break
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
<b>Granby Count</b>		2							
	Granby	Visual Inspection	Paid	0	0	0			Gutters
	Granby	Visual Inspection	Paid	0	0	0			
<b>Griswold Count</b>	#REF!								
<b>Haddam Count</b>		1							
	Haddam	Visual Inspection	Paid	0	0	0			Gutters - With Extension
<b>Hamden Count</b>	#REF!								
<b>Hampton Count</b>		5							
	Hampton	Visual Inspection	Paid	0	0	0			Gutters
	Hampton	Visual Inspection	Paid	0	0	0			
	Hampton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Hampton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Hampton	Visual Inspection	Paid	0	0	0			
<b>Hartford Count</b>	#REF!								
<b>Hebron Count</b>		35							
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Hebron	Petrographic Analysis	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Petrographic Analysis	Paid	0	1	0.73			Waterproofing - Exterior;Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
<b>Killingly Count</b>	2								
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
<b>Killingworth Count</b>	1								
	Killingworth	Visual Inspection	Paid	0	0	0			
<b>Lebanon Count</b>	6								
	Lebanon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Lebanon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Curtain or French Drain
<b>Longmeadow Count</b>	#REF!								
<b>Lyme Count</b>	1								
	Lyme	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
<b>Madison Count</b>	#REF!								
<b>Manchester Count</b>	301								
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	manchester	Petrographic Analysis	Paid	0	1	29			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	56	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	2.41	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	68	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	1	1.69			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters
	Manchester	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	2.49	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	1	1	55	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Manchester	Petrographic Analysis	Paid	1	1	2.58	Don't know	Floor and walls both	Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0		Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	30	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	1	1	2.67	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	0	1	2			
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
<b>Mansfield Count</b>	123								
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	1	0.54			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Mansfield	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Mansfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	1	0.52			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	1	0.68			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
<b>Mansfield Center Count</b>	5								
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Mansfield Center	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
<b>Marlborough Count</b>		8							
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters
	Marlborough	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Marlborough	Petrographic Analysis	Paid	0	0	0			Gutters
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Middletown Count</b>		2							
	Middletown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Middletown	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
<b>New Haven Count</b>	#REF!								
<b>Newington Count</b>		2							
	Newington	Visual Inspection	Paid	0	0	0			Finished Basement
	Newington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
<b>Northford Count</b>	#REF!								
<b>Norwich Count</b>		1							
	Norwich	Visual Inspection	Paid	0	0	0			
<b>Plainfield Count</b>		2							
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Plainfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Plantsville Count</b>	#REF!								
<b>Pomfret Count</b>		2							
	Pomfret	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Pomfret	Visual Inspection	Paid	0	0	0			Gutters
<b>Portland Count</b>		6							
	Portland	Visual Inspection	Paid	0	0	0			Gutters
	Portland	Visual Inspection	Paid	0	0	0			Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Portland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Portland	Visual Inspection	Paid	0	0	0			
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters
	Portland	Visual Inspection	Paid	0	0	0			Gutters
<b>Rocky Hill Count</b>	1								
	Rocky Hill	Visual Inspection	Paid	0	0	0			
<b>S Glastonbury Count</b>	1								
	S Glastonbury	Visual Inspection	Paid	0	0	0			
<b>Simsbury Count</b>	1								
	Simsbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
<b>Somers Count</b>	141								
	Somers	Petrographic Analysis	Paid	0	1	1.33			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	1.51			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Somers	Visual Inspection	Approved - Pending Payment	1	0	0	Don't know	Wall only	
	Somers	Petrographic Analysis	Paid	0	1	0.48			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	1	1	0.64	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Footing Drains
	Somers	Petrographic Analysis	Paid	1	1	1.32	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	1.32			Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	0	1	0.92			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	0.79			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.63			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	1	1	0.54	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	1.31			Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	1	1	16	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	0	1	2.37			Gutters;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
<b>South Glastonbury Count</b>	7								
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			
	South Glastonbury	Petrographic Analysis	Paid	1	1	35	Don't know	Wall only	

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>South Windsor Count</b>	488								
	South Windsor	Petrographic Analysis	Paid	0	1	2.37			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0.76			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	33			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0		Floor and walls both	Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	1.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	26			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	0.48	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0.45			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.63			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	23	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	38			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0		Wall only	
	South Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	28			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	29	Don't know	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	0.99	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	SOUTH WINDSOR	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0		Floor and walls both	Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	43			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.4			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	30	No visible signs		Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	11			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0.77			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Interior;Gutters;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	0.8			
	South Windsor	Petrographic Analysis	Paid	1	1	1.67	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	1.35			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	1.33			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	3.22	Don't know	Wall only	Gutters;Curtain or French Drain
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	2.96	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Petrographic Analysis	Paid	0	1	1.81			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	0	1	86			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
<b>South Windssor Count</b>	1								
	South Windssor	Visual Inspection	Paid	0	0	0			Gutters
<b>Southington Count</b>	1								
	Southington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
<b>Stafford Count</b>	195								
	Stafford	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0		Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	visual	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	1.81	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	0.81	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0		Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	1	1	29	No visible signs		Waterproofing - Exterior
	Stafford	Petrographic Analysis	Paid	0	1	43			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	2.18			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	No visible signs		Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
<b>Stafford Springs Count</b>	1								
	Stafford Springs	Petrographic Analysis	Paid	1	1	2.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
<b>STAFFORD SPGS Count</b>	1								
	STAFFORD SPGS	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
<b>Stafford Springs Count</b>	48								
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	1	1	23	Don't know	Floor and walls both	Gutters - With Extension
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Stafford Springs	Visual Inspection	Paid	0	0	0			
	Stafford Springs	Visual Inspection	Paid	0	0	0			Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			
	Stafford Springs	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford springs	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
	Stafford Springs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			
	Stafford Springs	Petrographic Analysis	Paid	1	1	0		Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Curtain or French Drain
	Stafford Springs	Petrographic Analysis	Paid	1	1	94	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	0	1	32			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Footing Drains
	STAFFORD Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	1	1	1.05	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	STAFFORD SPRINGS	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	stafford springs	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	
	Stafford Springs	Visual Inspection	Paid	0	0	0			
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	1	1	3.16	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
<b>Stafford Springs, Count</b>	1								
	Stafford Springs,	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
<b>Staffordville Count</b>	1								
	Staffordville	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
<b>Stamford Count</b>	#REF!								
<b>Storrs Count</b>	4								
	Storrs	Visual Inspection	Paid	0	0	0			Gutters
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
<b>Storrs Mansfield Count</b>	7								

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.57			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.43			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
<b>Storrs-Mansfield Count</b>	1								
	Storrs-Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
<b>Suffield Count</b>	50								
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Suffield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Petrographic Analysis	Paid	1	1	70	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
<b>Thompson Count</b>	1								
	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Tolland Count</b>	705								
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	1	1	1.21	No visible signs		Gutters
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0			
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.89			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.61	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	51	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	0.81	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	70	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.09	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Tolland	Petrographic Analysis	Paid	1	1	2.06	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0.09			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	34		Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	0.45	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	73	Minor degradation	Floor and walls both	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	50	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2.88	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.78			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	1.49			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.81			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	28			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Don't know		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.69			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.51	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.54	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.19	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	84	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	14			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	2.07			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.67			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Wall only	
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.08	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
<b>Union Count</b>	30								
	Union	Petrographic Analysis	Paid	0	1	0.86			Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Union	Visual Inspection	Paid	0	0	0			Finished Basement
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Union	Petrographic Analysis	Paid	1	1	1.8	Minor degradation	Wall only	Finished Basement
	Union	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Union	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Paid	0	1	0.95			Waterproofing - Exterior;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Union	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	0	0	0			
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Union	Petrographic Analysis	Paid	0	0	0			
	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Union	Petrographic Analysis	Paid	0	1	74			Gutters;Finished Basement
	Union	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
<b>Vernon Count</b>	219								
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	1.1			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	0	1	0.83			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	1	1	58	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	1	1	2.07	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	0.5	Minor degradation	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	3.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
<b>Vernon Rockville Count</b>	2								
	Vernon Rockville	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon Rockville	Visual Inspection	Paid	0	0	0			
<b>Voluntown Count</b>	1								
	Voluntown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Wallingford Count</b>	#REF!								
<b>Waterbury Count</b>	#REF!								

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Waterford Count</b>	#REF!								
<b>West Granby Count</b>	1								
	West Granby	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
<b>West Hartford Count</b>	2								
	West Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	West Hartford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
<b>West Suffield Count</b>	#REF!								
<b>WEST WILLINGTON Count</b>	1								
	WEST WILLINGTON	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
<b>Wethersfield Count</b>	2								
	Wethersfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
<b>Willimantic Count</b>	1								
	Willimantic	Visual Inspection	Paid	0	0	0			
<b>Willington Count</b>	183								
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	0.82	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	0.85	Don't know	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	54	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement



All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Wilmington	Petrographic Analysis	Paid	0	1	1.74			Gutters;Footing Drains;Curtain or French Drain
	Wilmington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Wilmington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Wilmington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Wilmington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Wilmington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Wilmington	Petrographic Analysis	Paid	1	1	60	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Wilmington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Wilmington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Wilmington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Wilmington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Wilmington	Visual Inspection	Paid	0	0	0			Gutters
	Wilmington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Gutters - With Extension
	Wilmington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Wilmington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Wilmington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Wilmington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Wilmington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Wilmington	Visual Inspection	Paid	0	0	0			Gutters
	Wilmington	Visual Inspection	Paid	0	0	0			
	Wilmington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Wilmington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Wilmington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Wilmington	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Interior;Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Willington	Petrographic Analysis	Paid	0	1	2.42			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Petrographic Analysis	Paid	1	1	1.34	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Petrographic Analysis	Paid	0	1	1.36			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	0	1	2			Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.054			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	1.46			Gutters;Finished Basement

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	1	1	2.34	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Exterior;Gutters

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Wilmington	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Wilmington	Petrographic Analysis	Paid	1	1	33	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement
	Wilmington	Visual Inspection	Paid	0	0	0			
	Wilmington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Wilmington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Wilmington	Visual Inspection	Paid	0	0	0			
	Wilmington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
<b>Windham Count</b>	7								
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			
	Windham	Petrographic Analysis	Paid	0	0	0			Gutters
	Windham	Visual Inspection	Paid	0	0	0			Gutters
<b>Windsor Count</b>	11								
	Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Windsor	Visual Inspection	Paid	0	0	0			
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
<b>Winsted Count</b>	1								

All Approved and Paid ONLY

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Winsted	Petrographic Analysis	Paid	0	0	0			Gutters
<b>Wolcott Count</b>	1								
	Wolcott	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Woodstock Count</b>	6								
	Woodstock	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters
	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Woodstock	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters - With Extension
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								









All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Grand Count</b>	3988								
<b>Amston Count</b>	6								
	Amston	Visual Inspection	On Hold	0	0	0			Finished Basement;Curtain or French Drain
	Amston	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Amston	Petrographic Analysis	Paid	1	1	2.23	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Amston	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Amston	Visual Inspection	Paid	0	0	0			Gutters
<b>Andover Count</b>	34								
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Denied	0	0	0			Gutters
	Andover	Visual Inspection	Paid	0	0	0			Gutters
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Andover	Petrographic Analysis	Paid	0	0	0			
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Andover	Visual Inspection	Paid	0	0	0			
	Andover	Visual Inspection	Paid	0	0	0			
	Andover	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Andover	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Andover	Petrographic Analysis	Paid	1	1	3	Don't know	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Andover	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Andover	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Andover	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Andover	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
<b>Ashford Count</b>	81								
	Ashford	Petrographic Analysis	Paid	1	1	43	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Petrographic Analysis	Paid	1	1	32	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters
	Ashford	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Paid	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Denied	1	1	0.75	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Petrographic Analysis	Paid	1	1	1.38	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Petrographic Analysis	Paid	1	1	1	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	ASHFORD	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0	Don't know		
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ashford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Petrographic Analysis	Paid	1	1	1.33	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ashford	Petrographic Analysis	Paid	0	1	72			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ashford	Petrographic Analysis	Paid	1	1	1.35	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			
	Ashford	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ashford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Gutters
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ashford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Ashford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
<b>Avon Count</b>	5								
	Avon	Visual Inspection	Paid	0	0	0			
	Avon	Visual Inspection	Paid	0	0	0			
	Avon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Avon	Visual Inspection	Pending	0	0	0			
	Avon	Visual Inspection	Paid	0	0	0			
<b>Berlin Count</b>	4								
	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Berlin	Visual Inspection	Paid	0	0	0			
	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Berlin	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
<b>Bloomfield Count</b>	15								
	Bloomfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Denied	0	0	0			Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Bloomfield	Visual Inspection	Paid	0	0	0			
	Bloomfield	Visual Inspection	Pending DoH Approval	0	0	0			
	Bloomfield	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
	Bloomfield	Visual Inspection	Denied	0	0	0			
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bloomfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Bloomfield	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters
	Bloomfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
<b>Bolton Count</b>	74								
	Bolton	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	1	11			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	No visible signs		Gutters - With Extension;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)		Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Bolton	Visual Inspection	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	1	0.87			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	1	1.2			Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	On Hold	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bolton	Petrographic Analysis	Paid	1	1	1	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	On Hold	0	0	0			Gutters
	Bolton	Visual Inspection	Pending	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Bolton	Petrographic Analysis	Paid	0	1	2.15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Petrographic Analysis	Paid	0	1	0.66			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Bolton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	bolton	Petrographic Analysis	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Bolton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Bolton	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Bolton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Bolton	Visual Inspection	Paid	0	0	0			
	Bolton	Petrographic Analysis	Paid	0	0	0			
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Bolton	Visual Inspection	On Hold	1	0	0	No visible signs		Gutters;Curtain or French Drain
	Bolton	Visual Inspection	Paid	0	0	0			Gutters
	Bolton	Visual Inspection	Paid	0	0	0			
<b>Bristol Count</b>	3								
	Bristol	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Bristol	Visual Inspection	Denied	0	0	0			Finished Basement
	Bristol	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
<b>BROAD BROOK Count</b>	5								
	BROAD BROOK	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Broad Brook	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	broad brook	Visual Inspection	Paid	0	0	0			Gutters
	Broad Brook	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Broad Brook	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Footing Drains;Curtain or French Drain
<b>Broadbrook Count</b>	1								
	Broadbrook	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
<b>Brooklyn Count</b>	2								
	Brooklyn	Visual Inspection	Paid	0	0	0			
	Brooklyn	Visual Inspection	Paid	0	0	0			Gutters
<b>Canterbury Count</b>	1								
	Canterbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
<b>Canton Count</b>	2								
	Canton	Visual Inspection	Paid	0	0	0			Gutters
	Canton	Visual Inspection	Paid	0	0	0			Gutters
<b>Chaplin Count</b>	3								
	Chaplin	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Chaplin	Visual Inspection	Paid	0	0	0			
	Chaplin	Visual Inspection	Paid	0	0	0			
<b>Cheshire Count</b>	2								
	Cheshire	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Cheshire	Visual Inspection	Paid	0	0	0			
<b>Colchester Count</b>	9								
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Colchester	Visual Inspection	Pending DoH Approval	0	0	0			Curtain or French Drain
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Colchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Colchester	Visual Inspection	Paid	0	0	0			Gutters
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Colchester	Visual Inspection	Pending	0	0	0			
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Colchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
<b>Columbia Count</b>	27								
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	0	0	0			Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Columbia	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	Columbia	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Columbia	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Columbia	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Columbia	Visual Inspection	Paid	0	0	0			Gutters
	Columbia	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	1	0	0	No visible signs		Gutters
	Columbia	Visual Inspection	Paid	0	0	0			
	Columbia	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Columbia	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	Columbia	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Columbia	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break
<b>Coventry Count</b>	271								
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	15	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	On Hold	1	1	0		Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	0		Wall only	
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0			Gutters
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	0.55			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	34	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Denied	1	1	70	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.3	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	0	1	55			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Denied	0	0	0			
	Coventry	Visual Inspection	Denied	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	1	2.35	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	1	1	0.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16		Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	1	1	3.16	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Coventry	Petrographic Analysis	Denied	1	1	25	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Pending DoH Approval	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			
	COVENTRY	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Coventry	Petrographic Analysis	Paid	0	1	54			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Denied	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Coventry	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Coventry	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Visual Inspection	Paid	0	0	0			Finished Basement;Curtain or French Drain
	Coventry	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Coventry	Visual Inspection	Paid	0	0	0			
	Coventry	Petrographic Analysis	Paid	1	1	1.83	Don't know		Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Coventry	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Coventry	Visual Inspection	Denied	0	0	0			Gutters
	Coventry	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
<b>Cromwell Count</b>		2							
	Cromwell	Petrographic Analysis	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Cromwell	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
<b>Durham Count</b>		1							
	Durham	Visual Inspection	On Hold	0	0	0			
<b>East Granby Count</b>		5							
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	East Granby	Visual Inspection	Pending DoH Approval	0	0	0			
	East Granby	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	East Granby	Petrographic Analysis	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>East Hampton Count</b>	6								
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hampton	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hampton	Visual Inspection	Paid	0	0	0			Gutters
<b>East Hartford Count</b>	16								
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters
	East Hartford	Visual Inspection	Paid	0	0	0			
	East Hartford	Visual Inspection	Pending	0	0	0			Waterproofing - Exterior;Gutters
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	East Hartford	Visual Inspection	Paid	0	0	0			Finished Basement
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	East Hartford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hartford	Visual Inspection	On Hold	1	0	0	No visible signs		
	East Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Hartford	Visual Inspection	Pending DoH Approval	0	0	0			
	East Hartford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Hartford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	East Hartford	Visual Inspection	Denied	0	0	0			
<b>East Lyme Count</b>	2								
	East Lyme	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Lyme	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters
<b>East Windsor Count</b>	59								
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	1	1.41			Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Petrographic Analysis	Paid	1	1	1.05	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Wall only	Gutters;Gutters - With Extension;Finished Basement
	East Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			
	East Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	1	1	0.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	1	29			Waterproofing - Exterior;Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	East Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	East Windsor	Petrographic Analysis	Denied	0	0	0			
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	East Windsor	Petrographic Analysis	Paid	0	1	1.13			Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	East Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters
	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
	East Windsor	Visual Inspection	Paid	1	0	0	No visible signs		
	East Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Eastford Count</b>	3								
	Eastford	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
	Eastford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Eastford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
<b>Ellington Count</b>	285								
	Ellington	Petrographic Analysis	On Hold	1	0	0	Don't know		Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Ellington	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters
	Ellington	Visual Inspection	Approved - Pending Payment	0	0	0			
	Ellington	Visual Inspection	Pending	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Denied	0	1	11.5			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	1.15			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	1.81	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	1.7			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	2.28	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters - With Extension
	Ellington	Petrographic Analysis	Denied	0	1	0.34			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	1.52			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.57			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	1	1	24	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	0.75			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	0.5			Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Interior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Gutters;Gutters - With Extension;Capillary Break
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	6	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0	Moderate to severe (significant repairs required)		Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	1.86			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	1	1.86	Don't know		Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	16			Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Petrographic Analysis	Paid	1	1	13	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	3.38	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	0.69			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	1	1	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	1	1	1.57	Moderate to severe (significant repairs required)	Floor and walls both	
	Ellington	Visual Inspection	On Hold	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Denied	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	1	1	1.39	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Denied	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Footing Drains
	Ellington	Petrographic Analysis	Paid	0	1	0.71			Gutters;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Petrographic Analysis	Paid	0	1	0.7			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Petrographic Analysis	Paid	1	1	2.21	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Ellington	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0	No visible signs		
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Ellington	Visual Inspection	Denied	1	0	0	Minor degradation	Floor and walls both	Finished Basement;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Petrographic Analysis	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Ellington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Visual Inspection	Paid	0	0	0			Gutters
	Ellington	Petrographic Analysis	Paid	0	1	36			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Ellington	Visual Inspection	Paid	0	0	0			
	Ellington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
<b>Enfield Count</b>	96								
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.88	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Enfield	Petrographic Analysis	Paid	1	1	27	Don't know	Concrete floor only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Enfield	Visual Inspection	On Hold	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Enfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Petrographic Analysis	Paid	0	1	0.13			
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	1	1	0.62	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	1	1	0.45	No visible signs	Wall only	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	33		Wall only	Waterproofing - Exterior;Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Enfield	Petrographic Analysis	Paid	0	0	0			
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	59	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	1	1	0.39	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Petrographic Analysis	Paid	1	1	0.89	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Petrographic Analysis	Paid	1	1	1.14	Moderate to severe (significant repairs required)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			
	Enfield	Petrographic Analysis	Paid	1	1	0.51			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation		Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Enfield	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	1.46			Gutters
	Enfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters
	Enfield	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Enfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Enfield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Enfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Enfield	Petrographic Analysis	Paid	0	1	0.24			Gutters;Finished Basement
	Enfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Enfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Farmington Count</b>		3							
	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Farmington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Farmington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
<b>Glastonbury Count</b>		95							
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	On Hold	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Curtain or French Drain
	Glastonbury	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Pending DoH Approval	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Denied	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0	No visible signs		
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	On Hold	0	0	0	No visible signs		Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	GLASTONBURY	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Capillary Break
	Glastonbury	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters
	Glastonbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	Glastonbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Glastonbury	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
	Glastonbury	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Glastonbury	Visual Inspection	Paid	0	0	0			
<b>Granby Count</b>		4							
	Granby	Visual Inspection	Denied	0	0	0			Gutters
	Granby	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	Granby	Visual Inspection	Paid	0	0	0			Gutters
	Granby	Visual Inspection	Paid	0	0	0			
<b>Griswold Count</b>		1							
	Griswold	Petrographic Analysis	Pending DoH Approval	0	1	0.4			Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
<b>Haddam Count</b>		2							
	Haddam	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Haddam	Visual Inspection	Pending DoH Approval	0	0	0			Finished Basement
<b>Hamden Count</b>		1							
	Hamden	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
<b>Hampton Count</b>		5							
	Hampton	Visual Inspection	Paid	0	0	0			Gutters
	Hampton	Visual Inspection	Paid	0	0	0			
	Hampton	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Hampton	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior
	Hampton	Visual Inspection	Paid	0	0	0			
<b>Hartford Count</b>		2							
	Hartford	Visual Inspection	Pending DoH Approval	0	0	0	Minor degradation	Concrete floor only	Finished Basement
	Hartford	Visual Inspection	Denied	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Hebron Count</b>	40								
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Petrographic Analysis	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			
	Hebron	Visual Inspection	Denied	1	0	0	Don't know	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Denied	0	0	0			
	Hebron	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Hebron	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Hebron	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Hebron	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Hebron	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Hebron	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	Hebron	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Hebron	Petrographic Analysis	Paid	0	1	0.73			Waterproofing - Exterior;Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters
	Hebron	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
<b>Killingly Count</b>	2								
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Killingly	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
<b>Killingworth Count</b>	1								
	Killingworth	Visual Inspection	Paid	0	0	0			
<b>Lebanon Count</b>	6								
	Lebanon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Lebanon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Paid	0	0	0			
	Lebanon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement;Curtain or French Drain



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Longmeadow Count</b>	1								
	Longmeadow	Petrographic Analysis	On Hold	0	0	0			Gutters;Finished Basement
<b>Lyme Count</b>	1								
	Lyme	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
<b>Madison Count</b>	1								
	Madison	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement
<b>Manchester Count</b>	321								
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	manchester	Petrographic Analysis	Paid	0	1	29			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	56	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	2.41	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	1	0.12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	68	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Manchester	Petrographic Analysis	Paid	0	1	1.69			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Petrographic Analysis	Pending DoH Approval	1	1	34	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Pending DoH Approval	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters
	Manchester	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	2.49	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Don't know		Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0		Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Petrographic Analysis	On Hold	0	1	1.42			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Visual Inspection	Paid	0	0	0			Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	55	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Denied	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Manchester	Petrographic Analysis	Paid	1	1	2.58	Don't know	Floor and walls both	Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0		Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	30	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	On Hold	0	0	0			
	Manchester	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Petrographic Analysis	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	1	1	2.67	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Denied	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	MANCHESTER	Petrographic Analysis	Paid	0	1	1.5			Gutters;Gutters - With Extension;Finished Basement
	manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Capillary Break
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters
	Manchester	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			
	Manchester	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.58	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	1.9	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Manchester	Petrographic Analysis	Paid	0	1	2			
	Manchester	Petrographic Analysis	Paid	0	1	0	Don't know		Gutters;Finished Basement
	Manchester	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters
	Manchester	Petrographic Analysis	Paid	1	1	5.78	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Manchester	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
<b>Mansfield Count</b>	135								
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	14			Gutters;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	1	1	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement
	Mansfield	Visual Inspection	On Hold	0	0	0			
	Mansfield	Visual Inspection	On Hold	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Pending DoH Approval	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	1	1	0.83	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	1	0.54			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Mansfield	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	4.4			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Mansfield	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Mansfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters
	Mansfield	Petrographic Analysis	Paid	0	1	0.52			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Mansfield	Petrographic Analysis	Paid	0	1	0.68			Gutters;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Mansfield	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Petrographic Analysis	Paid	0	1	0			Gutters
	Mansfield	Visual Inspection	Denied	0	0	0			
	Mansfield	Petrographic Analysis	Paid	0	0	0			
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
<b>Mansfield Center Count</b>		7							
	Mansfield Center	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Mansfield Center	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Mansfield Center	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Mansfield Center	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Mansfield Center	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Mansfield Center	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
<b>Marlborough Count</b>		11							
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters
	Marlborough	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Footing Drains
	Marlborough	Petrographic Analysis	Paid	0	0	0			Gutters
	Marlborough	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains
	Marlborough	Visual Inspection	Pending DoH Approval	0	0	0			
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Marlborough	Visual Inspection	Pending DoH Approval	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Marlborough	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Marlborough	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
<b>Middletown Count</b>	3								
	Middletown	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Middletown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Middletown	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
<b>New Haven Count</b>	1								
	New Haven	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
<b>Newington Count</b>	2								
	Newington	Visual Inspection	Paid	0	0	0			Finished Basement
	Newington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
<b>Northford Count</b>	1								
	Northford	Visual Inspection	Pending DoH Approval	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
<b>Norwich Count</b>	1								
	Norwich	Visual Inspection	Paid	0	0	0			
<b>Plainfield Count</b>	3								
	Plainfield	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Plainfield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Plainfield	Visual Inspection	Pending	0	0	0			
<b>Plantsville Count</b>	1								
	Plantsville	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
<b>Pomfret Count</b>	3								
	Pomfret	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Pomfret	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Pomfret	Visual Inspection	Paid	0	0	0			Gutters
<b>Portland Count</b>	6								
	Portland	Visual Inspection	Paid	0	0	0			Gutters
	Portland	Visual Inspection	Paid	0	0	0			Finished Basement
	Portland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Portland	Visual Inspection	Paid	0	0	0			
	Portland	Petrographic Analysis	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Rocky Hill Count</b>	Portland	Visual Inspection	Paid	0	0	0			Gutters
	4								
	Rocky Hill	Visual Inspection	Paid	0	0	0			
	Rocky Hill	Visual Inspection	On Hold	0	0	0			
	Rocky Hill	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Rocky Hill	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
<b>S Glastonbury Count</b>	1								
	S Glastonbury	Visual Inspection	Paid	0	0	0			
<b>Simsbury Count</b>	1								
	Simsbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
<b>Somers Count</b>	147								
	Somers	Petrographic Analysis	Paid	0	1	1.33			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	On Hold	0	1	0.65			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Capillary Break



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Denied	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	1.51			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Somers	Visual Inspection	Approved - Pending Payment	1	0	0	Don't know	Wall only	
	Somers	Petrographic Analysis	Paid	0	1	0.48			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Somers	Petrographic Analysis	Paid	0	1	2			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	1	1	0.64	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Footing Drains
	Somers	Petrographic Analysis	Paid	1	1	1.32	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	1.32			Gutters;Finished Basement;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	Denied	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.94			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	0	1	0.92			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	0.79			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0.63			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	1	1	0.54	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	1	0			
	Somers	Petrographic Analysis	Paid	0	0	0			
	Somers	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	1	1	1.6	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Somers	Petrographic Analysis	Paid	0	1	1.31			Gutters;Gutters - With Extension;Finished Basement
	Somers	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Somers	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			
	Somers	Petrographic Analysis	Paid	1	1	16	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Footing Drains
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Somers	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Somers	Visual Inspection	Paid	0	0	0			Gutters
	Somers	Petrographic Analysis	Paid	0	1	2.37			Gutters;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Somers	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	Somers	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Somers	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
<b>South Glastonbury Count</b>	7								
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Glastonbury	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			
	South Glastonbury	Petrographic Analysis	Paid	1	1	35	Don't know	Wall only	
	South Glastonbury	Visual Inspection	Paid	0	0	0			Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Glastonbury	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>South Windsor Count</b>	544								

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	1	2.37			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0.76			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	33			Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0		Floor and walls both	Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	1.76	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	26			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	0.48	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	0	1	0.45			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Denied	0	0	0			Finished Basement
	South windsor	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Concrete floor only	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	40	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	south windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	25	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.63			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	1	1	23	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	38			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	On Hold	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	1	1	39	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0		Wall only	
	South Windsor	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	1	1	36		Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters
	South Windsor	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	28			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	29	Don't know	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	0.99	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Finished Basement
	South Windsor	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Denied	0	1	2			Waterproofing - Exterior;Gutters;Finished Basement



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	On Hold	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	SOUTH WINDSOR	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Approved - Pending Payment	1	0	0		Floor and walls both	Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	43			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.4			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	30	No visible signs		Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	11			Gutters
	South Windsor	Petrographic Analysis	Paid	0	1	0.77			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Denied	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	0.93			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	1.1	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	72	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	1	1	1.26	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	0	1	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	0.64			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	1	0.8			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Petrographic Analysis	Paid	1	1	1.67	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Petrographic Analysis	Paid	0	1	1.35			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	1	1.33			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	1	1	3.22	Don't know	Wall only	Gutters;Curtain or French Drain
	SOUTH WINDSOR	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	South Windsor	Petrographic Analysis	Paid	1	1	2.96	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Denied	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Petrographic Analysis	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Don't know		
	South Windsor	Petrographic Analysis	Paid	0	1	1.81			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	South Windsor	Petrographic Analysis	Paid	0	1	86			Waterproofing - Exterior;Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Curtain or French Drain
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Denied	0	0	0			
	South Windsor	Petrographic Analysis	Paid	1	1	38	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	1	0	0		Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Petrographic Analysis	Paid	1	1	18	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	South Windsor	Visual Inspection	Paid	0	0	0			
	South Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	South Windsor	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	South Windsor	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	South Windsor	Visual Inspection	Paid	0	1	12.5			Waterproofing - Exterior;Gutters;Finished Basement
	South Windsor	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Gutters - With Extension
<b>South Windssor Count</b>		1							
	South Windssor	Visual Inspection	Paid	0	0	0			Gutters
<b>Southington Count</b>		2							
	Southington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Southington	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Interior;Gutters;Footing Drains
<b>Stafford Count</b>		204							
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0		Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	13			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	20			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Petrographic Analysis	Paid	1	1	0.91	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	0.69			Gutters;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	1	0.58			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	visual	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	1.81	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	0.81	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Denied	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0		Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Denied	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Visual Inspection	On Hold	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	29	No visible signs		Waterproofing - Exterior
	Stafford	Petrographic Analysis	Paid	0	1	43			
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Petrographic Analysis	Paid	0	1	2.18			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	On Hold	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior
	Stafford	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		
	Stafford	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Petrographic Analysis	Paid	1	1	1.3	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Petrographic Analysis	Paid	0	1	1			Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			Gutters
	Stafford	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	No visible signs		Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Paid	0	0	0			
	Stafford	Visual Inspection	Denied	1	0	0	Don't know	Wall only	Gutters;Gutters - With Extension
	Stafford	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Stafford	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Stafford	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Stafford	Petrographic Analysis	Paid	0	1	1.74			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains
	Stafford	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Stafford	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Stafford	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	
	Stafford	Petrographic Analysis	Paid	1	1	52.5	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
<b>Stafford Springs Count</b>	1								

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Petrographic Analysis	Paid	1	1	2.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
<b>STAFFORD SPGS Count</b>	1								
	STAFFORD SPGS	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
<b>Stafford Springs Count</b>	50								
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	stafford springs	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	1	1	23	Don't know	Floor and walls both	Gutters - With Extension
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Stafford Springs	Visual Inspection	On Hold	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			
	Stafford Springs	Visual Inspection	Paid	0	0	0			Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			
	Stafford Springs	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Stafford Springs	Petrographic Analysis	Paid	0	1	1.8			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Stafford springs	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	
	Stafford Springs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Petrographic Analysis	Paid	0	0	0			
	Stafford Springs	Petrographic Analysis	Paid	1	1	0		Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Curtain or French Drain
	Stafford Springs	Petrographic Analysis	Paid	1	1	94	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	0	1	32			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Stafford Springs	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	STAFFORD Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Stafford Springs	Petrographic Analysis	Paid	1	1	1.05	Minor degradation	Wall only	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	STAFFORD SPRINGS	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Stafford springs	Visual Inspection	Paid	0	0	0			Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	stafford springs	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement
	Stafford Springs	Visual Inspection	Paid	1	0	0	No visible signs	Wall only	
	Stafford Springs	Visual Inspection	Paid	0	0	0			
	Stafford Springs	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Stafford Springs	Petrographic Analysis	Paid	1	1	3.16	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Stafford Springs	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
<b>Stafford Springs, Count</b>		1							
	Stafford Springs,	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
<b>Staffordville Count</b>		1							
	Staffordville	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
<b>Stamford Count</b>		1							
	Stamford	Visual Inspection	Pending DoH Approval	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Storrs Count</b>	4								
	Storrs	Visual Inspection	Paid	0	0	0			Gutters
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Storrs	Petrographic Analysis	Paid	1	1	3.03	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Storrs	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
<b>Storrs Mansfield Count</b>	7								
	Storrs Mansfield	Petrographic Analysis	Paid	1	1	2.2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.57			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			
	Storrs Mansfield	Petrographic Analysis	Paid	0	1	0.43			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Storrs Mansfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
<b>Storrs-Mansfield Count</b>	1								
	Storrs-Mansfield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
<b>Suffield Count</b>	67								
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Petrographic Analysis	Paid	1	1	58	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Petrographic Analysis	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Petrographic Analysis	Paid	1	1	70	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	On Hold	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Suffield	Visual Inspection	Paid	0	0	0			Gutters
	Suffield	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Suffield	Visual Inspection	Paid	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Suffield	Visual Inspection	Denied	0	0	0			
	Suffield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Suffield	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
<b>Thompson Count</b>	1								
	Thompson	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Tolland Count</b>	750								
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	1.43	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	3			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	2	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	1	1	1.21	No visible signs		Gutters
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	0			
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.89			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.61	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	51	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	0.81	Don't know	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	70	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Denied	1	1	46	Minor degradation	Wall only	Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Denied	0	1	16			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.09	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior
	Tolland	Petrographic Analysis	Paid	1	1	2.06	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0.09			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	1	1	26	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	29	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	34		Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Denied	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	45			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0.45	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	73	Minor degradation	Floor and walls both	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	50	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Denied	0	1	1.49			Waterproofing - Interior
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	2.88	Minor degradation	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.78			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	1.49			Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.81			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters
	Tolland	Petrographic Analysis	Paid	0	1	28			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Pending DoH Approval	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	1			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Don't know		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	71	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	10	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	TOLLAND	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.9			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	13	No visible signs	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0		Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	15			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	25			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)		Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	74	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	26	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	0	1	11			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	17			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	0	0			
	tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	7	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	30	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0			Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	8			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	16			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	1.28			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.5	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	7			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	12			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	39			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	1.02	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Denied	1	1	74	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.15	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0.5			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	4.13	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	3.58	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	2			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break
	Tolland	Petrographic Analysis	Paid	0	1	1.88			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	3.03	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Denied	1	1	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	1	1	1.75	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	1.03			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.38	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	2.13			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	1	0.69			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	1	0.75			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	1	1	2.51	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	1	1	3.54	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	On Hold	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Finished Basement
	Tolland	Visual Inspection	On Hold	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Approved - Pending Payment	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Approved - Pending Payment	1	0	0	Moderate to severe (significant repairs required)	Concrete floor only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual	Denied	1	1	84	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	1.19	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	1	1	84	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Gutters;Curtain or French Drain



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	No visible signs		Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Denied	1	1	0.42	Minor degradation	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	14			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Tolland	Petrographic Analysis	Paid	0	1	2.07			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Petrographic Analysis	Paid	0	1	0.67			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Tolland	Petrographic Analysis	Paid	0	0	0			Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Don't know	Wall only	
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	On Hold	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0			
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	
	Tolland	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Tolland	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Tolland	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Finished Basement;Footing Drains;Curtain or French Drain
	Tolland	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Tolland	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Tolland	Petrographic Analysis	Paid	1	1	3.08	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
<b>Union Count</b>	32								
	Union	Petrographic Analysis	Paid	0	1	0.86			Gutters
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters - With Extension;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters
	Union	Visual Inspection	Paid	0	0	0			Finished Basement
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Union	Petrographic Analysis	Paid	1	1	1.8	Minor degradation	Wall only	Finished Basement
	Union	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Union	Petrographic Analysis	Paid	0	1	0			Gutters;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Paid	0	1	0.95			Waterproofing - Exterior;Footing Drains
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Union	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Petrographic Analysis	Paid	1	1	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Petrographic Analysis	Denied	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters - With Extension;Footing Drains
	Union	Visual Inspection	Paid	0	0	0			
	Union	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Footing Drains
	Union	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Union	Petrographic Analysis	Paid	0	0	0			
	Union	Petrographic Analysis	Paid	1	1	40	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Union	Petrographic Analysis	Paid	0	1	74			Gutters;Finished Basement
	Union	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Union	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
<b>Vernon Count</b>	239								
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Pending	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Denied	0	0	0			
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	1.1			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	34			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	1.29	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	1	1	1.43	Severe (imminent threat of failure)	Floor and walls both	Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0		Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Denied	1	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	0.83			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	1	1	58	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	2.07	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	0.5	Minor degradation	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	3.01	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	1	1	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	vernon	Petrographic Analysis	Denied	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Petrographic Analysis	Paid	1	1	2	Moderate to severe (significant repairs required)	Wall only	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Don't know	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Denied	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Concrete floor only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	1	1	4.65	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	1.78			Gutters;Gutters - With Extension;Finished Basement



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0	Minor degradation		Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	21			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Petrographic Analysis	Paid	0	1	2.1			Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			
	Vernon	Petrographic Analysis	Paid	1	1	70	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Petrographic Analysis	Paid	0	1	1.18			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	1	2.03			Waterproofing - Exterior;Gutters
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Paid	0	1	1			Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Petrographic Analysis	Paid	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Denied	0	1	0			Gutters
	Vernon	Petrographic Analysis	Paid	1	1	36	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	2.8			Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Petrographic Analysis	Denied	1	1	2.8	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Petrographic Analysis	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Vernon	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Gutters;Gutters - With Extension
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Petrographic Analysis	Paid	0	1	0			Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Vernon	Visual Inspection	Paid	0	0	0			Gutters
	Vernon	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Vernon	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Curtain or French Drain
<b>Vernon Rockville Count</b>	2								
	Vernon Rockville	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Vernon Rockville	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Voluntown Count</b>		1							
	Voluntown	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Wallingford Count</b>		1							
	Wallingford	Visual Inspection	Pending DoH Approval	0	0	0			Gutters
<b>Waterbury Count</b>		1							
	Waterbury	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
<b>Waterford Count</b>		1							
	Waterford	Visual Inspection	On Hold	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Footing Drains
<b>West Granby Count</b>		1							
	West Granby	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
<b>West Hartford Count</b>		6							
	West Hartford	Visual Inspection	Denied	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters
	West Hartford	Visual Inspection	Denied	0	0	0			Gutters;Finished Basement
	West Hartford	Visual Inspection	Pending DoH Approval	0	0	0			Finished Basement
	West Hartford	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	West Hartford	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	West Hartford	Visual Inspection	On Hold	0	0	0			Gutters
<b>West Suffield Count</b>		1							
	West Suffield	Visual Inspection	Pending	0	0	0			Gutters
<b>WEST WILLINGTON Count</b>		1							
	WEST WILLINGTON	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
<b>Wethersfield Count</b>		5							
	Wethersfield	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Wethersfield	Visual Inspection	Pending	0	0	0			Gutters
	Wethersfield	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters
	Wethersfield	Visual Inspection	Denied	0	0	0			Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Willimantic Count</b>	1								
	Willimantic	Visual Inspection	Paid	0	0	0			
<b>Willington Count</b>	192								
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	0.24			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	0.82	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Denied	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0			Waterproofing - Exterior;Gutters;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Capillary Break;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	2		Wall only	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	1	1	1.45	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	4			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	0.85	Don't know	Floor and walls both	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Petrographic Analysis	Paid	1	1	54	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	0	1	1.74			Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	45	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters
	Willington	Petrographic Analysis	Paid	1	1	60	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension



All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Capillary Break;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	No visible signs		Waterproofing - Interior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Petrographic Analysis	Paid	0	1	2.42			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Petrographic Analysis	Paid	1	1	1.34	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Petrographic Analysis	Paid	0	1	0.6			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters - With Extension;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Denied	1	1	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	0	1	1.36			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Capillary Break;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	1.37	Minor to moderate (repair suggested/recommended)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	27	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension
	Willington	Petrographic Analysis	Paid	0	1	2			Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.054			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	1.46			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	1	1	1.15	Minor degradation	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Visual Inspection	Pending DoH Approval	1	0	0	No visible signs		Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)		Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	0	1	10			Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	
	Willington	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Wall only	Waterproofing - Exterior;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Footing Drains
	Willington	Petrographic Analysis	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Don't know	Floor and walls both	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Gutters;Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)		Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0			Waterproofing - Exterior
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Footing Drains
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Gutters;Gutters - With Extension;Finished Basement;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Curtain or French Drain
	Willington	Visual Inspection	Denied	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	1	1	28	Minor to moderate (repair suggested/recommended)	Wall only	Waterproofing - Exterior;Gutters;Finished Basement
	Willington	Petrographic Analysis	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains;Curtain or French Drain
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Paid	0	0	0			Gutters
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Interior;Gutters;Finished Basement
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement;Footing Drains
	Willington	Petrographic Analysis	Paid	0	0	0			
	Willington	Petrographic Analysis	Paid	1	1	2.34	Moderate to severe (significant repairs required)	Wall only	Waterproofing - Interior;Finished Basement;Curtain or French Drain
	Willington	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	1	0	0	Minor degradation	Wall only	Gutters;Curtain or French Drain
	Willington	Petrographic Analysis	Paid	0	1	0.53			Waterproofing - Exterior;Gutters
	Willington	Visual Inspection	Denied	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Gutters - With Extension

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Willington	Visual Inspection	Paid	0	0	0	No visible signs		Waterproofing - Exterior;Gutters;Gutters - With Extension;Footing Drains
	Willington	Petrographic Analysis	Paid	1	1	33	Minor degradation	Wall only	Waterproofing - Exterior;Finished Basement
	Willington	Visual Inspection	Denied	1	0	0	Severe (imminent threat of failure)	Wall only	Gutters
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Wall only	Gutters;Gutters - With Extension
	Willington	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Capillary Break;Finished Basement;Footing Drains
	Willington	Visual Inspection	Paid	0	0	0			
	Willington	Visual Inspection	Paid	1	0	0	Moderate to severe (significant repairs required)	Floor and walls both	Gutters;Finished Basement
<b>Windham Count</b>		8							
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Finished Basement
	Windham	Visual Inspection	On Hold	0	0	0			Gutters;Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			
	Windham	Visual Inspection	Paid	0	0	0			Finished Basement
	Windham	Visual Inspection	Paid	0	0	0			
	Windham	Petrographic Analysis	Paid	0	0	0			Gutters
	Windham	Visual Inspection	Paid	0	0	0			Gutters
<b>Windsor Count</b>		11							
	Windsor	Visual Inspection	Approved - Pending Payment	0	0	0			Gutters;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement;Footing Drains
	Windsor	Visual Inspection	Paid	0	0	0			
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			

All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
	Windsor	Visual Inspection	Paid	0	0	0			Waterproofing - Exterior;Waterproofing - Interior;Gutters;Gutters - With Extension;Finished Basement
	Windsor	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
<b>Winsted Count</b>	1								
	Winsted	Petrographic Analysis	Paid	0	0	0			Gutters
<b>Wolcott Count</b>	1								
	Wolcott	Visual Inspection	Paid	0	0	0			Gutters;Finished Basement
<b>Woodstock Count</b>	7								
	Woodstock	Visual Inspection	Paid	1	0	0	Severe (imminent threat of failure)	Floor and walls both	Gutters
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters
	Woodstock	Visual Inspection	Paid	1	0	0	Minor to moderate (repair suggested/recommended)	Floor and walls both	Waterproofing - Exterior;Footing Drains;Curtain or French Drain
	Woodstock	Petrographic Analysis	Paid	0	0	0			Gutters;Finished Basement
	Woodstock	Visual Inspection	Denied	0	0	0			Gutters
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters;Gutters - With Extension;Footing Drains
	Woodstock	Visual Inspection	Paid	0	0	0			Gutters - With Extension
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								









All Applications

	Home City	Type of Test Performed	Application Status	Was Damage Present?	Was Pyrrhotite Present	Pyrrhotite Percent	Damage Level	Damage Location	House Features
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								
<b>Count</b>	0								